Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B8805 Unit Location: Anona ES. Inspection Date: 8/17/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations 1 \boxtimes (Show Location on Back) Tie downs and Anchors 2 \boxtimes (Show Location on Back) Set Backs (Between Units 3 \boxtimes and from property) \boxtimes 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity \times 6 Roof Trusses \times Roof Covering (Note type 8 \boxtimes Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type 13 and Condition

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	half 200 - 10 12 12 12 12 12 12 12 12 12 12 12 12 12
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	\boxtimes			· ·
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		K-5	
1					Additional Comments/Observations
			된		
			7,		
7					

Date:

Manager Signature:

<u>8/30/21</u> Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B8935 Unit Location: Anona ES. Inspection Date: 8/17/21

Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations 1 (Show Location on Back) Tie downs and Anchors \times (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes 7 Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T111 Exterior Lighting (note if 10 \boxtimes any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Cor Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
				7	
^					

 $\frac{g-17-z}{\text{Date:}}$

Manager Signature:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B9119 Unit Location: Anona ES. Inspection Date: 8/17/21

Inspected By: John H. Borycens License Number: BN 7352 Condition Line **Inspection Criteria** # **Inspection Comments** Good Fair Poor New Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Aluminum Steps and Ramps \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 **Roof Trusses** \boxtimes 7 Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 \bowtie T 111 Exterior Lighting (note if 10 \boxtimes any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line #	Inspection Criteria	New	Condi		Poor	Inspection Comments
1.1	Ceilings/Tiles/Grid/	INEW	and the Real Property of the Parket	ган	POOI	
14	Wire Hangers (12ga)	Ш		Ш		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)					
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Co Yes	ndition No	_, -2	Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
	6				
1					

Manager Signature:

ate:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B9209 Unit Location: Anona ES. Inspection Date: 8/17/21

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** Good Fair Poor New Pier and foundations (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system		\boxtimes			,
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures					N/A

#	Inspection Criteria	Co	ndition		Inspection Comments
		Yes	No		
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		K-5	
	-	-			
			<i>3-17-</i>		Manager Signature: Date:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B9847 Unit Location: Anona ES. Inspection Date: 8/17/21

License Number: BN 7352 Inspected By: John H. Borycens **Inspection Criteria** Condition Line **Inspection Comments** # Good Fair Poor New Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 **Roof Trusses** \boxtimes 7 Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No	1.3		Inspection Comments		
29	Is unit in 100-year flood plain?	Is unit in 100-year flood plain?	Is unit in 100-year flood plain?		\boxtimes			
30	Technology Capable	\boxtimes						
31	Occupancy Certificate Posted in Unit	\boxtimes						
32	Local Agency Reports Posted	\boxtimes						
33	Does unit have any known Environmental factors? If yes, Explain.				-			
34	What grade level or usage is unit?	Other			K-5			
						Additional Comments/Observations		
					n in the second			
			0-17	-51		10/1. e/2-h.		

8-17-27 Date: Manager Signature:

7/30/2/ Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR0424 Unit Location: Anona ES. Inspection Date: 8/17/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum 5 \boxtimes Means of Egress Structural Integrity 6 \boxtimes Roof Trusses \boxtimes 7 Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 Metal Exterior Lighting (note if \boxtimes 10 any) Interior Walls and 11 \boxtimes Vinyl covered drywall Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)			300 day (300 day)		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Cutler hammer panel
20	Emergency Lighting		\boxtimes			Emergency light not working
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit	\boxtimes		-	
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
-		-			
	#20 work order for the	emergen	cy light #10	1041	
			0-17-	7/	alelli 8/2/24

Date:

Manager Signature:

Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR1317 Unit Location: Anona ES. Inspection Date: 8/17/21

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # Fair New Good Poor Pier and foundations (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units 3 \boxtimes and from property) \boxtimes 4 Steps and Ramps Concrete walkways \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes 7 Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 concrete board Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \times 11 Vinyl covered drywall Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	ition	Egi-vii	Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)					
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

#	Inspection Criteria	Co	ndition		Inspection Comments		
	e, 197 begins.	Yes	No	160	그리는 이 그들은 전혀 그는 그 반면을 가져왔다. 살아왔었다. 하는 그 그는 사실하다 모르다.		
29	Is unit in 100-year flood plain?						
30	Technology Capable						
31	Occupancy Certificate Posted in Unit	\boxtimes					
32	Local Agency Reports Posted	\boxtimes					
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes				
34	What grade level or usage is unit?	Other		K-5			
	1						

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR1318 Unit Location: Anona ES. Inspection Date: 8/17/21

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units X 3 and from property) \boxtimes 4 Concrete walkways Steps and Ramps \boxtimes Means of Egress Structural Integrity X 6 **Roof Trusses** X Roof Covering (Note type X 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding X 9 concrete board Exterior Lighting (note if X 10 any) Interior Walls and X 11 Vinyl covered drywall Covering Doors/Windows/ X 12 Hardware Floors/Carpet/Tile Type 13 X and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No		Inspection Comments	
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other	K-5		
			Addi	tional Comments/Observations	
					*
				,	
7	1				2

8-17-4 Date:

Manager Signature:

8/30/2/

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR1319 Unit Location: Anona ES. Inspection Date: 8/17/21

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes 1 (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units 3 X and from property) \boxtimes 4 Steps and Ramps Concrete walkways \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 concrete board Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Condit Yes N			Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
	or Signature:	30-	-17-2	7	26/A- 3/30/A

Date:

Manager Signature:

Date:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR1320

Unit Location: Anona ES.

Inspection Date: 8/17/21

O	Talliber: Bicrozo					Offic Location. Anona Lo.
Inspe	ected By: John H. I	3oryc	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		New	Good	Fair	Poor	inspection Comments
1	Pier and foundations (Show Location on Back)		\boxtimes			
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)		\boxtimes			
4	Steps and Ramps		\boxtimes			Concrete walkways
5	Means of Egress		\boxtimes			
6	Structural Integrity		\boxtimes			
7	Roof Trusses		\boxtimes			
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Rubber
9	Exterior Walls/Siding		\boxtimes			concrete board
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering		\boxtimes			Vinyl covered drywall
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other	Other		
					Additional Comments/Observations
		98			
1					

8 -/7-2/ Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR1321 Unit Location: Anona ES. Inspection Date: 8/17/21

License Number: BN 7352 Inspected By: John H. Borycens **Inspection Criteria** Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units X 3 and from property) \boxtimes Concrete walkways 4 Steps and Ramps \boxtimes 5 Means of Egress Structural Integrity X6 Roof Trusses X Roof Covering (Note type X 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding X 9 concrete board Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ \times 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No	1.1.1.21	Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit	\boxtimes			
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.				5
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
7	1				
1					

Date:

Manager Signature:

)ate:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: BR1322 Unit Location: Anona ES. Inspection Date: 8/17/21

Inspected By: John H. Borycens License Number: BN 7352 Line **Inspection Criteria** Condition # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units 3 \boxtimes and from property) \boxtimes 4 Steps and Ramps Concrete walkways \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 **Roof Trusses** X Roof Covering (Note type X Rubber Shingles, Veral, etc.) Exterior Walls/Siding \times 9 concrete board Exterior Lighting (note if 10 X any) Interior Walls and X 11 Vinyl covered drywall Covering Doors/Windows/ 12 \times Hardware Floors/Carpet/Tile Type 13 X and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom
						×

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes	e e	
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit	\boxtimes			
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
1	1				

8-17-Z/

Manager Signature:

8/30/2/ Pate:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: ER8959

Unit Location: Anona ES.

Inspection Date: 8/17/21

Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion	14.9.50	
		New	Good	Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)		\boxtimes			
4	Steps and Ramps		\boxtimes			Aluminum
5	Means of Egress		\boxtimes			
6	Structural Integrity		\boxtimes			
7	Roof Trusses		\boxtimes			
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Modified
9	Exterior Walls/Siding		\boxtimes			T111
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering					Paneling
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			Emergency light not working South end
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
	Work order for emerger	ncv light:	# 101052		
1			2 .5	<i>a</i> ;	10h: eb.

Inspector Signature:

8-17-21 Date: Manager Signature:

)ate:

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: LR0645 Unit Location: Anona ES. Inspection Date: 8/17/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) X 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \times 9 Metal Exterior Lighting (note if \boxtimes 10 any) Interior Walls and 11 \boxtimes Vinyl covered drywall Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
1					

Inspector signature:

8-17-21 Data

Manager Signature:

8/30/2/ Date:

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: LR0657 Unit Location: Anona ES. Inspection Date: 8/17/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type X 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 Metal Exterior Lighting (note if \boxtimes 10 any) Interior Walls and 11 X Vinyl covered drywall Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes and Condition

Line	Inspection Criteria	-	Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	그렇게 되었다.
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			Emergency light not working
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures					This unit has a restroom

#	Inspection Criteria	CO	ndition		Inspection Comments
	Contraction of	Yes	No		그는 그렇게 하는 이번도 그는 일반이는 그래요요 그는 그는 이 가는 것이 그는 것이다.
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit	\boxtimes			
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		K-5	
	#20 work order for the 6	emergen	cy light #10	1038	
	#20 work order for the e	emergen	cy light #10	1038	
	#20 work order for the e	emergen	cy light #10	1038	
	#20 work order for the e	emergen	cy light #10	1038	

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: LR0829 Unit Location: Anona ES. Inspection Date: 8/17/21

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria	Kristia Kristia	Condit	tion		Inspection Comments
F-144		New	Good	Fair	Poor	
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress					
6	Structural Integrity					
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber
9	Exterior Walls/Siding					Metal
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering					Vinyl covered drywall
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition					

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes		
16	Weatherproofing (List Deficiencies)		\boxtimes		
17	HVAC				Bard
18	Electrical Receptacles		\boxtimes		
19	Distribution Panel (labeled Correctly)				Cutler hammer panel
20	Emergency Lighting				
21	Interior Light Fixtures (tied to structure)		\boxtimes		
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes		
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes		
24	Heat Detector/Smoke Detector in Classroom		\boxtimes		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes		
26	Intercom system				
27	Fire Extinguisher (Tagged and Current)				
28	Plumbing/Fixtures				This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit	\boxtimes			
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		К	Z-5
					Additional Comments/Observations
					<u> </u>
_		-			
			2-17-7	7-1	alle separa

Inspector Signature:

<u>8-17-レ/</u> Date: Manager Signature:

8/30/2/ Date:

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: LR0830 Unit Location: Anona ES. Inspection Date: 8/17/21

License Number: BN 7352 Inspected By: John H. Borycens **Inspection Criteria** Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations \times (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units X 3 and from property) X 4 Aluminum Steps and Ramps X 5 Means of Egress Structural Integrity X 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 Metal Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Cutler Hammer panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			Oec
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Co Yes	ndition No	35 50	Inspection Comments	
29	Is unit in 100-year flood plain?					
30	Technology Capable					
31	Occupancy Certificate Posted in Unit	\boxtimes				
32	Local Agency Reports Posted					
33	Does unit have any known Environmental factors? If yes, Explain.					
34	What grade level or usage is unit?	Other		K-5		
					Additional Comments/Observations	
7	1					

Inspector Signature:

 $\frac{\mathcal{B}-17-2/}{\text{Date:}}$

Manager Signature:

8/30/2/