Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B9980 Unit Location: Bardmoor ES. Inspection Date: 8/19/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** Good Fair Poor New Pier and foundations \boxtimes 1 (Show Location on Back) Tie downs and Anchors X 2 (Show Location on Back) Set Backs (Between Units 3 X and from property) X 4 Steps and Ramps Aluminum \times 5 Means of Egress Structural Integrity X 6 Roof Trusses 7 X Roof Covering (Note type X8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if X 10 any) Interior Walls and 11 X Paneling Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type X 13 and Condition

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes		
16	Weatherproofing (List Deficiencies)		\boxtimes		
17	HVAC		\boxtimes		Bard
18	Electrical Receptacles		\boxtimes		
19	Distribution Panel (labeled Correctly)				Square D panel
20	Emergency Lighting		\boxtimes		
21	Interior Light Fixtures (tied to structure)		\boxtimes		
22	Fire Alarm (Strobes, Horn, Pull Stations)				
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes		
24	Heat Detector/Smoke Detector in Classroom		\boxtimes		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes		in attic
26	Intercom system		\boxtimes		
27	Fire Extinguisher (Tagged and Current)	\boxtimes			
28	Plumbing/Fixtures				N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other	Other		
					Additional Comments/Observations
\searrow			Q-19-Z1	/	2/2/2/2

Inspector Signature:

Date:

Manager Signature:

Date: