Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Inspection Date: 8/24/21 Unit Number: B9501 **Unit Location:** Bay Point ES. Inspected By: John H. Borycens License Number: BN 7352 Condition Inspection Criteria Line **Inspection Comments** # New Good Fair Poor Pier and foundations X 1 (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units 3 X and from property) X 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses X Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\times$ 10 any) Interior Walls and  $\boxtimes$ Paneling Covering Doors/Windows/  $\boxtimes$ Hardware Floors/Carpet/Tile Type X 13 and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#	and Condition	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A
	Edit Statement - France					

Line #	Inspection Criteria	Condition Yes No		Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	K-5	
				Additional Comments/Observations
			1	
			<u> </u>	

B-14-4

Manager Signature:

8/30/21

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Inspection Date: 8/24/21 **Unit Location:** Bay Point ES. **Unit Number: BR8939** License Number: BN 7352 Inspected By: John H. Borycens Condition Inspection Criteria Line **Inspection Comments** # New Good Fair Poor Pier and foundations (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ Aluminum 4 Steps and Ramps  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ 7 Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if X 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	ine Inspection Criteria Condition			Inspection Comments		
#	and Condition	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom
	200 H 2					

Line #	Inspection Criteria	Condition Yes No	Inspection Comments				
29	Is unit in 100-year flood plain?						
30	Technology Capable						
31	Occupancy Certificate Posted in Unit						
32	Local Agency Reports Posted						
33	Does unit have any known Environmental factors? If yes, Explain.						
34	34/1 / 1 1 1		K-5				
			Additional Comments/Observations				
		· · · · · · · · · · · · · · · · · · ·					

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

**Unit Number: BR 9406 Unit Location:** Bay Point ES. Inspection Date: 8/24/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** Fair New Good Poor Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses X Roof Covering (Note type X 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and  $\times$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Cellings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC					Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments				
29	Is unit in 100-year flood plain?								
30	Technology Capable								
31	Occupancy Certificate Posted in Unit				V 70				
32	Local Agency Reports Posted	$\boxtimes$							
33	Does unit have any known Environmental factors? If yes, Explain.				4				
34	What grade level or usage is unit?	Other		K-5					
					Additional Comments/Observations				
				*					
	-								
7									

8-24-27

Manager Signature:

8/30/2/ Date:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Location: Bay Point ES. Inspection Date: 8/24/21 **Unit Number: BR 9417** Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations  $\times$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units 3 X and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\times$ 10 any) Interior Walls and 11 X Paneling Covering

Doors/Windows/

and Condition

Floors/Carpet/Tile Type

Hardware

12

13

 $\boxtimes$ 

 $\boxtimes$ 

Line #	Inspection Criteria	Condition			Inspection Comments	
#	LEDGE WITCHES ASS	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom
	And the second s					

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$		
30	Technology Capable	$\boxtimes$			
31	Occupancy Certificate Posted in Unit	$\boxtimes$			
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$		
34	What grade level or usage is unit?	Other		K-5	
Ť					Additional Comments/Observations
				F	
			<u> </u>		
	1				
					4
1	1				

8-24-71 Date:

Manager Signature:

**8/30/2/** Date: