Pinellas County Schools

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: BO 0567 Unit Location: Bay Side HS.. Inspection Date: 10/20/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations (Show Location on Back) Tie downs and Anchors X (Show Location on Back) Set Backs (Between Units X 3 and from property) \boxtimes Steps and Ramps 4 Aluminum \boxtimes 5 Means of Egress Structural Integrity 6 \boxtimes Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 Metal Exterior Lighting (note if \boxtimes 10 any) Interior Walls and 11 \boxtimes Plaster over drywall Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)				
16	Weatherproofing (List Deficiencies)				
17	HVAC				Bard
18	Electrical Receptacles				
19	Distribution Panel (labeled Correctly)				GE panel
20	Emergency Lighting				Emergency light is not working
21	Interior Light Fixtures (tied to structure)				
22	Fire Alarm (Strobes, Horn, Pull Stations)				
23	Heat Detector/Smoke Detector in Storage Spaces				
24	Heat Detector/Smoke Detector in Classroom				
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)				in attic
26	Intercom system				
27	Fire Extinguisher (Tagged and Current)				
28	Plumbing/Fixtures				N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	
			Additional Comments/Observations
	#20 work order for the e	emergency light #109791	
1			2

Manager Signature:

<u>19/28/21</u> Date:

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Location: Bay Side HS. **Unit Number:** BO 0568 Inspection Date: 10/20/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** Fair New Good Poor Pier and foundations (Show Location on Back) Tie downs and Anchors X (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity 6 \boxtimes Roof Trusses \boxtimes Roof Covering (Note type \boxtimes Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 Aluminum Exterior Lighting (note if X 10 any) Interior Walls and X11 Paneling Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line #	Inspection Criteria		Condition	ition		Inspection Comments	
74		New	B005	rair	1001		
4	Ceilings/Tiles/Grid/ Wire Hangers (12ga)						
15	Visual Aids (Chalk/Marker Boards and Tack Boards)						
16	Weatherproofing (List Deficiencies)						
17	HVAC					Bard	
18	Electrical Receptacles						
19	Distribution Panel (labeled Correctly)					GE panel	
20	Emergency Lighting						
21	Interior Light Fixtures (tied to structure)		\boxtimes				
22	Fire Alarm (Strobes, Horn, Pull Stations)						
23	Heat Detector/Smoke Detector in Storage Spaces						
24	Heat Detector/Smoke Detector in Classroom		\boxtimes				
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic	
26	Intercom system		\boxtimes				
27	Fire Extinguisher (Tagged and Current)	\boxtimes					
28	Plumbing/Fixtures					N/A	

Line #	Inspection Criteria	Cor Yes	ndition No	Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit	\boxtimes		
32	Local Agency Reports Posted	\boxtimes		
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes	
34	What grade level or usage is unit?	Other		
			nganasa sa	Additional Comments/Observations
			86	
			(0.00.7)	alle.

70-20-2 | Date: Manager Signature:

/5/25/21 Date:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BO 0569 Unit Location: Bay Side HS. Inspection Date: 10/20/21

Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria	New	Condi Good	tion Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)		\boxtimes			
4	Steps and Ramps		\boxtimes			Aluminum
5	Means of Egress		\boxtimes			
6	Structural Integrity		\boxtimes			
7	Roof Trusses		\boxtimes			
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified
9	Exterior Walls/Siding					Aluminum
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering		\boxtimes			Paneling
12	Doors/Windows/ Hardware		\boxtimes			
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		\boxtimes			GE panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Coi	ndition	Inspection Comments
#		Yes	No	
29	Is unit in 100-year flood plain?		\boxtimes	
30	Technology Capable			
31	Occupancy Certificate Posted in Unit	\boxtimes		
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
monthly 500 cm				
7	-			

<u>/0-20-2/</u> Date:

Manager Signature:

10/26/2/ ate:

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 8408 Unit Location: Bay Side HS.. **Inspection Date:** 10/20/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** Good New Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors X (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity \boxtimes 6 **Roof Trusses** \boxtimes Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T111 Exterior Lighting (note if X 10 any) Interior Walls and X 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			GE panel
20	Emergency Lighting					Emergency light is not working
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No	Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable	\boxtimes		
31	Occupancy Certificate Posted in Unit	\boxtimes		
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
	Work order number for	the eme	rgency light # 1	09793
8				

10-20-21 Date: Manager Signature:

P/28/21 Date:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 9326

Unit Location: Bay Side HS.

Inspection Date: 10/20/21

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
		New	Good	Fair	Poor	
1	Pier and foundations (Show Location on Back)		\boxtimes			
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress					
6	Structural Integrity					
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified
9	Exterior Walls/Siding					T111
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering		\boxtimes			Kem Lite
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Condi			Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	And the last of th	ndition	Inspection Comments
		Yes	No	
29	Is unit in 100-year flood plain?		\boxtimes	
30	Technology Capable			
31	Occupancy Certificate Posted in Unit	\boxtimes		
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes	
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
\setminus				_

10 - 20 - 2/ Date:

Manager Signature:

10/28/2/ ate:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BRN 9306 Unit Location: Bay Side HS. **Inspection Date:** 10/20/21

Insp	ected By: John H. I	Зогус	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
		New	Good	Fair	Poor	
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress		\boxtimes			
6	Structural Integrity					
7	Roof Trusses		\boxtimes			
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Modified
9	Exterior Walls/Siding		\boxtimes			T111
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering		\boxtimes			Kem Lite
12	Doors/Windows/ Hardware		\boxtimes			
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line	Inspection Criteria	Condition				Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	
			Additional Comments/Observations
			*

<u>/ク - 20 - 2/</u> Date:

Manager Signature: