Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR0930 Unit Location: Bear Creek ES. Inspection Date: 8/26/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units 3 \boxtimes and from property) \boxtimes 4 Steps and Ramps Concrete \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding 9 X Hardy board Exterior Lighting (note if \boxtimes 10 any) Interior Walls and 11 \boxtimes Vinyl covered drywall Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line Inspection Criteria			Cond	ition		Inspection Comments
#	And Contribution	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria		ndition		Inspection Comments
		Yes	No		
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit	\boxtimes			
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
-					
					*
		,	2-7/-3	z)	

8-26-21

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR0931 Unit Location: Bear Creek ES. Inspection Date: 8/26/21 Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations \boxtimes 1 (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Concrete \boxtimes 5 Means of Egress Structural Integrity X 6 **Roof Trusses** \boxtimes Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 Hardy board Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line #	Inspection Criteria	Nous	Condi		Door	Inspection Comments
	FloredCatherine Type	New	Good	rair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	K-5
			Additional Comments/Observations
1	1	-	1

<u>8 -26 -2 /</u> Date:

Manager Signature:

9/1/2/ Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR0932 Unit Location: Bear Creek ES. Inspection Date: 8/26/21 License Number: BN 7352 Inspected By: John H. Borycens **Inspection Criteria** Condition Line **Inspection Comments** # Fair Poor New Good Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Concrete \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 Hardy board Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ \boxtimes 12 Hardware

Floors/Carpet/Tile Type

and Condition

13

 \boxtimes

Line	Inspection Criteria		Condi	tion		Inspection Comments
#	Title constitutes and a title	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
					6
				40	
		2	3-26-	2/	16/lb- 9/./21
nspect	or Signature:	D	3 <i>-26</i> ate:		Manager Signature: Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR0933 Unit Location: Bear Creek ES. Inspection Date: 8/26/21 Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Condition Line # **Inspection Comments** Fair New Good Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Concrete \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 Hardy board Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line Inspection Criteria			Condi	tion		Inspection Comments
#	Place of Caraman Place From and Caraman	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	П	\boxtimes			
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line	Inspection Criteria	Col	ndition		Inspection Comments
#		Yes	No		
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
1	1				

8-26-2/ Date:

Manager Signature:

9/1/21

)até:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: BR0934 Unit Location: Bear Creek ES. Inspection Date: 8/26/21

Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Concrete \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 Hardy board Exterior Lighting (note if 10 \bowtie any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	tion		Inspection Comments
#	AUG CONTROL	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No		Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	K-5	
				Additional Comments/Observations

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Inspection Date: 8/26/21 BR0935 Unit Location: Bear Creek ES. **Unit Number:** Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations 1 (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Concrete \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 Hardy board Exterior Lighting (note if X 10 any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	tion	Francis (Inspection Comments
#	and Couplies as a par-	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			Emergency light is not working
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria		ndition		Inspection Comments		
		Yes	No	reaction of parts.			
29	Is unit in 100-year flood plain?		\boxtimes				
30	Technology Capable						
31	Occupancy Certificate Posted in Unit						
32	Local Agency Reports Posted						
33	Does unit have any known Environmental factors? If yes, Explain.						
34	What grade level or usage is unit?	Other		K-5			
			an talas angungsala ng ma		Additional Comments/Observations		
	Work order number for	the eme	rgency light	# 102809			
1							

8-26-2/ Date:

Manager Signature:

9/1/21

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Inspection Date: 8/26/21 **BR0936** Unit Location: Bear Creek ES. **Unit Number:** License Number: BN 7352 Inspected By: John H. Borycens **Inspection Criteria** Condition Line **Inspection Comments** # Good Fair Poor New Pier and foundations (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes and from property) \boxtimes 4 Steps and Ramps Concrete \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 **Roof Trusses** \boxtimes Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 Hardy board Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering \boxtimes Doors/Windows/ 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	tion		Inspection Comments
#	SHO COMPLETO	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Condition Yes No		Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable		-	
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	K-5	
			Addition	onal Comments/Observations
			k	
		0-76-5	, /	2/2/21

8 - 46 -Date: Manager Signature:

9/1/2/ Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR0937 Unit Location: Bear Creek ES. Inspection Date: 8/26/21 Inspected By: John H. Borycens BN 7352 License Number: Line Inspection Criteria Condition # **Inspection Comments** New Good Fair Poor Pier and foundations (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Concrete \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 Hardy board Exterior Lighting (note if \boxtimes 10 any) Interior Walls and 11 \boxtimes Vinyl covered drywall Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes		
16	Weatherproofing (List Deficiencies)		\boxtimes		
17	HVAC		\boxtimes		Bard
18	Electrical Receptacles		\boxtimes		
19	Distribution Panel (labeled Correctly)		\boxtimes		Square D panel
20	Emergency Lighting		\boxtimes		
21	Interior Light Fixtures (tied to structure)		\boxtimes		
22	Fire Alarm (Strobes, Horn, Pull Stations)				
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes		
24	Heat Detector/Smoke Detector in Classroom				
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)				in attic
26	Intercom system		\boxtimes		
27	Fire Extinguisher (Tagged and Current)				
28	Plumbing/Fixtures		\boxtimes		This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	K-5
			Additional Comments/Observations
	*		8
		8-26-21	Melli 9/1/21

Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR0938 Unit Location: Bear Creek ES. Inspection Date: 8/26/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition **Inspection Comments** Good New Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors \times (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) X 4 Steps and Ramps Concrete X 5 Means of Egress Structural Integrity X 6 Roof Trusses X Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding X 9 Hardy board Exterior Lighting (note if X 10 any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#	SARE CONGESTS AND	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line	Inspection Criteria	Conditi		Inspection Comments
#		Yes No		
29	Is unit in 100-year flood plain?			*
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	K-5	
				Additional Comments/Observations
			S61500 37 H91, S6 S6	
		1		
2				
		8-	26-21	16/16- 9/1/21

Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR0939 Unit Location: Bear Creek ES. Inspection Date: 8/26/21 Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** New Good Fair Poor Pier and foundations

1	(Show Location on Back)			
2	Tie downs and Anchors (Show Location on Back)	\boxtimes		
3	Set Backs (Between Units and from property)			
4	Steps and Ramps			Concrete
5	Means of Egress	\boxtimes		
6	Structural Integrity	\boxtimes		
7	Roof Trusses	\boxtimes		
8	Roof Covering (Note type Shingles, Veral, etc.)			Rubber
9	Exterior Walls/Siding			Hardy board
10	Exterior Lighting (note if any)			
11	Interior Walls and Covering	\boxtimes		Vinyl covered drywall
12	Doors/Windows/ Hardware			
13	Floors/Carpet/Tile Type and Condition	\boxtimes		

Line	Inspection Criteria	Red H	Cond	ition		Inspection Comments
#	and continue in the	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures					This unit has a restroom

Inspection Criteria	Condition			Inspection Comments
	Yes	No		
Is unit in 100-year flood plain?		\boxtimes		
Technology Capable				
Occupancy Certificate Posted in Unit	\boxtimes			
Local Agency Reports Posted				
Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
What grade level or usage is unit?	Other		K-5	
1				Additional Comments/Observations
\bigcap		8-76-	, /	10/1-
tor Signature:			—	Manager Signature: Date:
	Is unit in 100-year flood plain? Technology Capable Occupancy Certificate Posted in Unit Local Agency Reports Posted Does unit have any known Environmental factors? If yes, Explain. What grade level or	Is unit in 100-year flood plain? Technology Capable Occupancy Certificate Posted in Unit Local Agency Reports Posted Does unit have any known Environmental factors? If yes, Explain. What grade level or usage is unit? Other	Is unit in 100-year flood plain? Technology Capable Occupancy Certificate Posted in Unit Local Agency Reports Posted Does unit have any known Environmental factors? If yes, Explain. What grade level or usage is unit? Other	Is unit in 100-year flood plain? Technology Capable Occupancy Certificate Posted in Unit Local Agency Reports Posted Does unit have any known Environmental factors? If yes, Explain. What grade level or usage is unit? Other K-5

Relocatable Classroom Inspection Certificate

(Yearly Inspection Report) Inspection Date: 8/26/21 **Unit Number:** BR0940 Unit Location: Bear Creek ES. License Number: BN 7352 Inspected By: John H. Borycens **Inspection Criteria** Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Concrete \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 **Roof Trusses** X Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding X 9 Hardy board Exterior Lighting (note if X 10 any) Interior Walls and X 11 Vinyl covered drywall Covering Doors/Windows/ X 12 Hardware Floors/Carpet/Tile Type

 \boxtimes

13

and Condition

Line	Inspection Criteria	1000	Cond	ition		Inspection Comments
#	nim condition	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)		\boxtimes			
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments		
29	Is unit in 100-year flood plain?		\boxtimes				
30	Technology Capable	\boxtimes					
31	Occupancy Certificate Posted in Unit	\boxtimes					
32	Local Agency Reports Posted	\boxtimes					
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes				
34	What grade level or usage is unit?	Other		K-5			
				A	dditional Comments/Observations		
					8		
<u></u>							

8-26-2/ Date:

Manager Signature:

9/1/2/