		Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)										
Unit	Number: BR 0414				in a transformer Statistics	Unit Location: Be	elcher El.		Inspection Date:	8/31/21		
Insp	ected By: John H. E	Boryce	ens			License Number:	BN 7352					
Line #	Inspection Criteria	New	Condi		Poor			Inspection Comment				
1	Pier and foundations (Show Location on Back)											
2	Tie downs and Anchors (Show Location on Back)											
3	Set Backs (Between Units and from property)											
4	Steps and Ramps		$\boxtimes$			Aluminum						
5	Means of Egress											
6	Structural Integrity											
7	Roof Trusses											
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber						
9	Exterior Walls/Siding					Metal						
10	Exterior Lighting (note if any)											
11	Interior Walls and Covering					Vinyl covered drywall						
12	Doors/Windows/ Hardware											
13	Floors/Carpet/Tile Type and Condition											

Line Inspection Criteri		Condition				Inspection Comments
#	SALE CONTRACTOR	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\square$			
16	Weatherproofing (List Deficiencies)		$\square$			
17	HVAC		$\square$			Bard
18	Electrical Receptacles		$\square$			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)		$\square$			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		$\square$			
24	Heat Detector/Smoke Detector in Classroom		$\square$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	The second s	dition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other	6	K-5	
					Additional Comments/Observations
	т. Т.				
					~
$\int$	$\langle \rangle$	2	3-3/-2	1	11/1- 9/2/21
spect	or Signature:	Da	te:	<u> </u>	Manager Signature: Date:

					Pinellas County Sc Relocatable Classroom Inspection (Yearly Inspection Report	on Certificate	
Unit	Number: BR 0579				Unit Location: Belcher El.	Inspection Date: 8/3	31/21
Insp	ected By: John H. E	Boryce	ens		License Number: BN 7352		
Line #	Inspection Criteria	Now	Condit Good	Poor		Inspection Comments	
1	Pier and foundations (Show Location on Back)						
2	Tie downs and Anchors (Show Location on Back)						
3	Set Backs (Between Units and from property)		$\square$				
4	Steps and Ramps				Aluminum		
5	Means of Egress						
6	Structural Integrity				. w. A. A		
7	Roof Trusses						
8	Roof Covering (Note type Shingles, Veral, etc.)				Rubber		
9	Exterior Walls/Siding				Metal		
10	Exterior Lighting (note if any)						
11	Interior Walls and Covering				Vinyl covered drywall		
12	Doors/Windows/ Hardware						
13	Floors/Carpet/Tile Type and Condition						

Line	Inspection Criteria	n en fi	Cond	ition	11-	Inspection Comments
#	and Captoring and Inc.	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\square$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\square$			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		$\square$			
24	Heat Detector/Smoke Detector in Classroom		$\square$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		$\square$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures		$\square$			This unit has a restroom

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Comments								
29	ls unit in 100-year flood plain?												
30	Technology Capable	$\square$											
31	Occupancy Certificate Posted in Unit	$\square$											
32	Local Agency Reports Posted	$\boxtimes$											
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$										
34	What grade level or usage is unit?	Other	II	K-5	* *								
		Additional Comments/Observations											
	2												
	Yes No   Is unit in 100-year flood Image: Second												
nspect	or Signature:	 Di	<u>3-3/-2</u> ate:		Manager Signature: Date:								

					Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)		
Unit	Number: BR 0580				Unit Location: Belcher El.	Inspection Date:	8/31/21
Insp	ected By: John H. I	Boryce	ens		License Number: BN 7352		
Line #	Inspection Criteria	New	Condi	Poor	Inspection Commen	ts	
1	Pier and foundations (Show Location on Back)		$\boxtimes$				
2	Tie downs and Anchors (Show Location on Back)		$\square$				
3	Set Backs (Between Units and from property)						
4	Steps and Ramps				Aluminum		
5	Means of Egress						
6	Structural Integrity					1	
7	Roof Trusses						
8	Roof Covering (Note type Shingles, Veral, etc.)				Rubber		
9	Exterior Walls/Siding				Metal		
10	Exterior Lighting (note if any)						
11	Interior Walls and Covering				Vinyl covered drywall		
12	Doors/Windows/ Hardware						
13	Floors/Carpet/Tile Type and Condition						

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\square$		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\square$		
16	Weatherproofing (List Deficiencies)		$\square$		
17	HVAC		$\square$		Bard
18	Electrical Receptacles		$\square$		
19	Distribution Panel (labeled Correctly)		$\square$		Square D panel
20	Emergency Lighting		$\square$		
21	Interior Light Fixtures (tied to structure)		$\square$		
22	Fire Alarm (Strobes, Horn, Pull Stations)				
23	Heat Detector/Smoke Detector in Storage Spaces		$\square$		
24	Heat Detector/Smoke Detector in Classroom				
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)				in attic
26	Intercom system				
27	Fire Extinguisher (Tagged and Current)				
28	Plumbing/Fixtures				This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	K-5
			Additional Comments/Observations
			4
		÷	
	£		
$\int$		8-3/-21	20hi 09/2/21

Inspector Signature:

Date:

Manager Signature:

Date:

					Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)
Unit	Number: C 9105				Unit Location: Belcher El. Inspection Date: 8/31/21
Insp	ected By: John H. I	Boryce	ens		License Number: BN 7352
Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)				
2	Tie downs and Anchors (Show Location on Back)				
3	Set Backs (Between Units and from property)				
4	Steps and Ramps				Aluminum
5	Means of Egress				
6	Structural Integrity				
7	Roof Trusses				
8	Roof Covering (Note type Shingles, Veral, etc.)				Modified
9	Exterior Walls/Siding				T 111
10	Exterior Lighting (note if any)				
11	Interior Walls and Covering				Paneling
12	Doors/Windows/ Hardware				
13	Floors/Carpet/Tile Type and Condition				

Line #	Inspection Criteria		Condi			Inspection Comments
#	Shingathin Ge 1988	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\square$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\square$			
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Co Yes	ndition No	Inspection Comments
29	Is unit in 100-year flood plain?		$\square$	* · · · · · · · · · · · · · · · · · · ·
30	Technology Capable	$\square$		
31	Occupancy Certificate Posted in Unit	$\square$		
32	Local Agency Reports Posted	$\square$		
33	Does unit have any known Environmental factors? If yes, Explain.		$\square$	
34	What grade level or usage is unit?	Other		
		S and		Additional Comments/Observations
		<u>TOMETOMERO A HAQ. 7</u>		
			л.	
	2			
			<i>8-3/-2/</i> Date:	Manager Signature: <u>9/2/2/</u> Date:
nspec	tor Signature:	L	ale.	ivialiager Signature. Date.