					Pinellas Co Relocatable Classro (Yearly In		on Certificate		
Unit I	Number: B 9850				Unit Location: B	elleair ES .		Inspection Date:	8/31/21
Inspe	ected By: John H. E	Boryce	ens		License Number:	BN 7352			12000
Line #	Inspection Criteria	New	Condit Good	Poor			Inspection Comment	5	
1	Pier and foundations (Show Location on Back)		\square						
2	Tie downs and Anchors (Show Location on Back)								
3	Set Backs (Between Units and from property)								
4	Steps and Ramps				Aluminum				
5	Means of Egress								
6	Structural Integrity								
7	Roof Trusses					¥.			
8	Roof Covering (Note type Shingles, Veral, etc.)				Metal				
9	Exterior Walls/Siding				Metal				
10	Exterior Lighting (note if any)								
11	Interior Walls and Covering				Paneling				
12	Doors/Windows/ Hardware								
13	Floors/Carpet/Tile Type and Condition								

Line	Inspection Criteria	tion Criteria Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\square			
16	Weatherproofing (List Deficiencies)		\square			
17	HVAC		\square			Bard
18	Electrical Receptacles		\square			2
19	Distribution Panel (labeled Correctly)		\square			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)		\square			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		\square			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\square			in attic
26	Intercom system		\square			
27	Fire Extinguisher (Tagged and Current)	\square				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Comments
29	ls unit in 100-year flood plain?		\square		
30	Technology Capable	\square			
31	Occupancy Certificate Posted in Unit	\square			
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.		\square		
34	What grade level or usage is unit?	Other	1	K-5	
					Additional Comments/Observations
			*		
\sim	\square				1
X	tor Signature:		<u>8-3/-2</u> Date:		26/1/min 9/30/21

					Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)	
Unit	Number: B R1323				Unit Location: Belleair ES .	Inspection Date: 8/31/21
Insp	ected By: John H. I	Boryc	ens		License Number: BN 7352	
Line #	Inspection Criteria	New	Condi Good	Poor	Inspection	n Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps				Concrete	
5	Means of Egress					
6	Structural Integrity					
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)				Rubber	5
9	Exterior Walls/Siding				Hardy board	
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering				Vinyl covered drywall	
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\square			
16	Weatherproofing (List Deficiencies)		\square			
17	HVAC		\square			Bard
18	Electrical Receptacles		\square			
19	Distribution Panel (labeled Correctly)		\square			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line	Inspection Criteria	Condition		Inspection Comments					
#		Yes No							
29	Is unit in 100-year flood plain?								
30	Technology Capable								
31	Occupancy Certificate Posted in Unit								
32	Local Agency Reports Posted								
33	Does unit have any known Environmental factors? If yes, Explain.								
34	What grade level or usage is unit?	Other	K-5						
nspect	tor Signature:	<u>8-3/</u> Date:	-21_	Manager Signature: $\frac{9/32/27}{Date:}$					

					Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)			
Unit	Number: B R1324		- 1 		Unit Location: Belleair ES . Inspection Date: 8/31/21			
Insp	ected By: John H. I	Boryce	ens		License Number: BN 7352			
Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments			
1	Pier and foundations (Show Location on Back)							
2	Tie downs and Anchors (Show Location on Back)		\boxtimes					
3	Set Backs (Between Units and from property)		\boxtimes					
4	Steps and Ramps		\boxtimes		Concrete			
5	Means of Egress		\boxtimes					
6	Structural Integrity		\boxtimes					
7	Roof Trusses		\boxtimes					
8	Roof Covering (Note type Shingles, Veral, etc.)				Rubber			
9	Exterior Walls/Siding				Hardy board			
10	Exterior Lighting (note if any)		\square					
11	Interior Walls and Covering				Vinyl covered drywall			
12	Doors/Windows/ Hardware							
13	Floors/Carpet/Tile Type and Condition		\square					

Line	Inspection Criteria	10-065	Condi	ition		Inspection Comments
#	and couranes	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	K-5
			Additional Comments/Observations
\bigcap	$\langle \rangle$	2.74	$n \partial h$

Inspector Signature:

<u>8-3/-7/</u> Date:

Manager Signature:

<u>9/30/2/</u> Date:

						Pinellas Co Relocatable Classro (Yearly In:		on Certificate		
Unit l	Number: BR9985		See.			Unit Location: Be	elleair ES .		Inspection Date:	8/31/21
Insp	ected By: John H. E	Boryce	ens			License Number:	BN 7352			a nanko -
Line #	Inspection Criteria	New	Condition New Good Fair Poor				Inspection Com	ments	N SQL	
1	Pier and foundations (Show Location on Back)								*	
2	Tie downs and Anchors (Show Location on Back)								4	
3	Set Backs (Between Units and from property)		\square							
4	Steps and Ramps		\square			Aluminum				
5	Means of Egress		\square							
6	Structural Integrity		\square							
7	Roof Trusses		\square							
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Metal				
9	Exterior Walls/Siding		\square			Metal				
10	Exterior Lighting (note if any)		\square							4.
11	Interior Walls and Covering		\square			Paneling				
12	Doors/Windows/ Hardware		\boxtimes							
13	Floors/Carpet/Tile Type and Condition		\square						4	

Line	Inspection Criteria Condition			Inspection Comments		
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\square			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\square			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\square			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting					Emergency light is not working
21	Interior Light Fixtures (tied to structure)	\boxtimes	\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Condition Yes No		Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	K-5	
				Additional Comments/Observations
	·•.			
	#20 work worder for the	emergency light 10)4789	
		8-3/-	-21	10/4 9/30/21
nspec	tor Signature:	Date:		Manager Signature: Date:

						Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)		
Unit Number: C 8909						Unit Location: Belleair ES .	Inspection Date:	8/31/21
Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352		
Line #	Inspection Criteria	Condition New Good Fair Poor		Poor	Inspection Comn	nents		
1	Pier and foundations (Show Location on Back)		\square					
2	Tie downs and Anchors (Show Location on Back)		\square					
3	Set Backs (Between Units and from property)							
4	Steps and Ramps					Aluminum		
5	Means of Egress							
6	Structural Integrity		\square					
7	Roof Trusses							
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified		
9	Exterior Walls/Siding		\boxtimes			T 111		
10	Exterior Lighting (note if any)							
11	Interior Walls and Covering					Paneling		
12	Doors/Windows/ Hardware							
13	Floors/Carpet/Tile Type and Condition							

Line	Inspection Criteria	Condition				Inspection Comments	
#		New	Good	Fair	Poor		
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes				
16	Weatherproofing (List Deficiencies)		\square				
17	HVAC		\square			Bard	
18	Electrical Receptacles		\square				
19	Distribution Panel (labeled Correctly)					Square D panel	
20	Emergency Lighting						
21	Interior Light Fixtures (tied to structure)						
22	Fire Alarm (Strobes, Horn, Pull Stations)						
23	Heat Detector/Smoke Detector in Storage Spaces						
24	Heat Detector/Smoke Detector in Classroom						
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic	
26	Intercom system						
27	Fire Extinguisher (Tagged and Current)						
28	Plumbing/Fixtures					N/A	

Line	Inspection Criteria	Condition			Inspection Comments						
#		Yes	No								
29	ls unit in 100-year flood plain?		\square								
30	Technology Capable	\square									
31	Occupancy Certificate Posted in Unit	\square									
32	Local Agency Reports Posted	\boxtimes									
33	Does unit have any known Environmental factors? If yes, Explain.		\square								
34	What grade level or usage is unit?	Other		K-5							
-	Additional Comments/Observations										
100000											
~	1										
	\checkmark				n						
	()x		<i>8-3/-</i> Date:	<u>z/</u>	26/11/2 2/30/21						
Inspec	tor Signature:	C	Date:	705	Manager Signature: Date:						