						Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)			
Unit	Number: A 8830					Unit Location: Blanton ES. Inspection Date: 8/31/21			
Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352			
Line #	Inspection Criteria	New	Condi Good	tion Fair	Poor	Inspection Comments			
1	Pier and foundations (Show Location on Back)								
2	Tie downs and Anchors (Show Location on Back)								
3	Set Backs (Between Units and from property)		$\square$						
4	Steps and Ramps		$\square$			Aluminum			
5	Means of Egress		$\boxtimes$						
6	Structural Integrity								
7	Roof Trusses								
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified			
9	Exterior Walls/Siding		$\boxtimes$			T111			
10	Exterior Lighting (note if any)		$\square$						
11	Interior Walls and Covering		$\boxtimes$			Paneling			
12	Doors/Windows/ Hardware		$\boxtimes$						
13	Floors/Carpet/Tile Type and Condition		$\boxtimes$						

Line	Inspection Criteria	Sec	Condi	ition		Inspection Comments
#	and Condition into Land Lon	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\square$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\square$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\square$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\square$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition		Inspection Comments					
#		Yes	No							
29	Is unit in 100-year flood plain?		$\square$							
30	Technology Capable	$\square$								
31	Occupancy Certificate Posted in Unit									
32	Local Agency Reports Posted									
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$							
34	What grade level or usage is unit?	Other		Alpha Program						
		an an Malaona		Additional Co	omments/Observations					
					×					
					c					
$\int $	$\mathcal{I}$	2	8-2/-2/		alle-	9/2/21				
nspect	or signature:	D	<u>8-3/-2/</u> ate:	_	Manager Signature:	Date:				

					Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)		
Unit I	Number: A 8831				Unit Location: Blanton ES.	Inspection Date:	8/31/21
Inspe	ected By: John H. E	Boryce	ens		License Number: BN 7352		
Line #	Inspection Criteria	New	Condit Good	Poor	Inspection Commen	ts	
1	Pier and foundations (Show Location on Back)						
2	Tie downs and Anchors (Show Location on Back)						
3	Set Backs (Between Units and from property)						
4	Steps and Ramps		$\square$		Aluminum		
5	Means of Egress		$\square$				
6	Structural Integrity						
7	Roof Trusses						
8	Roof Covering (Note type Shingles, Veral, etc.)				Modified		
9	Exterior Walls/Siding				T111		
10	Exterior Lighting (note if any)					5	
11	Interior Walls and Covering				Paneling		
12	Doors/Windows/ Hardware		$\square$				
13	Floors/Carpet/Tile Type and Condition		$\boxtimes$				

Line	Inspection Criteria		Condi	tion		Inspection Comments
#	WHA CONTRACTOR	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\square$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\square$			
16	Weatherproofing (List Deficiencies)		$\square$			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Commen	nts
29	Is unit in 100-year flood plain?					
30	Technology Capable	$\square$			×	
31	Occupancy Certificate Posted in Unit	$\square$				
32	Local Agency Reports Posted	$\boxtimes$				
33	Does unit have any known Environmental factors? If yes, Explain.		$\square$			
34	What grade level or usage is unit?	Other		Alpha Program		
				Additional Co	omments/Observations	
					i i	

						Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)				
Unit	Number: A 8832					Unit Location: Blanton ES.	Inspection Date:	8/31/21		
Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352				
Line #	Inspection Criteria	New	Condi	tion Fair	Poor	Inspection Commen	ts			
1	Pier and foundations (Show Location on Back)									
2	Tie downs and Anchors (Show Location on Back)		$\square$							
3	Set Backs (Between Units and from property)		$\square$							
4	Steps and Ramps		$\square$			Aluminum				
5	Means of Egress									
6	Structural Integrity									
7	Roof Trusses									
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified				
9	Exterior Walls/Siding					T111				
10	Exterior Lighting (note if any)		$\square$				5. 5.			
11	Interior Walls and Covering		$\square$			Paneling				
12	Doors/Windows/ Hardware									
13	Floors/Carpet/Tile Type and Condition									

Line	Inspection Criteria Condition		-	Inspection Comments		
#	MAI CONTRACT	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\square$			
17	HVAC		$\square$			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\square$			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		$\square$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition		Inspection Comments			
#		Yes	No					
29	Is unit in 100-year flood plain?		$\square$					
30	Technology Capable	$\square$						
31	Occupancy Certificate Posted in Unit	$\boxtimes$						
32	Local Agency Reports Posted	$\boxtimes$						
33	Does unit have any known Environmental factors? If yes, Explain.							
34	What grade level or usage is unit?	Other		Alpha Program				
				Additional	Comments/Observations			
	6							
0	$\cap$				•			
//			8-3/-2	×.	2012 g/2/21			

						Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)			
Unit	Number: B 0903					Unit Location: Blanton ES. Inspection Date:	8/31/21		
Insp	ected By: John H. I	Boryce	ens			License Number: BN 7352			
Line #	Inspection Criteria	New	Condi Good	tion Fair	Poor	Inspection Comments			
1	Pier and foundations (Show Location on Back)								
2	Tie downs and Anchors (Show Location on Back)					]			
3	Set Backs (Between Units and from property)					]			
4	Steps and Ramps					] concrete walkways			
5	Means of Egress					]			
6	Structural Integrity					]			
7	Roof Trusses					]			
8	Roof Covering (Note type Shingles, Veral, etc.)					] Rubber			
9	Exterior Walls/Siding					hardy board			
10	Exterior Lighting (note if any)		$\boxtimes$			]			
11	Interior Walls and Covering					vinyl covered drywall			
12	Doors/Windows/ Hardware		$\boxtimes$			]			
13	Floors/Carpet/Tile Type and Condition		$\square$			]			

Line	Inspection Criteria		Condi	tion		Inspection Comments
#	and the subsection of the	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\square$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\square$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\square$			Bard
18	Electrical Receptacles		$\square$			
19	Distribution Panel (labeled Correctly)		$\square$			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Comments
29	ls unit in 100-year flood plain?				
30	Technology Capable	$\square$			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		K-5	
			enter Sector		Additional Comments/Observations
			aanaan maddii 15 ki seessaa miniin		
	tor Signature:	Ē	<i>8-3/-2</i> Date:	1	Manager Signature: Date:

	Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)											
Unit	Number: B 0904					Unit Location: Blanton ES.	Inspection Date: 8/31/21					
Insp	ected By: John H. B	Boryce	ens			License Number: BN 7352						
Line #	Inspection Criteria	New	Condi Good		Poor		Inspection Comments					
1	Pier and foundations (Show Location on Back)											
2	Tie downs and Anchors (Show Location on Back)											
3	Set Backs (Between Units and from property)											
4	Steps and Ramps					concrete walkways						
5	Means of Egress											
6	Structural Integrity											
7	Roof Trusses											
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber						
9	Exterior Walls/Siding					hardy board						
10	Exterior Lighting (note if any)											
11	Interior Walls and Covering					vinyl covered drywall						
12	Doors/Windows/ Hardware											
13	Floors/Carpet/Tile Type and Condition											

Line				Inspection Comments		
#	die geschen Longeschen eine Mig	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\square$			
19	Distribution Panel (labeled Correctly)		$\square$			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\square$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\square$			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\square$			in attic
26	Intercom system		$\square$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Cond Yes	ition No		Inspection Comments					
29	Is unit in 100-year flood plain?									
30	Technology Capable									
31	Occupancy Certificate Posted in Unit									
32	Local Agency Reports Posted									
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$							
34	What grade level or usage is unit?	Other		K-5						
	Additional Comments/Observations									
		1								
		8	-3/-2/	6	Manager Signature: Date:					
nspect	or signature:	Date	- <u>3/-2/</u> e:		Manager Signature: Date:					

	Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)											
Unit	Number: B 0905						nspection Date:	8/31/21				
Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352						
Line #	Inspection Criteria		Condi Good			Inspection Comments						
1	Pier and foundations (Show Location on Back)				Poor							
2	Tie downs and Anchors (Show Location on Back)											
3	Set Backs (Between Units and from property)						a dia					
4	Steps and Ramps					concrete walkways						
5	Means of Egress		$\square$					-				
6	Structural Integrity											
7	Roof Trusses											
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber						
9	Exterior Walls/Siding		$\square$			hardy board						
10	Exterior Lighting (note if any)		$\square$				a . 1					
11	Interior Walls and Covering		$\boxtimes$			vinyl covered drywall						
12	Doors/Windows/ Hardware		$\square$									
13	Floors/Carpet/Tile Type and Condition		$\square$									

Line	Inspection Criteria	Condition			Inspection Comments		
#	AND CONDENSION	New	Good	Fair	Poor		
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)						
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$				
16	Weatherproofing (List Deficiencies)		$\square$				
17	HVAC		$\square$			Bard	
18	Electrical Receptacles		$\square$				
19	Distribution Panel (labeled Correctly)		$\square$			Square D panel	
20	Emergency Lighting		$\square$				
21	Interior Light Fixtures (tied to structure)		$\square$				
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\square$				
23	Heat Detector/Smoke Detector in Storage Spaces						
24	Heat Detector/Smoke Detector in Classroom						
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic	
26	Intercom system						
27	Fire Extinguisher (Tagged and Current)						
28	Plumbing/Fixtures					N/A	

Line	Inspection Criteria	Co	ndition		Inspection Comments				
#		Yes	No						
29	Is unit in 100-year flood plain?								
30	Technology Capable	$\square$							
31	Occupancy Certificate Posted in Unit	$\square$							
32	Local Agency Reports Posted	$\boxtimes$							
33	Does unit have any known Environmental factors? If yes, Explain.		$\square$						
34				K-5	K-5				
		det :			Additional Comments/Observations				
			3						

Inspector Signature:

<u>8-3/-2/</u> Date:

Manager Signature:

<u>9/7/2/</u> Date:

	Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)											
Unit	Number: B 0906					Unit Location: Blanton ES. Inspection Date: 8/31/21						
Insp	ected By: John H. I	Boryce	ens			License Number: BN 7352						
Line #	Inspection Criteria	New	Condi Good	tion Fair	Poor	Inspection Comments						
1	Pier and foundations (Show Location on Back)		$\square$									
2	Tie downs and Anchors (Show Location on Back)											
3	Set Backs (Between Units and from property)											
4	Steps and Ramps		$\square$			concrete walkways						
5	Means of Egress		$\square$									
6	Structural Integrity											
7	Roof Trusses											
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber						
9	Exterior Walls/Siding					hardy board						
10	Exterior Lighting (note if any)		$\square$									
11	Interior Walls and Covering		$\boxtimes$			vinyl covered drywall						
12	Doors/Windows/ Hardware		$\boxtimes$									
13	Floors/Carpet/Tile Type and Condition											

Line	Line Inspection Criteria		Condi	tion		Inspection Comments
#	The Critical Contract of Contract	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\square$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\square$			
16	Weatherproofing (List Deficiencies)		$\square$			
17	HVAC		$\square$			Bard
18	Electrical Receptacles		$\square$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\square$			
21	Interior Light Fixtures (tied to structure)		$\square$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\square$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\square$			
24	Heat Detector/Smoke Detector in Classroom		$\square$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\square$			in attic
26	Intercom system		$\square$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable	$\boxtimes$			
31	Occupancy Certificate Posted in Unit	$\boxtimes$			
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.		$\square$		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
					•
				19	

Inspector Signature:

<u>&-3/-2/</u> Date:

Manager Signature:

<u>9/7/2/</u> Date:

	Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)											
Unit	Number: B 0907				400	Unit Location: B	ALC: N. Statistic Grant of the	Inspection Da	te: 8/31/21			
Insp	ected By: John H. I	Boryce	ens			License Number:	BN 7352					
Line #	Inspection Criteria	New	Condi Good		Poor			Inspection Comments				
1	Pier and foundations (Show Location on Back)		$\boxtimes$			-			-			
2	Tie downs and Anchors (Show Location on Back)					· · · ·			-			
3	Set Backs (Between Units and from property)											
4	Steps and Ramps		$\boxtimes$			concrete walkways						
5	Means of Egress											
6	Structural Integrity											
7	Roof Trusses							alter an	a h			
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber						
9	Exterior Walls/Siding					hardy board						
10	Exterior Lighting (note if any)											
11	Interior Walls and Covering					vinyl covered drywall	ğ Lu		а — 2			
12	Doors/Windows/ Hardware						n h Si					
13	Floors/Carpet/Tile Type and Condition											

Line	Inspection Criteria	Condition		35	Inspection Comments	
#	Sun coucies Tracina	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\square$			
16	Weatherproofing (List Deficiencies)		$\square$			
17	HVAC		$\square$			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\square$			Square D panel
20	Emergency Lighting		$\square$			
21	Interior Light Fixtures (tied to structure)		$\square$			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		$\square$			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\square$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Comments				
29	Is unit in 100-year flood plain?								
30	Technology Capable								
31	Occupancy Certificate Posted in Unit	$\boxtimes$							
32	Local Agency Reports Posted	$\boxtimes$							
33	Does unit have any known Environmental factors? If yes, Explain.								
34	What grade level or usage is unit?	Other		K-5					
1. <sup>19</sup> .		172015			Additional Comments/Observations				
			C.						
				¢.					

Inspector Signature:

<u>8-3/-2/</u> Date:

Manager Signature:

<u>9/2/21</u> Date:

					Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)			
Unit	Number: B 0908				Unit Location: Blanton ES. Inspection Date: 8/31/21			
Insp	ected By: John H. E	Boryce	ens		License Number: BN 7352			
Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments			
1	Pier and foundations (Show Location on Back)							
2	Tie downs and Anchors (Show Location on Back)		$\square$					
3	Set Backs (Between Units and from property)		$\square$					
4	Steps and Ramps		$\square$		concrete walkways			
5	Means of Egress		$\square$					
6	Structural Integrity		$\boxtimes$					
7	Roof Trusses		$\boxtimes$					
8	Roof Covering (Note type Shingles, Veral, etc.)		$\boxtimes$		Rubber			
9	Exterior Walls/Siding		$\boxtimes$		hardy board			
10	Exterior Lighting (note if any)							
11	Interior Walls and Covering				vinyl covered drywall			
12	Doors/Windows/ Hardware							
13	Floors/Carpet/Tile Type and Condition							

Line	Inspection Criteria	-	Condi	tion		Inspection Comments
#	Service States	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\square$			
16	Weatherproofing (List Deficiencies)		$\square$			
17	HVAC		$\square$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\square$			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		$\square$			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Con	dition		Inspection Comments								
#		Yes	No										
29	Is unit in 100-year flood plain?		$\boxtimes$										
30	Technology Capable	$\square$											
31	Occupancy Certificate Posted in Unit												
32	Local Agency Reports Posted	$\square$											
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$										
34	What grade level or usage is unit?	Other		K-5									
	Additional Comments/Observations												
		4											
$\bigvee$	$\wedge$												
$\langle \rangle$	$\langle /$		-1.	1	$\mathcal{A}$								
spect	or Signature:		2-3/-2 te:		Manager Signature: Date:								
speci		Dal	le.		Manager Signature: Date:								

					Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)				
Unit	Number: B 0909				Unit Location: Blanton ES.	Inspection Date:	8/31/21		
Insp	ected By: John H. E	Boryce	ens		License Number: BN 7352				
Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Commer	its	225910		
1	Pier and foundations (Show Location on Back)								
2	Tie downs and Anchors (Show Location on Back)								
3	Set Backs (Between Units and from property)								
4	Steps and Ramps				concrete walkways				
5	Means of Egress								
6	Structural Integrity								
7	Roof Trusses								
8	Roof Covering (Note type Shingles, Veral, etc.)				Rubber				
9	Exterior Walls/Siding				hardy board				
10	Exterior Lighting (note if any)								
11	Interior Walls and Covering				vinyl covered drywall				
12	Doors/Windows/ Hardware								
13	Floors/Carpet/Tile Type and Condition		$\boxtimes$			-			

Line	Inspection Criteria	ALC: NO	Condi	ition	in state	Inspection Comments
#	and coloniation	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\square$			
16	Weatherproofing (List Deficiencies)		$\square$			
17	HVAC		$\square$			Bard
18	Electrical Receptacles		$\square$			
19	Distribution Panel (labeled Correctly)		$\square$			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\square$			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition		Inspection Comments							
#		Yes	No									
29	Is unit in 100-year flood plain?		$\square$									
30	Technology Capable	$\square$										
31	Occupancy Certificate Posted in Unit	$\square$										
32	Local Agency Reports Posted											
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$									
34	What grade level or usage is unit?	Other		K-5								
R	Additional Comments/Observations											
					×							
-												
$\int$	$\sim$		3-3/-2	/	nelle gp/er							
ispect	or Signature:	D	<i>B-3/-2-</i> ate:		Manager Signature: Date:							

					Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)			
Unit	Number: B 0910				Unit Location: Blanton ES.	Inspection Date: 8/31/21		
Insp	ected By: John H. E	Boryc	ens		License Number: BN 7352			
Line #	Inspection Criteria	New	Condi Good	Poor	Inspectio	on Comments		
1	Pier and foundations (Show Location on Back)							
2	Tie downs and Anchors (Show Location on Back)							
3	Set Backs (Between Units and from property)							
4	Steps and Ramps		$\square$		concrete walkways			
5	Means of Egress							
6	Structural Integrity							
7	Roof Trusses		$\square$					
8	Roof Covering (Note type Shingles, Veral, etc.)				Rubber			
9	Exterior Walls/Siding		$\square$		hardy board			
10	Exterior Lighting (note if any)		$\square$					
11	Interior Walls and Covering				vinyl covered drywall			
12	Doors/Windows/ Hardware		$\square$					
13	Floors/Carpet/Tile Type and Condition		$\square$					

Line	Inspection Criteria		Condi	tion		Inspection Comments
#	and Concerns.	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\square$			
16	Weatherproofing (List Deficiencies)		$\square$			
17	HVAC		$\square$			Bard
18	Electrical Receptacles		$\square$			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Con	dition		Inspection Comments							
#	and the second	Yes	No									
29	Is unit in 100-year flood plain?		$\boxtimes$									
30	Technology Capable	$\square$										
31	Occupancy Certificate Posted in Unit	$\square$										
32	Local Agency Reports Posted											
33	Does unit have any known Environmental factors? If yes, Explain.			-								
34	What grade level or usage is unit?	Other		K-5								
	Additional Comments/Observations											
	12 C											
	,											
	*				-							
$\bigcap$	A				$\sim 0$							
	(A)		<u>3-3/-2</u> ate:	<u></u>	Alla 9/2/21							
spect	or signature:	Da	ate:		Manager Signature: Date:							

				• (********		Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)		
Unit	Number: B 0911					Unit Location: Blanton ES.	Inspection Date:	8/31/21
Insp	ected By: John H. E	Boryc	ens			License Number: BN 7352		
Line #	Inspection Criteria	New	Condi	tion Fair	Poor	Inspection Comme	ents	
1	Pier and foundations (Show Location on Back)							
2	Tie downs and Anchors (Show Location on Back)							
3	Set Backs (Between Units and from property)							
4	Steps and Ramps					concrete walkways		P
5	Means of Egress							
6	Structural Integrity							K.
7	Roof Trusses							
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber		
9	Exterior Walls/Siding					hardy board	Pres L	
10	Exterior Lighting (note if any)							
11	Interior Walls and Covering					vinyl covered drywall		
12	Doors/Windows/ Hardware		$\square$					
13	Floors/Carpet/Tile Type and Condition							

Line	Inspection Criteria		Condi	ition		Inspection Comments
#	SNA CONDUCTS	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\square$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)					
17	HVAC		$\square$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\square$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Condition			Inspection Comments				
#		Yes	No						
29	Is unit in 100-year flood plain?								
30	Technology Capable	$\square$							
31	Occupancy Certificate Posted in Unit	$\boxtimes$							
32	Local Agency Reports Posted	$\boxtimes$							
33	Does unit have any known Environmental factors? If yes, Explain.								
34	What grade level or usage is unit?	Other		K-5					
$\overline{\square}$	1								
pecto	or Signature:	Da	<i>8-3∕-2</i> ate:	2	Manager Signature: Date:				

	Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)							
Unit	Number: B 0912					Unit Location: Blanton ES.	Inspection Date:	8/31/21
Insp	ected By: John H. I	Зогус	ens			License Number: BN 7352		an a
Line #	Inspection Criteria	Condition New Good Fair Poor				Inspection Commer	its	
1	Pier and foundations (Show Location on Back)							
2	Tie downs and Anchors (Show Location on Back)							
3	Set Backs (Between Units and from property)							
4	Steps and Ramps					concrete walkways		
5	Means of Egress							
6	Structural Integrity							
7	Roof Trusses							
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber		
9	Exterior Walls/Siding					hardy board		1
10	Exterior Lighting (note if any)							
11	Interior Walls and Covering					vinyl covered drywall		
12	Doors/Windows/ Hardware							
13	Floors/Carpet/Tile Type and Condition							

Line	Inspection Criteria	-	Condi	ition		Inspection Comments
#	and Constraints	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\square$			
16	Weatherproofing (List Deficiencies)		$\square$			
17	HVAC		$\square$			Bard
18	Electrical Receptacles		$\square$			
19	Distribution Panel (labeled Correctly)		$\square$			Square D panel
20	Emergency Lighting		$\square$			
21	Interior Light Fixtures (tied to structure)		$\square$			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		$\square$			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\square$			in attic
26	Intercom system		$\square$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition		Inspection Comments						
#		Yes	No								
29	Is unit in 100-year flood plain?		$\square$								
30	Technology Capable	$\square$									
31	Occupancy Certificate Posted in Unit	$\square$									
32	Local Agency Reports Posted										
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$								
34	What grade level or usage is unit?	Other		K-5							
	Additional Comments/Observations										
2	$\frown$										
$\langle \rangle$	$\langle \rangle$				<i>D</i>						
X			<u>8-3/-2</u> ate:	1	2/1/2/ 9/7/21						
spect	or Signature:	D	ate:		Manager Signature: Date:						