						Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)
Unit I	Number: B8614					Unit Location: Brooker Creek ES. Inspection Date: 9/2/2021
Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria	New	Condit Good	tion Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)		\square			
3	Set Backs (Between Units and from property)		\square			
4	Steps and Ramps		\square			Aluminum
5	Means of Egress		\square			
6	Structural Integrity					
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Modified
9	Exterior Walls/Siding		\square			T 111
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering					Paneling
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			×
17	HVAC		\square			Bard
18	Electrical Receptacles		\square			
19	Distribution Panel (labeled Correctly)		\square			Square D panel
20	Emergency Lighting		\square			
21	Interior Light Fixtures (tied to structure)		\square			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		\square			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures		\square			This unit has a sink only

Line	Inspection Criteria	Co	ndition	a managana an	Inspection Comments
#		Yes	No		
29	Is unit in 100-year flood plain?				
30	Technology Capable	\square			
31	Occupancy Certificate Posted in Unit	\square			
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		K-5 scie	ence lab
		n e de Anno Colesco e de Colesco de Colesco			Additional Comments/Observations
			5		
			9-2-21	,	24/12- 2/9/21
Inspect	of Signature:	Ē	Date:	_	Manager Signature: Date:

						Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)		
Unit	Number: B9001					Unit Location: Brooker Creek ES.	Inspection Date:	9/2/2021
Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352		
Line #	Inspection Criteria	New	Condi	tion Fair	Poor	Inspection Comme	nts	
1	Pier and foundations (Show Location on Back)		\square					
2	Tie downs and Anchors (Show Location on Back)					2		
3	Set Backs (Between Units and from property)							
4	Steps and Ramps		\boxtimes			Aluminum		
5	Means of Egress							
6	Structural Integrity							
7	Roof Trusses							
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified		
9	Exterior Walls/Siding					Т 111	1	
10	Exterior Lighting (note if any)							
11	Interior Walls and Covering					Paneling		
12	Doors/Windows/ Hardware		\square					
13	Floors/Carpet/Tile Type and Condition							

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\square			
16	Weatherproofing (List Deficiencies)		\square			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		\square			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\square			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Condition		Inspection Comments
#		Yes No		
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	K-5	
	1			
X		9-2-2	1	Manager Signature: Date:

						Pinellas County Schoo Relocatable Classroom Inspection Cert (Yearly Inspection Report)		
Unit	Number: B9112					Unit Location: Brooker Creek ES.	Inspection Date:	9/2/2021
Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352		
Line #	Inspection Criteria	New	Condi Good	tion Fair	Poor	Insp	ection Comments	
1	Pier and foundations (Show Location on Back)						na na ann an Anna ann an A	
2	Tie downs and Anchors (Show Location on Back)							
3	Set Backs (Between Units and from property)							
4	Steps and Ramps					Aluminum		
5	Means of Egress		\boxtimes					
6	Structural Integrity		\boxtimes					
7	Roof Trusses		\boxtimes					
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified		
9	Exterior Walls/Siding		\boxtimes			Т 111	г. Г	
10	Exterior Lighting (note if any)		\boxtimes					
11	Interior Walls and Covering		\square			Paneling		
12	Doors/Windows/ Hardware							
13	Floors/Carpet/Tile Type and Condition							

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\square			
16	Weatherproofing (List Deficiencies)		\square			
17	HVAC		\square			Bard
18	Electrical Receptacles		\square			
19	Distribution Panel (labeled Correctly)		\square			Square D panel
20	Emergency Lighting		\square			
21	Interior Light Fixtures (tied to structure)		\square			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\square			
23	Heat Detector/Smoke Detector in Storage Spaces		\square			
24	Heat Detector/Smoke Detector in Classroom		\square			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\square			in attic
26	Intercom system		\square			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Co Yes	ndition No			Inspection Comments
29	Is unit in 100-year flood plain?					
30	Technology Capable					
31	Occupancy Certificate Posted in Unit	\boxtimes				
32	Local Agency Reports Posted					
33	Does unit have any known Environmental factors? If yes, Explain.			4		
34	What grade level or usage is unit?	Other		K-5		
					Additional Comments/Observ	vations
				50000000000000000000000000000000000000		
					£	
\wedge						
$\langle \rangle$	X		,			n.
nenat	or Signature:	4	9 - 2 - 2/ Pate:		Managar	Signature: Date:
Ispect	or olynature.	D	ale.		wanager	Signature: Date:

					Pinellas Con Relocatable Classroom				
Unit I	Number: B9323				Unit Location: Bro	a state of the second		Inspection Date:	9/2/2021
Insp	ected By: John H. E	Boryce	ens		License Number: E	BN 7352			
Line #	Inspection Criteria	New	Condit Good	Poor		Ins	pection Comme	nts	
1	Pier and foundations (Show Location on Back)								
2	Tie downs and Anchors (Show Location on Back)								
3	Set Backs (Between Units and from property)								
4	Steps and Ramps				Aluminum				
5	Means of Egress								
6	Structural Integrity		\square						
7	Roof Trusses					_			
8	Roof Covering (Note type Shingles, Veral, etc.)				Modified				
9	Exterior Walls/Siding				T 111				
10	Exterior Lighting (note if any)								
11	Interior Walls and Covering				Paneling				
12	Doors/Windows/ Hardware					-			
13	Floors/Carpet/Tile Type and Condition								

Line	Inspection Criteria		Condi	ition	alater e a	Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\square			
17	HVAC					Bard
18	Electrical Receptacles		\square			
19	Distribution Panel (labeled Correctly)		\square			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		\square			
24	Heat Detector/Smoke Detector in Classroom		\square			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\square			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\square				
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition	Landars Poly	Inspection Comments
#		Yes	No		
29	ls unit in 100-year flood plain?		\square		
30	Technology Capable	\square			
31	Occupancy Certificate Posted in Unit	\square			
32	Local Agency Reports Posted	\square			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other	<u>.</u>	K-5	
		and the second	an a		Additional Comments/Observations
			9-2-2 ate:		Nilli 2/2/21

						Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)	
Unit Number: E8919						Unit Location: Brooker Creek ES. Inspection Date:	9/2/2021
Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352	
Line #	Inspection Criteria	Condition New Good Fair Poor		Poor	Inspection Comments		
1	Pier and foundations (Show Location on Back)		\square				
2	Tie downs and Anchors (Show Location on Back)						
3	Set Backs (Between Units and from property)						
4	Steps and Ramps		\square			Aluminum	
5	Means of Egress						
6	Structural Integrity						
7	Roof Trusses						
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified	
9	Exterior Walls/Siding		\square			T 111	
10	Exterior Lighting (note if any)		\square				
11	Interior Walls and Covering		\square			Paneling	
12	Doors/Windows/ Hardware		\square				
13	Floors/Carpet/Tile Type and Condition						

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)				
16	Weatherproofing (List Deficiencies)				
17	HVAC				Bard
18	Electrical Receptacles				
19	Distribution Panel (labeled Correctly)				Square D panel
20	Emergency Lighting				
21	Interior Light Fixtures (tied to structure)		\square		
22	Fire Alarm (Strobes, Horn, Pull Stations)				
23	Heat Detector/Smoke Detector in Storage Spaces				
24	Heat Detector/Smoke Detector in Classroom				
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)				in attic
26	Intercom system				
27	Fire Extinguisher (Tagged and Current)	\boxtimes			
28	Plumbing/Fixtures				N/A

Line	Inspection Criteria	Conditio	n	Inspection Comments			
#		Yes No					
29	Is unit in 100-year flood plain?]				
30	Technology Capable]				
31	Occupancy Certificate Posted in Unit]				
32	Local Agency Reports Posted						
33	Does unit have any known Environmental factors? If yes, Explain.]				
34	What grade level or usage is unit?	Other	K-5	K-5			
				Additional Comments/Observations			
11213							
$ \land$	1						
	\times						
$\langle \zeta$	J	9-7	-71	all'i doly			
spect	or Signature:	Date:	-2/	Manager Signature: Date:			