	Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)									
Unit I	Number: B 8718					Unit Location: Calvin Hunsinger	Inspection Date:	9/15/21		
Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352				
Line #	Inspection Criteria	Condition New Good Fair Poor		Poor	Inspection Comments					
1	Pier and foundations (Show Location on Back)									
2	Tie downs and Anchors (Show Location on Back)		\square							
3	Set Backs (Between Units and from property)		\square							
4	Steps and Ramps					Aluminum				
5	Means of Egress		\square							
6	Structural Integrity									
7	Roof Trusses									
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified				
9	Exterior Walls/Siding					T 111				
10	Exterior Lighting (note if any)									
11	Interior Walls and Covering					Paneling				
12	Doors/Windows/ Hardware									
13	Floors/Carpet/Tile Type and Condition									

Line	Inspection Criteria	Condition			Inspection Comments		
#		New	Good	Fair	Poor		
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)						
15	Visual Aids (Chalk/Marker Boards and Tack Boards)						
16	Weatherproofing (List Deficiencies)						
17	HVAC					Bard	
18	Electrical Receptacles						
19	Distribution Panel (labeled Correctly)					Square D panel	
20	Emergency Lighting						
21	Interior Light Fixtures (tied to structure)						
22	Fire Alarm (Strobes, Horn, Pull Stations)						
23	Heat Detector/Smoke Detector in Storage Spaces						
24	Heat Detector/Smoke Detector in Classroom						
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic	
26	Intercom system						
27	Fire Extinguisher (Tagged and Current)	\boxtimes					
28	Plumbing/Fixtures					N/A	

Line	Inspection Criteria	Co	ndition	Inspection Comments
#		Yes	No	
29	Is unit in 100-year flood plain?		\square	
30	Technology Capable	\square		
31	Occupancy Certificate Posted in Unit	\square		
32	Local Agency Reports Posted	\boxtimes		
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes	
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
		•		
				*
	or Signature:		<u>9-/5-2/</u> ate:	Manager Signature: <u>9/30/21</u> Date:
nopood	(A) and a			Manager Signature. Date.

	Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)										
Unit	Number: B 9117		1. A.			Unit Location: Calvin Hunsinger.	Inspection Date:	9/15/21			
Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352					
Line #	Inspection Criteria	New	Condi Good	tion Fair	Poor	Inspection Commo	ents				
1	Pier and foundations (Show Location on Back)		\square								
2	Tie downs and Anchors (Show Location on Back)										
3	Set Backs (Between Units and from property)										
4	Steps and Ramps					Aluminum	с				
5	Means of Egress					\$					
6	Structural Integrity		\square								
7	Roof Trusses										
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified					
9	Exterior Walls/Siding					T 111					
10	Exterior Lighting (note if any)										
11	Interior Walls and Covering		\square			Paneling	~				
12	Doors/Windows/ Hardware		\square								
13	Floors/Carpet/Tile Type and Condition										

Line	Inspection Criteria	pection Criteria Condition			Inspection Comments		
#		New	Good	Fair	Poor		
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\square				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes				
16	Weatherproofing (List Deficiencies)		\boxtimes				
17	HVAC		\square			Bard	
18	Electrical Receptacles		\square				
19	Distribution Panel (labeled Correctly)		\boxtimes			Westinghouse panel	
20	Emergency Lighting		\square				
21	Interior Light Fixtures (tied to structure)		\square				
22	Fire Alarm (Strobes, Horn, Pull Stations)		\square				
23	Heat Detector/Smoke Detector in Storage Spaces		\square				
24	Heat Detector/Smoke Detector in Classroom						
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\square			in attic	
26	Intercom system		\square				
27	Fire Extinguisher (Tagged and Current)	\boxtimes					
28	Plumbing/Fixtures					N/A	

Line	Inspection Criteria	Co	ndition	A second s	Inspection Comme	nts
#		Yes	No			
29	Is unit in 100-year flood plain?		\square			
30	Technology Capable	\square				
31	Occupancy Certificate Posted in Unit	\square				
32	Local Agency Reports Posted	\square		ũ.		
33	Does unit have any known Environmental factors? If yes, Explain.		\square			
34	What grade level or usage is unit?	Other				
				Additional Cor	nments/Observations	
					×	
-						
			9 <i>−15 −2</i> ate:	24	all fren	<u>9/30/21</u> Date:
nspect	or Signature:	D	ate:		Manager Signature:	Date: