					Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)		
Unit	Number: B 9016				Unit Location: Campbell Park Es.	Inspection Date:	9/2/2021
Insp	ected By: John H. E	Boryce	ens		License Number: BN 7352		
Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments		
1	Pier and foundations (Show Location on Back)						
2	Tie downs and Anchors (Show Location on Back)						
3	Set Backs (Between Units and from property)						
4	Steps and Ramps		\boxtimes		Concrete		
5	Means of Egress						
6	Structural Integrity						Г.
7	Roof Trusses						
8	Roof Covering (Note type Shingles, Veral, etc.)				Rubber		
9	Exterior Walls/Siding				Hardy board		
10	Exterior Lighting (note if any)						
11	Interior Walls and Covering				vinyl covered drywall		
12	Doors/Windows/ Hardware						
13	Floors/Carpet/Tile Type and Condition						

Line	Inspection Criteria		Condi	ition	Sara a	Inspection Comments
#	the country of the second	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\square			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					NA

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		\square		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.		\square		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
\bigcirc			2-7-5	1	10/1 data

Inspector Signature:

Date: 4

Manager Signature:

9/9/21 Date:

						Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)	
Unit	Number: B 9017					Unit Location: Campbell Park Es. Inspection Date: 9/2/2	021
Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352	
Line #	Inspection Criteria	New	Condi Good	tion Fair	Poor	Inspection Comments	
1	Pier and foundations (Show Location on Back)						
2	Tie downs and Anchors (Show Location on Back)						
3	Set Backs (Between Units and from property)						
4	Steps and Ramps		\boxtimes			Concrete	
5	Means of Egress						
6	Structural Integrity						
7	Roof Trusses						
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber	
9	Exterior Walls/Siding					Hardy board	
10	Exterior Lighting (note if any)						
11	Interior Walls and Covering					vinyl covered drywall	
12	Doors/Windows/ Hardware						
13	Floors/Carpet/Tile Type and Condition		\boxtimes				

Line	Inspection Criteria		Condi			Inspection Comments
#	aut gougeds	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\square			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\square			
16	Weatherproofing (List Deficiencies)		\square			
17	HVAC					Bard
18	Electrical Receptacles		\square			
19	Distribution Panel (labeled Correctly)		\square			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition		Inspection Comments
#		Yes	No		
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable	\square			
31	Occupancy Certificate Posted in Unit	\square			
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		K-5	
nspect	or Signature:		7 – <i>Z – Z</i> ate:	/	Manager Signature: Date:

					Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)		
Unit I	Number: B 9018				Unit Location: Campbell Park Es.	Inspection Date:	9/2/2021
Inspe	ected By: John H. E	Boryce	ens		License Number: BN 7352		
Line #	Inspection Criteria	New	Condit Good	Poor	Inspection Comme	nts	
1	Pier and foundations (Show Location on Back)						
2	Tie downs and Anchors (Show Location on Back)					<u>*</u>	
3	Set Backs (Between Units and from property)						
4	Steps and Ramps				Concrete		
5	Means of Egress						
6	Structural Integrity					2	
7	Roof Trusses					9	
8	Roof Covering (Note type Shingles, Veral, etc.)				Rubber		
9	Exterior Walls/Siding				Hardy board		
10	Exterior Lighting (note if any)						
11	Interior Walls and Covering				vinyl covered drywall		
12	Doors/Windows/ Hardware						
13	Floors/Carpet/Tile Type and Condition						

Line	Inspection Criteria		Condi	tion		Inspection Comments
#	and Develope	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\square			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\square			
16	Weatherproofing (List Deficiencies)		\square			
17	HVAC		\square			Bard
18	Electrical Receptacles		\square			
19	Distribution Panel (labeled Correctly)		\square			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		\square			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\square			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition		Inspection Comments
#		Yes	No		
29	Is unit in 100-year flood plain?		\square		
30	Technology Capable	\square			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other	1	K-5	
		and the second			Additional Comments/Observations
1					0
X	$ \land ($		~		Allan 9/9/21
	A		9- <i>2-2</i>) ate:	/	76/16/ 9/9/21

					Relocatable Clas	County So sroom Inspection Inspection Report	on Certificate		
Unit	Number: B 9019				Unit Location: Campbell Park Es.			Inspection Date: 9/2/2	9/2/2021
Insp	ected By: John H. I	Boryc	ens		License Number	: BN 7352			
Line #	Inspection Criteria	New	Condi Good	Poor			Inspection Commen	ts	
1	Pier and foundations (Show Location on Back)								
2	Tie downs and Anchors (Show Location on Back)								
3	Set Backs (Between Units and from property)								
4	Steps and Ramps				Concrete				
5	Means of Egress								
6	Structural Integrity								
7	Roof Trusses								
8	Roof Covering (Note type Shingles, Veral, etc.)				Rubber				
9	Exterior Walls/Siding				Hardy board				
10	Exterior Lighting (note if any)								
11	Interior Walls and Covering				vinyl covered drywall				
12	Doors/Windows/ Hardware								
13	Floors/Carpet/Tile Type and Condition								

Line	Inspection Criteria	Stores	Condi	tion	11	Inspection Comments
#	ant toppical	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\square			
16	Weatherproofing (List Deficiencies)		\square			
17	HVAC		\square			Bard
18	Electrical Receptacles		\square			
19	Distribution Panel (labeled Correctly)		\square			Square D panel
20	Emergency Lighting		\square			
21	Interior Light Fixtures (tied to structure)		\square			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\square			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\square			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					NIA

Line	Inspection Criteria	Co	ndition		Inspection Comments
#		Yes	No		
29	Is unit in 100-year flood plain?		\square		
30	Technology Capable	\square			
31	Occupancy Certificate Posted in Unit	\square			
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		K-5	
		1	_		
$\overline{\langle}$	Dr Signature:		7-2-24	,	Manager Signature: $\frac{9/9/21}{Date:}$

					Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)
Unit	Number: B 9020				Unit Location: Campbell Park Es. Inspection Date: 9/2/2021
Insp	ected By: John H. I	Boryc	ens		License Number: BN 7352
Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)				
2	Tie downs and Anchors (Show Location on Back)				
3	Set Backs (Between Units and from property)				
4	Steps and Ramps				Concrete
5	Means of Egress				
6	Structural Integrity				
7	Roof Trusses				
8	Roof Covering (Note type Shingles, Veral, etc.)				Rubber
9	Exterior Walls/Siding				Hardy board
10	Exterior Lighting (note if any)				
11	Interior Walls and Covering				vinyl covered drywall
12	Doors/Windows/ Hardware				
13	Floors/Carpet/Tile Type and Condition				

Line	Inspection Criteria	18.17	Condi	tion		Inspection Comments
#	and Condition	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\square			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\square			
16	Weatherproofing (List Deficiencies)		\square			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)		\square			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition		Inspection Comments							
#		Yes	No									
29	Is unit in 100-year flood plain?											
30	Technology Capable	\square			14							
31	Occupancy Certificate Posted in Unit											
32	Local Agency Reports Posted	\boxtimes										
33	Does unit have any known Environmental factors? If yes, Explain.		\square									
34	What grade level or usage is unit?	Other	1	K-5								
	Additional Comments/Observations											
	· - ·											
0	1											
$\langle \rangle$	K	9	-z-2/		Manager Signature: Date:							
spect	or Signature:	D	ate:		Manager Signature: Date:							

						Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)	
Unit	Number: B 9021			niete Randelick		Unit Location: Campbell Park Es. Inspection Date: 9/2/2	2021
Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352	
Line #	Inspection Criteria	New	Condi Good		Poor	Inspection Comments	
1	Pier and foundations (Show Location on Back)						
2	Tie downs and Anchors (Show Location on Back)						
3	Set Backs (Between Units and from property)						
4	Steps and Ramps					Concrete	
5	Means of Egress						
6	Structural Integrity		\square				
7	Roof Trusses						
8	Roof Covering (Note type Shingles, Veral, etc.)		\square			Rubber	
9	Exterior Walls/Siding					Hardy board	
10	Exterior Lighting (note if any)						1.00
11	Interior Walls and Covering		\square			vinyl covered drywall	
12	Doors/Windows/ Hardware		\square				
13	Floors/Carpet/Tile Type and Condition		\square				

Line	Inspection Criteria		Condi	ition	المعالمة	Inspection Comments
#	aud Confiber	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\square			
16	Weatherproofing (List Deficiencies)		\square			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		\square			Square D panel
20	Emergency Lighting		\square			
21	Interior Light Fixtures (tied to structure)		\square			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\square			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\square			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Col Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable	\square			
31	Occupancy Certificate Posted in Unit	\square			
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.		\square		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
	*				
Inspe¢	tor Signature:		9-2-2/ Date:		Manager Signature: Date:

						Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)
Unit	Number: C 9215			in a		Unit Location: Campbell Park Es. Inspection Date: 9/2/2021
Insp	ected By: John H. I	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria	New	Condi Good		Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)		\square			
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress					
6	Structural Integrity					
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified
9	Exterior Walls/Siding					T 111
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering					Paneling
12	Doors/Windows/ Hardware		\boxtimes			
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes		
16	Weatherproofing (List Deficiencies)		\square		
17	HVAC		\bowtie		Bard
18	Electrical Receptacles		\square		
19	Distribution Panel (labeled Correctly)		\square		Square D panel
20	Emergency Lighting		\square		
21	Interior Light Fixtures (tied to structure)		\square		
22	Fire Alarm (Strobes, Horn, Pull Stations)		\square		
23	Heat Detector/Smoke Detector in Storage Spaces		\square		
24	Heat Detector/Smoke Detector in Classroom		\square		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\square		in attic
26	Intercom system				
27	Fire Extinguisher (Tagged and Current)	\boxtimes			
28	Plumbing/Fixtures				N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	K-5
			Additional Comments/Observations
			Σ.
			5
\bigcap			2

Inspector Signature:

<u>9-2-2/</u> Date:

Manager Signature:

Date:

					Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)		
Unit	Number: ER 8961				Unit Location: Campbell Park Es.	Inspection Date:	9/2/2021
Insp	ected By: John H. I	Boryce	ens		License Number: BN 7352		
Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comme	ents	
1	Pier and foundations (Show Location on Back)						
2	Tie downs and Anchors (Show Location on Back)						
3	Set Backs (Between Units and from property)						
4	Steps and Ramps				Aluminum	3	
5	Means of Egress						
6	Structural Integrity						
7	Roof Trusses						1
8	Roof Covering (Note type Shingles, Veral, etc.)				Modified		
9	Exterior Walls/Siding				Т 111		
10	Exterior Lighting (note if any)						
11	Interior Walls and Covering				Paneling	а. С	
12	Doors/Windows/ Hardware						
13	Floors/Carpet/Tile Type and Condition				· · · · · · · · · · · · · · · · · · ·		

Line #	Inspection Criteria	Now	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)				
16	Weatherproofing (List Deficiencies)		\square		
17	HVAC		\square		Bard
18	Electrical Receptacles		\square		
19	Distribution Panel (labeled Correctly)				Square D panel
20	Emergency Lighting				
21	Interior Light Fixtures (tied to structure)				
22	Fire Alarm (Strobes, Horn, Pull Stations)				
23	Heat Detector/Smoke Detector in Storage Spaces		\square		
24	Heat Detector/Smoke Detector in Classroom		\square		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\square		in attic
26	Intercom system		\square		
27	Fire Extinguisher (Tagged and Current)				
28	Plumbing/Fixtures		\square		This unit has a restroom

Line #		Conditi Yes No		Inspection Comments									
29	Is unit in 100-year flood plain?												
30	Technology Capable												
31	Occupancy Certificate Posted in Unit												
32	Local Agency Reports Posted												
33	Does unit have any known Environmental factors? If yes, Explain.		3										
34		Other	ĸ	5									
	Additional Comments/Observations												
Inspe	ctor Signature:	<u> </u>	2-21	Manager Signature: Date:									

						Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)	Sos-en Streen Terrest	
Unit	Number: LR 0608					Unit Location: Campbell Park Es. Inspection	Date:	9/2/2021
Insp	ected By: John H. E	Boryce	ens	den Fri Generalis		License Number: BN 7352		
Line #	Inspection Criteria	Condition New Good Fair Poor			Poor	Inspection Comments		en e
1	Pier and foundations (Show Location on Back)		\square					
2	Tie downs and Anchors (Show Location on Back)							
3	Set Backs (Between Units and from property)							
4	Steps and Ramps		\square			Aluminum		
5	Means of Egress							
6	Structural Integrity							
7	Roof Trusses							
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber		
9	Exterior Walls/Siding					Metal		
10	Exterior Lighting (note if any)							
11	Interior Walls and Covering					vinyl covered drywall		
12	Doors/Windows/ Hardware						_	
13	Floors/Carpet/Tile Type and Condition							

Line #	Inspection Criteria		Condi		121	Inspection Comments
#	Flocies Carband to 1988	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\square			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\square			
17	HVAC		\square			Bard
18	Electrical Receptacles		\square			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line	Inspection Criteria	Co	ndition	en print Traditionale e	Inspection Comments			
#		Yes	No					
29	Is unit in 100-year flood plain?		\square					
30	Technology Capable	\square						
31	Occupancy Certificate Posted in Unit	\square						
32	Local Agency Reports Posted	\square						
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes					
34	What grade level or usage is unit?	evel or Other						
				With the Care	Additional Comments/Observations			
			÷.					
\bigcap	1							
$\langle \rangle$	\bigvee		-					
λ	()		9-2-2	1	pilli g/g/2			
nspect	or Signature:	D	ate:		Manager Signature: Date:			

						Pinellas County Schools Relocatable Classroom Inspection Certificate (Yearly Inspection Report)		
Unit I	Number: LR 0609					Unit Location: Campbell Park Es.	Inspection Date:	9/2/2021
Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352		
Line #	Inspection Criteria	Condition New Good Fair Poor			Poor	Inspection Comment	S	
1	Pier and foundations (Show Location on Back)							
2	Tie downs and Anchors (Show Location on Back)							
3	Set Backs (Between Units and from property)							
4	Steps and Ramps					Aluminum		
5	Means of Egress							
6	Structural Integrity							
7	Roof Trusses							
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber		
9	Exterior Walls/Siding					Metal		
10	Exterior Lighting (note if any)							
11	Interior Walls and Covering					vinyl covered drywall		
12	Doors/Windows/ Hardware							
13	Floors/Carpet/Tile Type and Condition							

Line	Inspection Criteria	Condition		- Internet	Inspection Comments	
#	Alter Scholar	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\square			
17	HVAC		\square			Bard
18	Electrical Receptacles		\square			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting		\square			
21	Interior Light Fixtures (tied to structure)		\square			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\square			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		\square			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\square				
28	Plumbing/Fixtures					This unit has a restroom

Line #		Cor Yes	ndition No		Inspection Comments
29		Is unit in 100-year flood plain?		\square	
30	Technology Capable	\square			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\square		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
3					
			9-2-2		Manager Signature: Date:
Inspect	tor Signature:		Date:	/	Manager Signature: Date: