Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 1373 Unit Location: Clearwater Adult ED. Inspection Date: 9/9/2021

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations \times (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units 3 \boxtimes and from property) X 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity X 6 Roof Trusses X Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding X 9 metal Exterior Lighting (note if 10 X any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ X 12 Hardware Floors/Carpet/Tile Type 13 \times and Condition

Line #	Inspection Criteria		Condi			Inspection Comments
	Property of the second	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					*
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition	Inspection Comments
#		Yes	No	
29	Is unit in 100-year flood plain?		\boxtimes	
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes	
34	What grade level or usage is unit?	Adult I	Ed.	
				Additional Comments/Observations
	1.1-11			
1	1			

Inspector Signature:

9-9-2/

Manager Signature:

9/50/21

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 1374

Unit Location: Clearwater Adult ED.

Inspection Date: 9/9/2021

Inspected By: John H. Borycens License Number: BN 7352 Line **Inspection Criteria** Condition # **Inspection Comments** New Good Fair Poor Pier and foundations (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units X 3 and from property) \boxtimes 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity X 6 **Roof Trusses** X Roof Covering (Note type X 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding 9 \times metal Exterior Lighting (note if 10 \times any) Interior Walls and 11 X Vinyl covered drywall Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type 13 X and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No	Inspection Comments			
29	Is unit in 100-year flood plain?		\boxtimes				
30	Technology Capable	\boxtimes					
31	Occupancy Certificate Posted in Unit	\boxtimes					
32	Local Agency Reports Posted	\boxtimes					
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes				
34	What grade level or usage is unit?	Adult E	Ēd.				
	Additional Comments/Observations						
	1			2			

Inspector Signature:

9-9-2/ Date: Manager Signature:

9/30/21 Date:

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 1370 Unit Location: Clearwater Adult ED. Inspection Date: 9/9/2021

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # Good Fair Poor New Pier and foundations \times (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \times 4 Steps and Ramps Aluminum \boxtimes Means of Egress Structural Integrity X Roof Trusses X Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 metal Exterior Lighting (note if 10 X any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type 13 X and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	上,我是是一个人的。 第二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			⊎
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments						
29	Is unit in 100-year flood plain?								
30	Technology Capable								
31	Occupancy Certificate Posted in Unit								
32	Local Agency Reports Posted								
33	Does unit have any known Environmental factors? If yes, Explain.								
34	What grade level or usage is unit?	Adult Ed.							
		Additional Comments/Observations							
			*						
			*						
	i.								
/									

Inspector signature:

Manager Signature:

<u>9/39/21</u> Date: