Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B 8721 Unit Location: Clearwater HS. Inspection Date: 9/9/2021 Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity 6  $\boxtimes$ Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ Modified Shingles, Veral, etc.) Exterior Walls/Siding X9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and X 11 Paneling Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line #	Inspection Criteria	Condition  New Good Fair Poor		Poor	Inspection Comments	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)			T dil		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			346
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments	
29	Is unit in 100-year flood plain?		$\boxtimes$			
30	Technology Capable	$\boxtimes$				
31	Occupancy Certificate Posted in Unit	$\boxtimes$				
32	Local Agency Reports Posted					
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$			
34				9-12		
					Additional Comments/Observations	
1			-			

Manager Signature:

<u>19/18/2/</u> Date:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B 8722 Unit Location: Clearwater HS.

Inspection Date: 9/9/2021

Unit	Number: B 8/22					Unit Location: Clearwater HS.	Inspection Date: 9/9/2021
Inspe	ected By: John H. I	3oryc	ens			License Number: BN 7352	
Line #			法是是基本义主义是是国际国际的 医多种性神经病 医多种皮肤病				
*		New	Good	Fair	Poor	inspection	Comments
1	Pier and foundations (Show Location on Back)						
2	Tie downs and Anchors (Show Location on Back)						
3	Set Backs (Between Units and from property)						
4	Steps and Ramps					Aluminum	
5	Means of Egress						
6	Structural Integrity		$\boxtimes$				
7	Roof Trusses		$\boxtimes$				
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified	
9	Exterior Walls/Siding		$\boxtimes$			T 111	.2
10	Exterior Lighting (note if any)						
11	Interior Walls and Covering					Paneling	
12	Doors/Windows/ Hardware		$\boxtimes$				
13	Floors/Carpet/Tile Type and Condition						

Line	Inspection Criteria	Condition			Inspection Comments			
#		New	Good	Fair	Poor	医电影 医电影性 化重量 化化二甲烷 医电影 医电影 医电影 医电影		
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)							
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$					
16	Weatherproofing (List Deficiencies)		$\boxtimes$					
17	HVAC		$\boxtimes$			Bard		
18	Electrical Receptacles		$\boxtimes$					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			G E panel		
20	Emergency Lighting		$\boxtimes$					
21	Interior Light Fixtures (tied to structure)		$\boxtimes$					
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$					
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic		
26	Intercom system		$\boxtimes$					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$						
28	Plumbing/Fixtures					N/A		

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				<del></del>
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations
7	^				

Date:

Manager Signature:

10/18/21

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8811 Unit Location: Clearwater HS. Inspection Date: 9/9/2021

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition **Inspection Comments** # New Good Fair Poor Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type 13  $\boxtimes$ and Condition

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$		
16	Weatherproofing (List Deficiencies)				
17	HVAC				Bard
18	Electrical Receptacles				
19	Distribution Panel (labeled Correctly)		$\boxtimes$		Square D panel
20	Emergency Lighting		$\boxtimes$		
21	Interior Light Fixtures (tied to structure)		$\boxtimes$		
22	Fire Alarm (Strobes, Horn, Pull Stations)				25
23	Heat Detector/Smoke Detector in Storage Spaces				
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)				in attic
26	Intercom system				
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$			
28	Plumbing/Fixtures				N/A

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit	$\boxtimes$			
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$		
34	What grade level or usage is unit?	Other		9-12	
Additional Comments/Observations					
	,				
	1				
X	/		9-9-21	/	ple kli 19/18/21
nspect	or Signature:	D	ate:		Manager Signature: Date:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B 8812 Unit Location: Clearwater HS. Inspection Date: 9/9/2021

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria	New	Condit Good	tion Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)		$\boxtimes$			
2	Tie downs and Anchors (Show Location on Back)		$\boxtimes$			
3	Set Backs (Between Units and from property)		$\boxtimes$			
4	Steps and Ramps		$\boxtimes$			Aluminum
5	Means of Egress		$\boxtimes$			
6	Structural Integrity		$\boxtimes$			
7	Roof Trusses		$\boxtimes$			
8	Roof Covering (Note type Shingles, Veral, etc.)		$\boxtimes$			Modified
9	Exterior Walls/Siding					T 111
10	Exterior Lighting (note if any)		$\boxtimes$			
11	Interior Walls and Covering		$\boxtimes$			Paneling
12	Doors/Windows/ Hardware		$\boxtimes$			
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	【蓝素】黑蓝素、黑色色色色色色色色色色色色色色色色色色色色色色色色色色色色色色色色色色色
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Cor Yes	ndition No		Inspection Comments				
29	Is unit in 100-year flood plain?					*			
30	Technology Capable								
31	Occupancy Certificate Posted in Unit								
32	Local Agency Reports Posted								
33	Does unit have any known Environmental factors? If yes, Explain.								
34	What grade level or usage is unit?	Other		9-12					
					Additional Comments/Observations				
		*							
8									
					<del></del>				
_									

9-9-27 Date:

Manager Signature:

70/18/2/ Date:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8821 Unit Location: Clearwater HS.

Inspection Date: 9/9/2021

Oint	Number: B 8821				i parti	Unit Location: Clearwater HS.	Inspection Date:	9/9/2021
Insp	ected By: John H. I	Boryc	ens			License Number: BN 7352		
Line #	Inspection Criteria		Condi	tion		Inspection Commer	nts	
		New	Good	Fair	Poor			
1	Pier and foundations (Show Location on Back)		$\boxtimes$					
2	Tie downs and Anchors (Show Location on Back)							
3	Set Backs (Between Units and from property)		$\boxtimes$					
4	Steps and Ramps					Aluminum .		0
5	Means of Egress							
6	Structural Integrity							
7	Roof Trusses							
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified		
9	Exterior Walls/Siding					T 111		
10	Exterior Lighting (note if any)		$\boxtimes$					
11	Interior Walls and Covering		$\boxtimes$			Paneling		
12	Doors/Windows/ Hardware		$\boxtimes$					
13	Floors/Carpet/Tile Type and Condition		$\boxtimes$					

Line	Inspection Criteria	Condition		k dak	Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			R&R emergency light
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments	
29	Is unit in 100-year flood plain?		$\boxtimes$			
30	Technology Capable					
31	Occupancy Certificate Posted in Unit	$\boxtimes$				
32	Local Agency Reports Posted	$\boxtimes$				
33	Does unit have any known Environmental factors? If yes, Explain.					
34	What grade level or usage is unit?	Other		9-12	*	·
					Additional Comments/Observations	
	Work order for the eme	rgency lig	ght 104	1784		
						8
7	1					

7 - 7 - 2/ Date:

Manager Signature:

)ate:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8823 Unit Location: Clearwater HS. Inspection Date: 9/9/2021

Inspected By: John H. Borycens **License Number:** BN 7352 Inspection Criteria Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations  $\times$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units 3  $\boxtimes$ and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding 9  $\boxtimes$ T 111 Exterior Lighting (note if 10  $\boxtimes$ any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$		
16	Weatherproofing (List Deficiencies)		$\boxtimes$		
17	HVAC		$\boxtimes$		Bard
18	Electrical Receptacles		$\boxtimes$		
19	Distribution Panel (labeled Correctly)		$\boxtimes$		Square D panel
20	Emergency Lighting		$\boxtimes$		
21	Interior Light Fixtures (tied to structure)		$\boxtimes$		
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$		
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$		
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$		in attic
26	Intercom system		$\boxtimes$		
27	Fire Extinguisher (Tagged and Current)				
28	Plumbing/Fixtures				N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments	
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	9-12	
			Additional Comments/Observations	
1	8			

 $\frac{9-9-2}{\text{Date:}}$ 

Manager Signature:

<u>19/18/21</u> Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

**Unit Number:** B 8913 Unit Location: Clearwater HS. Inspection Date: 9/9/2021 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations  $\boxtimes$ 1 (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 **Roof Trusses**  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria		dition No		Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		9-12	
			H100		Additional Comments/Observations
				3	

Date:

Manager Signature:

0/18/2/ Date:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B 8916 Unit Location: Clearwater HS. Inspection Date: 9/9/2021
Inspected By: John H. Borycens License Number: BN 7352

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
	<b>走走走多走</b>	New	Good	Fair	Poor	mspection comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)		$\boxtimes$			
3	Set Backs (Between Units and from property)		$\boxtimes$			
4	Steps and Ramps		$\boxtimes$			Aluminum
5	Means of Egress		$\boxtimes$			
6	Structural Integrity		$\boxtimes$			
7	Roof Trusses		$\boxtimes$			
8	Roof Covering (Note type Shingles, Veral, etc.)		$\boxtimes$			Modified
9	Exterior Walls/Siding		$\boxtimes$			T 111
10	Exterior Lighting (note if any)		$\boxtimes$			
11	Interior Walls and Covering		$\boxtimes$			Paneling
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition		$\boxtimes$			

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)					
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations
					+
	x				

9-9-2/ Date:

Manager Signature:

Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8922 Unit Location: Clearwater HS. Inspection Date: 9/9/2021

Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations  $\times$ (Show Location on Back) Tie downs and Anchors X (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\times$ 4 Aluminum Steps and Ramps X 5 Means of Egress Structural Integrity X 6 Roof Trusses X Roof Covering (Note type  $\times$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and X 11 Paneling Covering Doors/Windows/ X 12 Hardware Floors/Carpet/Tile Type X 13 and Condition

Line	Inspection Criteria	Condition		76 . A	Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)					
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$		
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations
P					

 $\frac{9 - 9 - 2}{\text{Date:}}$ 

Manager Signature:

19/18/21 Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8933 Unit Location: Clearwater HS. Inspection Date: 9/9/2021

Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations X 1 (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$		
16	Weatherproofing (List Deficiencies)		$\boxtimes$		
17	HVAC		$\boxtimes$		Bard
18	Electrical Receptacles				
19	Distribution Panel (labeled Correctly)		$\boxtimes$		Square D panel
20	Emergency Lighting		$\boxtimes$		
21	Interior Light Fixtures (tied to structure)		$\boxtimes$		
22	Fire Alarm (Strobes, Horn, Pull Stations)				
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$		
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$		in attic
26	Intercom system		$\boxtimes$		
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$			
28	Plumbing/Fixtures				N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	9-12
			Additional Comments/Observations
		19	
			.10

7-9-21 Date: Manager Signature:

Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

**Unit Number:** B 8946 **Unit Location:** Clearwater HS. Inspection Date: 9/9/2021 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** Poor New Good Fair Pier and foundations  $\times$ 1 (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses X Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 T 111 Exterior Lighting (note if 10  $\boxtimes$ any) Interior Walls and 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line #	Inspection Criteria				Inspection Comments	
,"		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria Is unit in 100-year flood plain?	Condition Yes No			Inspection Comments
			$\boxtimes$		
30	Technology Capable	$\boxtimes$			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.				-
34	NAME OF THE PARTY		9-12		
					Additional Comments/Observations
7	1				

9 - 9 - 2/ Date:

Manager Signature:

10/88/2/ Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

**Unit Number:** B 8948 Unit Location: Clearwater HS. Inspection Date: 9/9/2021 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property) X 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity X 6 Roof Trusses X Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if  $\times$ 10 any) Interior Walls and X 11 Paneling Covering Doors/Windows/ X 12 Hardware

Floors/Carpet/Tile Type

and Condition

13

 $\boxtimes$ 

Line #	Inspection Criteria	Condition				Inspection Comments
		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments		
29	Is unit in 100-year flood plain?		$\boxtimes$				
30	Technology Capable	$\boxtimes$					
31	Occupancy Certificate Posted in Unit	$\boxtimes$		-			
32	Local Agency Reports Posted	$\boxtimes$					
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$				
34	What grade level or usage is unit?	Other		9-12			
	Additional Comments/Observations						
		(4)					
7	1						

Date:

Manager Signature:

)ate:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8956 Unit Location: Clearwater HS. Inspection Date: 9/9/2021

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors X (Show Location on Back) Set Backs (Between Units X3 and from property) X 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity X 6 **Roof Trusses** X Roof Covering (Note type X 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if X 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type 13  $\boxtimes$ and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Comments			
29	Is unit in 100-year flood plain?			= -				
30	Technology Capable	$\boxtimes$						
31	Occupancy Certificate Posted in Unit							
32	Local Agency Reports Posted	$\boxtimes$						
33	Does unit have any known Environmental factors? If yes, Explain.							
34	144		9-12	9-12				
					Additional Comments/Observations			
				×				
7	1							

9-9-2/ Date:

Manager Signature:

10/13/21 Date:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9004 Unit Location: Clearwater HS. **Inspection Date:** 9/9/2021

Inspe	ected By: John H. E	Boryc	ens			License Number: BN 7352
Line #	Inspection Criteria	Now	Condi		Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)	IVEW		- Call		
2	Tie downs and Anchors (Show Location on Back)		$\boxtimes$			<i>y</i>
3	Set Backs (Between Units and from property)		$\boxtimes$			
4	Steps and Ramps					Aluminum
5	Means of Egress		$\boxtimes$			
6	Structural Integrity					
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)		$\boxtimes$			Modified
9	Exterior Walls/Siding					T 111
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering					Paneling
12	Doors/Windows/ Hardware		$\boxtimes$			
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				¥
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations
~					

9-9-2/ Date:

Manager Signature:

19/18/21 Date:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B 9025 Unit Location: Clearwater HS. Inspection Date: 9/9/2021

Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\times$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ Roof Trusses  $\boxtimes$ Roof Covering (Note type X Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\times$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and X 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria		Condition			Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Cond Yes I	ition No		Inspection Comments				
29	Is unit in 100-year flood plain?		$\boxtimes$						
30	Technology Capable								
31	Occupancy Certificate Posted in Unit								
32	Local Agency Reports Posted								
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$						
34	What grade level or usage is unit?	Other	5/	9-12					
	Additional Comments/Observations								
-									
					4.				
		0	0 -	,					
nspect	or Signature:	Date	-9-2/ e:	_	Manager Signature: Date:				

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9102 **Unit Location:** Clearwater HS. Inspection Date: 9/9/2021 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property) 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and 11  $\boxtimes$ Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments			
29	Is unit in 100-year flood plain?							
30	Technology Capable							
31	Occupancy Certificate Posted in Unit							
32	Local Agency Reports Posted	$\boxtimes$						
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$					
34	340 4 1 1 1		9-12	9-12				
					Additional Comments/Observations			
4								
					2			

7-9-2/ Date:

Manager Signature:

10/18/2/ Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9115 **Unit Location:** Inspection Date: 9/9/2021 Clearwater HS. Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Condition Line # **Inspection Comments** Fair New Good Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 **Roof Trusses**  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)				
16	Weatherproofing (List Deficiencies)		$\boxtimes$		
17	HVAC		$\boxtimes$		Bard
18	Electrical Receptacles		$\boxtimes$		
19	Distribution Panel (labeled Correctly)		$\boxtimes$		Square D panel
20	Emergency Lighting		$\boxtimes$		R&R emergency light
21	Interior Light Fixtures (tied to structure)		$\boxtimes$		
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$		
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$		
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$		in attic
26	Intercom system		$\boxtimes$		).
27	Fire Extinguisher (Tagged and Current)				
28	Plumbing/Fixtures				N/A

Line #	Inspection Criteria	Medical Trans	ndition		Inspection Comments					
<b>"</b> "		Yes	No							
29	Is unit in 100-year flood plain?		$\boxtimes$							
30	Technology Capable	$\boxtimes$								
31	Occupancy Certificate Posted in Unit									
32	Local Agency Reports Posted	$\boxtimes$								
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$							
34	240 4 4 4 4			9-12	9-12					
					Additional Comments/Observations					
	#20 work order for the e	emergeno	cy light 🍴	4795						

 $\frac{9-9-2}{\text{Date:}}$ 

Manager Signature:

10/18/21 Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9136 Unit Location: Clearwater HS. Inspection Date: 9/9/2021 Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors  $\times$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses X Roof Covering (Note type  $\times$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if X 10 any) Interior Walls and 11 X Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line #	Inspection Criteria	New	Cond Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$		
16	Weatherproofing (List Deficiencies)		$\boxtimes$		
17	HVAC		$\boxtimes$		Bard
18	Electrical Receptacles		$\boxtimes$		
19	Distribution Panel (labeled Correctly)		$\boxtimes$		Square D panel
20	Emergency Lighting		$\boxtimes$		
21	Interior Light Fixtures (tied to structure)				
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$		
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$		
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$		in attic
26	Intercom system		$\boxtimes$		
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$			
28	Plumbing/Fixtures				N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	9-12
		300 10	Additional Comments/Observations

9-9-2/ Date: Manager Signature:

19/18/2/ Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9139 Unit Location: Clearwater HS. Inspection Date: 9/9/2021

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria	New	Condition Good	tion Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)		$\boxtimes$			
2	Tie downs and Anchors (Show Location on Back)		$\boxtimes$			
3	Set Backs (Between Units and from property)		$\boxtimes$			
4	Steps and Ramps		$\boxtimes$			Aluminum
5	Means of Egress		$\boxtimes$			
6	Structural Integrity		$\boxtimes$			
7	Roof Trusses		$\boxtimes$			
8	Roof Covering (Note type Shingles, Veral, etc.)		$\boxtimes$			Modified
9	Exterior Walls/Siding		$\boxtimes$			T 111
10	Exterior Lighting (note if any)		$\boxtimes$			
11	Interior Walls and Covering					Paneling
12	Doors/Windows/ Hardware		$\boxtimes$			
13	Floors/Carpet/Tile Type and Condition					

Line #	Inspection Criteria		Condition			Inspection Comments
		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria		dition No		Inspection Comments			
29	Is unit in 100-year flood plain?		$\boxtimes$					
30	Technology Capable	$\boxtimes$						
31	Occupancy Certificate Posted in Unit							
32	Local Agency Reports Posted							
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$					
34	What grade level or usage is unit?	Other		9-12				
					Additional Comments/Observations			
	¥							
7	1							

9-9-2/ Date:

Manager Signature:

10/13/21

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9205 **Unit Location:** Clearwater HS. Inspection Date: 9/9/2021 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 **Roof Trusses**  $\boxtimes$ Roof Covering (Note type X 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No	-352	Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$		8.
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations
*					
				,	
1	1				

Date:

Manager Signature:

<u>19/18/21</u> Date:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9207 Unit Location: Clearwater HS. Inspection Date: 9/9/2021

Insp	ected By: John H. I	Boryc	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
		New	Good	Fair	Poor	inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)		$\boxtimes$			
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress		$\boxtimes$			
6	Structural Integrity					
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified
9	Exterior Walls/Siding					T 111
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering					Paneling
12	Doors/Windows/ Hardware		$\boxtimes$			
13	Floors/Carpet/Tile Type and Condition		$\boxtimes$			

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit	$\boxtimes$		,	
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		9-12	
			9 (1000)		Additional Comments/Observations

 $\frac{9-9-2}{\text{Date:}}$ 

Manager Signature:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

**Unit Number:** B 9310 Unit Location: Clearwater HS. Inspection Date: 9/9/2021 Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** New Good Fair Poor Pier and foundations (Show Location on Back) Tie downs and Anchors 2  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 **Roof Trusses**  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line #	Inspection Criteria		Condi			Inspection Comments
		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					ti de la constant de
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$		
30	Technology Capable	$\boxtimes$			
31	Occupancy Certificate Posted in Unit	$\boxtimes$			
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations
	*				
			0 2	<b>7</b> /	1.000

7-4-Z/ Date: Manager Signature:

10/18/21 Date:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B 9324 Unit Location: Clearwater HS. Inspection Date: 9/9/2021 BN 7352 Inspected By: John H. Borycens License Number: **Inspection Criteria** Condition Line **Inspection Comments** # Fair Good Poor New Pier and foundations X (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line #	Inspection Criteria		Cond			Inspection Comments
		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC					Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$	4	
30	Technology Capable	$\boxtimes$			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$		
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations
* 4					
			8		
1					

2 - 9 - Z/ Date:

Manager Signature:

70/88/28

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9325 Unit Location: Clearwater HS. Inspection Date: 9/9/2021 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum 5  $\boxtimes$ Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria	Condition				Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit	$\boxtimes$			
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations
			2002 ET 1841 B. 200. USB 1706		
					8
		*			
^					

9 - 9 - 2 f Date:

Manager Signature:

12/18/21

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

**Unit Number: BRN 9307** Unit Location: Clearwater HS. Inspection Date: 9/9/2021 Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition **Inspection Comments** New Good Fair Poor

1	Pier and foundations (Show Location on Back)	$\boxtimes$		
2	Tie downs and Anchors (Show Location on Back)	$\boxtimes$		
3	Set Backs (Between Units and from property)	$\boxtimes$		
4	Steps and Ramps	$\boxtimes$		Aluminum
5	Means of Egress	$\boxtimes$		
6	Structural Integrity	$\boxtimes$		
7	Roof Trusses	$\boxtimes$		
8	Roof Covering (Note type Shingles, Veral, etc.)	$\boxtimes$		Modified
9	Exterior Walls/Siding	$\boxtimes$		T 111
10	Exterior Lighting (note if any)	$\boxtimes$		
11	Interior Walls and Covering	$\boxtimes$		Paneling
12	Doors/Windows/ Hardware	$\boxtimes$		
13	Floors/Carpet/Tile Type and Condition	$\boxtimes$		

Line	Inspection Criteria		Condition			Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No	Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$	
30	Technology Capable	$\boxtimes$		
31	Occupancy Certificate Posted in Unit	$\boxtimes$		
32	Local Agency Reports Posted	$\boxtimes$		
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$	
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
	4			
/				

9-9-Z/ Date: Manager Signature:

<u>19/18/2/</u> Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BRN 9328 Unit Location: Clearwater HS. Inspection Date: 9/9/2021

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors X (Show Location on Back) Set Backs (Between Units X 3 and from property)  $\times$ 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses X Roof Covering (Note type X Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 T 111 Exterior Lighting (note if X 10 any) Interior Walls and 11 X Paneling Covering Doors/Windows/ X 12 Hardware Floors/Carpet/Tile Type  $\times$ 13 and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				7
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom

Line #	Inspection Criteria	Condition	Inspection Comments
		Yes No	
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	
			Additional Comments/Observations
10.44			
		-	
			$\mathcal{L}_{\mathcal{L}}$

Date:

Manager Signature:

10/18/21

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BRN 9404 Unit Location: Clearwater HS. Inspection Date: 9/9/2021 Inspected By: John H. Borycens BN 7352 License Number: Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type XModified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if X 10 any) Interior Walls and 11  $\times$ Paneling Covering Doors/Windows/ 12  $\boxtimes$ Hardware Floors/Carpet/Tile Type  $\boxtimes$ and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)	A				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			6
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom

Line	Inspection Criteria	Con	dition	Inspection Comments
#		Yes	No	
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit	$\boxtimes$		
32	Local Agency Reports Posted	$\boxtimes$		
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$	
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
94				
<u></u>				

9-9-2/ Date:

Manager Signature:

<u>P/18/21</u> Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: C 8904 Unit Location: Clearwater HS. Inspection Date: 9/9/2021 Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors X (Show Location on Back) Set Backs (Between Units X 3 and from property) X 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity X 6 Roof Trusses X Roof Covering (Note type X 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 X T 111 Exterior Lighting (note if X 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type 13  $\boxtimes$ and Condition

Line #	Inspection Criteria	Condition  New Good Fair Poor				Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$		
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations
			9-9-71	-	26/8/2

7 - 7 - 2 / Date:

Manager Signature:

Date: