Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 7107 Unit Location: Cross Bayou ES. Inspection Date: 9/15/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** Good Fair New Poor Pier and foundations (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units X 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses X Roof Covering (Note type X 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if 10 \times any) Interior Walls and 11 \boxtimes Paneling Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					1000年,1000年
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)					Cutler Hammer panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
			-		
7	1				

9-15-2/

Manager Signature:

10/11/21

Relocatable Classroom Inspection Certificate

(Yearly Inspection Report)

Unit Number: B 9134 Unit Location: Cross Bayou ES. Inspection Date: 9/15/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes Steps and Ramps 4 Aluminum \boxtimes 5 Means of Egress Structural Integrity 6 \boxtimes Roof Trusses \boxtimes Roof Covering (Note type X 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X T 111 9 Exterior Lighting (note if X 10 any) Interior Walls and \times 11 Paneling Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			~
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting				X	Emergency light not working
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Coi Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit	\boxtimes			
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
	# 20 Work order foor th	e emerge	ency light#	105484	

9-/5-2/ Date:

Manager Signature:

10/11/21 Date!

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9414 Unit Location: Cross Bayou ES. Inspection Date: 9/15/21 Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** New Good Fair Poor Pier and foundations 1 (Show Location on Back) Tie downs and Anchors 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity X 6 Roof Trusses X Roof Covering (Note type \times 8 Modified I Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No		Inspection Comments	
29	Is unit in 100-year flood plain?				The second secon
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other	K-5		
			Addi	tional Comments/Observations	
		-			

9-/>-2/ Date:

Manager Signature:

10/11/21 rate:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: E 8717 Unit Location: Cross Bayou ES. Inspection Date: 9/15/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition **Inspection Comments** New Good Fair Poor Pier and foundations \times (Show Location on Back) Tie downs and Anchors X (Show Location on Back) Set Backs (Between Units X 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity 6 \times Roof Trusses X Roof Covering (Note type 8 X Modified I Shingles, Veral, etc.) Exterior Walls/Siding 9 X T 111 Exterior Lighting (note if 10 \times any) Interior Walls and 11 X Paneling Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			ε.
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit	\boxtimes			
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
\bigvee		-	Q 15 3	. 1	110.

7-15-21 Date: Manager Signature:

Date:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: Unit Location: Cross Bayou ES. **ERK 9033**

Inspection Date: 9/15/21

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria		Condit	tion		Inspection Comments
"		New	Good	Fair	Poor	
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps		\boxtimes			Aluminum
5	Means of Egress					
6	Structural Integrity		\boxtimes			
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Metal
9	Exterior Walls/Siding		\boxtimes			Metal
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering		\boxtimes			Paneling
12	Doors/Windows/ Hardware		\boxtimes			
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line #	Inspection Criteria		Condi	ition		Inspection Comments
" "		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)					Cutler Hammer panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Condition Yes No		Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	К	
				Additional Comments/Observations
	1			
1				

9-/5-2/ Date:

Manager Signature:

Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: Unit Location: Cross Bayou ES. LR 0429 Inspection Date: 9/15/21 Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units X and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses X Roof Covering (Note type \boxtimes Rubber Shingles, Veral, etc.) Exterior Walls/Siding 9 X Metal Exterior Lighting (note if X 10 any) Interior Walls and 11 \boxtimes Vinyl covered drywall Covering Doors/Windows/ X Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting				\boxtimes	Emergency light is not working
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	2007 2007 2007 2007 2007 2007 2007 2007	Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	K-5	
	Additional Comments/Observations			
	#20 work order for the emergency light # 105489			
				*
\bigvee	7			

<u>ター/ S - Z /</u> Date:

Manager Signature:

10/11/21 Date: