Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 0764 Unit Location: Curlew Creek (Chi Chi) Inspection Date: 9/15/21

Insp	ected By: John H. I	Boryc	ens		License Number: BN 7352
Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)				
2	Tie downs and Anchors (Show Location on Back)		$\boxtimes$		
3	Set Backs (Between Units and from property)		$\boxtimes$		
4	Steps and Ramps		$\boxtimes$		Aluminum
5	Means of Egress		$\boxtimes$		
6	Structural Integrity				
7	Roof Trusses				
8	Roof Covering (Note type Shingles, Veral, etc.)		$\boxtimes$		Rubber
9	Exterior Walls/Siding				Metal
10	Exterior Lighting (note if any)				
11	Interior Walls and Covering		$\boxtimes$		Vinyl covered drywall
12	Doors/Windows/ Hardware				
13	Floors/Carpet/Tile Type and Condition		$\boxtimes$		

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	보다면 하는 경기들이 그리고 있는데 그렇게 되었다. 그리고 그 그렇게 되었다.
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	
			Additional Comments/Observations
		EL .	
			*
nspect	or Signature:	<u>9-15-7</u> Date:	Manager Signature: Date:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 0765 Unit Location: Curlew Creek (Chi Chi) Inspection Date: 9/15/21

Insp	ected By: John H. I	3oryc	ens			License Number: BN 7352
Line #	Inspection Criteria	New	Condi Good	tion Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)		$\boxtimes$			
4	Steps and Ramps		$\boxtimes$			Aluminum
5	Means of Egress		$\boxtimes$			
6	Structural Integrity		$\boxtimes$			
7	Roof Trusses		$\boxtimes$			
8	Roof Covering (Note type Shingles, Veral, etc.)		$\boxtimes$			Rubber
9	Exterior Walls/Siding		$\boxtimes$			Metal
10	Exterior Lighting (note if any)		$\boxtimes$			
11	Interior Walls and Covering					Vinyl covered drywall
12	Doors/Windows/ Hardware		$\boxtimes$			
13	Floors/Carpet/Tile Type and Condition		$\boxtimes$			

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom

Line #	Inspection Criteria	Condition Yes No		Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			*
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
		0.		
	1		7	

Inspector Signature:

 $\frac{9-15-2}{\text{Date:}}$ 

Manager Signature:

9/30/2/ Date:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 0766 Unit Location: Curlew Creek (Chi Chi) Inspection Date: 9/15/21

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
"		New	Good	Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)		$\boxtimes$			
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress		$\boxtimes$			
6	Structural Integrity		$\boxtimes$			
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)		$\boxtimes$			Rubber
9	Exterior Walls/Siding		$\boxtimes$			Metal
10	Exterior Lighting (note if any)		$\boxtimes$			
11	Interior Walls and Covering		$\boxtimes$			Vinyl covered drywall
12	Doors/Windows/ Hardware		$\boxtimes$			
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	마른 사람들은 하는 그 그 사람이 없는 것이 하고 있다. 그는 사람들은 사람들은 사람들이 되었다.
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition	Inspection Comments
		Yes No	。
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	
		public design of the public de	Additional Comments/Observations
			*
		8	
1	1		41

Inspector Signature:

9-/5-2/ Date:

Manager Signature:

9/30/2/ Date:

## **Pinellas County Schools**

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

**Unit Number: BR 0767** Unit Location: Curlew Creek (Chi Chi) Inspection Date: 9/15/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ Rubber Shingles, Veral, etc.) Exterior Walls/Siding X 9 Metal Exterior Lighting (note if X 10 any) Interior Walls and 11  $\boxtimes$ Vinyl covered drywall Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type 13  $\boxtimes$ and Condition

Line	Inspection Criteria		Condi	tion	1.1.	Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom

	Inspection Criteria	Yes	ndition No	Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit	$\boxtimes$		
32	Local Agency Reports Posted	$\boxtimes$		
33	Does unit have any known Environmental factors? If yes, Explain.			·
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
				· · · · · · · · · · · · · · · · · · ·
	A			