Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Location: Curlew Creek ES Inspection Date: 9/15/21 Unit Number: BR 0575

ected By: John H. E	Boryce	ens			License Number: BN 7352
Inspection Criteria	New		tion Fair	Poor	Inspection Comments
Pier and foundations (Show Location on Back)		\boxtimes			
Tie downs and Anchors (Show Location on Back)		\boxtimes			
Set Backs (Between Units and from property)		\boxtimes			
Steps and Ramps		\boxtimes			Aluminum
Means of Egress		\boxtimes			
Structural Integrity		\boxtimes			
Roof Trusses		\boxtimes			
Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Rubber
Exterior Walls/Siding		\boxtimes			Metal
Exterior Lighting (note if any)		\boxtimes			
Interior Walls and Covering		\boxtimes			Vinyl covered drywall
Doors/Windows/ Hardware		\boxtimes			
Floors/Carpet/Tile Type and Condition					
	Pier and foundations (Show Location on Back) Tie downs and Anchors (Show Location on Back) Set Backs (Between Units and from property) Steps and Ramps Means of Egress Structural Integrity Roof Trusses Roof Covering (Note type Shingles, Veral, etc.) Exterior Walls/Siding Exterior Lighting (note if any) Interior Walls and Covering Doors/Windows/Hardware Floors/Carpet/Tile Type	Inspection Criteria New Pier and foundations (Show Location on Back) Tie downs and Anchors (Show Location on Back) Set Backs (Between Units and from property) Steps and Ramps Means of Egress Structural Integrity Roof Trusses Roof Covering (Note type Shingles, Veral, etc.) Exterior Walls/Siding Exterior Lighting (note if any) Interior Walls and Covering Doors/Windows/ Hardware Floors/Carpet/Tile Type	Pier and foundations (Show Location on Back) Tie downs and Anchors (Show Location on Back) Set Backs (Between Units and from property) Steps and Ramps Means of Egress Structural Integrity Roof Trusses Roof Covering (Note type Shingles, Veral, etc.) Exterior Walls/Siding Exterior Lighting (note if any) Interior Walls and Covering Doors/Windows/ Hardware Floors/Carpet/Tile Type	Inspection Criteria New Good Fair	Inspection Criteria New Good Fair Poor

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting				\boxtimes	Emergency light not working
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit	\boxtimes			
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		K-	-5
					Additional Comments/Observations
					*
	#20work order for the e	mergeno	y light 1	05392	
					2

 $\frac{9-/S-Z/}{\text{Date:}}$

Manager Signature:

9/30/21 Date:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 0584 Unit Location: Curlew Creek ES Inspection Date: 9/15/21

Inspe	ected By: John H. E	Boryce	ens		License Number: BN 7352		
Line #	Inspection Criteria	Now	Condi	Poor	Inspection Comments		
1	Pier and foundations (Show Location on Back)						
2	Tie downs and Anchors (Show Location on Back)						
3	Set Backs (Between Units and from property)		\boxtimes				
4	Steps and Ramps		\boxtimes		Aluminum .		
5	Means of Egress		\boxtimes				
6	Structural Integrity						
7	Roof Trusses		\boxtimes				
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes		Rubber		
9	Exterior Walls/Siding				Metal		
10	Exterior Lighting (note if any)		\boxtimes				
11	Interior Walls and Covering		\boxtimes		Vinyl covered drywall		
12	Doors/Windows/ Hardware		\boxtimes				
13	Floors/Carpet/Tile Type and Condition						

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				。 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit	\boxtimes			
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
	or Signature:	-	9 - / S	-z/	Manager Signature: Date:

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 9504 Unit Location: Curlew Creek ES Inspection Date: 9/15/21 Inspected By: John H. Borycens License Number: **BN 7352** Inspection Criteria Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors X (Show Location on Back) Set Backs (Between Units 3 X and from property) X 4 Steps and Ramps Aluminum \times 5 Means of Egress Structural Integrity 6 \boxtimes Roof Trusses X Roof Covering (Note type \times Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if X 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ X 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condition		1	Inspection Comments
#		New	Good	Fair	Poor	그러 그 그 맛있다면 그 가게 하는 그리고 하는 것들이 그리고 가장이었다. 그 그리고 있다.
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC *		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
			9-15-2	/	20/21

Date:

Manager Signature:

Date:

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: ER 9014 Unit Location: Curlew Creek ES Inspection Date: 9/15/21 Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Condition Line **Inspection Comments** # Fair New Good Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units 3 X and from property) X 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type X Modified 8 Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if X 10 any) Interior Walls and X 11 Paneling Covering Doors/Windows/ \times 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria	Condition				Inspection Comments
#		New	Good	Fair	Poor	물레드 보고 하는 마음 모양이 그리지 않는 중에서 그 사고 하다가 그림을 맞을 때 그는 다.
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line	Inspection Criteria	Coi	ndition		Inspection Comments
#		Yes	. No		
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		OT/P	T
					Additional Comments/Observations
		Parkage and an own for the first several recommendation			
				*	
				*	
_					
			G_K-5	,	

9-75-2/ Date:

Manager Signature:

9/30/2/ Date:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: LR 0516 Unit Location: Curlew Creek ES Inspection Date: 9/15/21

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria	New	Condi Good	tion Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)		\boxtimes			
4	Steps and Ramps		\boxtimes			Aluminum
5	Means of Egress		\boxtimes			
6	Structural Integrity		\boxtimes			
7	Roof Trusses		\boxtimes			
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Rubber
9	Exterior Walls/Siding		\boxtimes			Metal
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering					Vinyl covered drywall
12	Doors/Windows/ Hardware		\boxtimes			
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria		lition No		Inspection Comments
		162	1		2000年1月1日 1月1日 1月1日 1月1日 1月1日 1月1日 1月1日 1月1日
29	Is unit in 100-year flood plain?				
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other	,	K-5	
					Additional Comments/Observations
	-				
~	1				

9-/5-Z/

Manager Signature:

9/30/2/ Date:

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: LR 0672 Unit Location: Curlew Creek ES Inspection Date: 9/15/21 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** Poor New Good Fair Pier and foundations X (Show Location on Back) Tie downs and Anchors X (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) X Steps and Ramps 4 Aluminum \boxtimes 5 Means of Egress Structural Integrity 6 \boxtimes Roof Trusses \boxtimes Roof Covering (Note type \boxtimes Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 Metal Exterior Lighting (note if X 10 any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			*
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line	Inspection Criteria	Condition		Inspection Comments	
#		Yes No			
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		·		
34	What grade level or usage is unit?	Other	K-5		
			Addition	al Comments/Observations	
			-		
7					

 $\frac{9-15-2}{\text{Date:}}$

Manager Signature:

9/30/21 Pate: