## **Pinellas County Schools**

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Location: Curtis Fundamental Unit Number: B 8815 **Inspection Date:** 9/16/21 Inspected By: John H. Borycens License Number: BN 7352 Condition **Inspection Criteria** Line **Inspection Comments** # Good Fair Poor New Pier and foundations X (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units X 3 and from property) X 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and X 11 Paneling Covering Doors/Windows/ X Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria	teria Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments					
29	Is unit in 100-year flood plain?							
30	Technology Capable							
31	Occupancy Certificate Posted in Unit							
32	Local Agency Reports Posted							
33	Does unit have any known Environmental factors? If yes, Explain.							
34	What grade level or usage is unit?	Other	K-5					
	Additional Comments/Observations							
	,							
		8						
		•						
	1							

Inspector Signature:

 $\frac{9-16-24}{\text{Date:}}$ 

Manager Signature:

9/30/21

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: ER 8906 Unit Location: Curtis Fundamental

Inspection Date: 9/16/21

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
		New	Good	Fair	Poor	
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)		$\boxtimes$			
4	Steps and Ramps		$\boxtimes$			Aluminum
5	Means of Egress					
6	Structural Integrity		$\boxtimes$			
7	Roof Trusses		$\boxtimes$			
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified
9	Exterior Walls/Siding					T 111
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering					Paneling
12	Doors/Windows/ Hardware		$\boxtimes$			
13	Floors/Carpet/Tile Type and Condition		$\boxtimes$			

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					This unit has a restroom

Line	Inspection Criteria	Condi	lion		Inspection Comments		
#		Yes N	0				
29	Is unit in 100-year flood plain?						
30	Technology Capable						
31	Occupancy Certificate Posted in Unit						
32	Local Agency Reports Posted						
33	Does unit have any known Environmental factors? If yes, Explain.						
34	What grade level or usage is unit?	Other		K-5			
	Additional Comments/Observations						
					3		
				74			

Inspector Signature:

9-16-21 Date:

Manager Signature:

9/30/2/ Date: