Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 9405 **Unit Location: Dropout Prevention** Inspection Date: 10/20/21 Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations \times 1 (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units 3 \boxtimes and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes 7 Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and 11 \boxtimes Paneling Covering Doors/Windows/ 12 Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

| Line | Inspection Criteria | | Condi | ition | | Inspection Comments |
|------|---|-------------|-------------|-------|------|--|
| # | | New | Good | Fair | Poor | |
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | | | | A CONTRACTOR OF THE CONTRACTOR |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | \boxtimes | | | |
| 16 | Weatherproofing (List Deficiencies) | | \boxtimes | | | |
| 17 | HVAC | | \boxtimes | | | Bard |
| 18 | Electrical Receptacles | | \boxtimes | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | | Square D panel |
| 20 | Emergency Lighting | | \boxtimes | | | |
| 21 | Interior Light Fixtures (tied to structure) | | \boxtimes | | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | \boxtimes | | | in attic |
| 26 | Intercom system | | \boxtimes | | | |
| 27 | Fire Extinguisher (Tagged and Current) | \boxtimes | | | | |
| 28 | Plumbing/Fixtures | | \boxtimes | | | This unit has a restroom |
| | | | | | | |

| Line # | Inspection Criteria | Condition | Inspection Comments | | | |
|-----------|--|-----------|---------------------|--|--|--|
| | | Yes No | | | | |
| 29 | Is unit in 100-year flood plain? | | | | | |
| 30 | Technology Capable | | | | | |
| 31 | Occupancy Certificate Posted in Unit | | | | | |
| 32 | Local Agency Reports Posted | | | | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | | | | |
| 34 | What grade level or usage is unit? | Other | | | | |
| | Additional Comments/Observations | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| \sim | | | | | | |

Inspector Signature:

Date:

Manager Signature:

10/28/2/ Date:

Pinellas County Schools

Relocatable Classroom Inspection Certificate

(Yearly Inspection Report) 10/20/21 **Dropout Prevention** Inspection Date: **Unit Location:** Unit Number: BRO 0847 BN 7352 License Number: Inspected By: John H. Borycens Condition Inspection Criteria Line **Inspection Comments** # Poor New Good Fair Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Aluminum Steps and Ramps \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes 7 Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding 9 \boxtimes Hardy board Exterior Lighting (note if 10 X any) Interior Walls and 11 Vinyl covered drywall Covering Doors/Windows/ X 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

| Line # | Inspection Criteria | New | Condi Good | Poor | Inspection Comments |
|-----------|---|-----|---------------|------|--------------------------|
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | \boxtimes | | |
| 16 | Weatherproofing (List Deficiencies) | | \boxtimes | | |
| 17 | HVAC | | \boxtimes | | Bard |
| 18 | Electrical Receptacles | | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | Cuttler Hammer panel |
| 20 | Emergency Lighting | | \boxtimes | | |
| 21 | Interior Light Fixtures (tied to structure) | | \boxtimes | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | \boxtimes | | in attic |
| 26 | Intercom system | | | | |
| 27 | Fire Extinguisher (Tagged and Current) | | | | |
| 28 | Plumbing/Fixtures | | | | This unit has a restroom |
| | | | | | |

| Line | Inspection Criteria | Co | ndition | Inspection Comments | | | | | | | |
|--------|--|----------------------------------|-----------------|--|--|--|--|--|--|--|--|
| # | | Yes | No | 的现在分词 1000 2000 2000 1000 1000 1000 1000 100 | | | | | | | |
| 29 | Is unit in 100-year flood plain? | | \boxtimes | | | | | | | | |
| 30 | Technology Capable | | | | | | | | | | |
| 31 | Occupancy Certificate Posted in Unit | | | | | | | | | | |
| 32 | Local Agency Reports Posted | | | | | | | | | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | | | | | | | | | |
| 34 | What grade level or usage is unit? | Other | | | | | | | | | |
| | | Additional Comments/Observations | | | | | | | | | |
| | | | | * | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | , | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | 100. | | | | | | | |
| nspect | or Signature: | | o-zo-z/ ate: | Manager Signature: Date: | | | | | | | |