Unit Number: B 8805

Unit Location: Anona ES.

Ollit	Number: B 8809	MACH AS				Unit Location: Anona ES.	inspection Date:	8/23/22
Insp	ected By: John H. I	3oryc	ens			License Number: BN 7352		
Line	Inspection Criteria		Condi	tion				
#		New	Good	Fair	Poor	Inspection Comme		
1	Pier and foundations (Show Location on Back)		\boxtimes					
2	Tie downs and Anchors (Show Location on Back)		\boxtimes					
3	Set Backs (Between Units and from property)		\boxtimes					
4	Steps and Ramps		\boxtimes			Aluminum		
5	Means of Egress		\boxtimes				¥	
6	Structural Integrity		\boxtimes					
7	Roof Trusses							
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Modified		
9	Exterior Walls/Siding		\boxtimes			T 111		
10	Exterior Lighting (note if any)		\boxtimes					
11	Interior Walls and Covering					Paneling		
12	Doors/Windows/ Hardware							
13	Floors/Carpet/Tile Type and Condition							

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			· · · · · · · · · · · · · · · · · · ·
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				•
28	Plumbing/Fixtures					N/A
						. 48%

Line #	Inspection Criteria	Yes	ndition No	Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes	
30	Technology Capable	\boxtimes		
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted	\boxtimes		
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes	
34	What grade level or usage is unit?	3rd Grade		
				Additional Comments/Observations
7				

8-23-12 Date:

Manager Signature:

9/19/22

Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8935 Unit Location: Anona ES. Inspection Date: 8/23/22 Inspected By: John H. Borycens License Number: BN 7352 Line **Inspection Criteria** Condition # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \times (Show Location on Back) Set Backs (Between Units X 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity 6 \boxtimes Roof Trusses \boxtimes Roof Covering (Note type \boxtimes Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and X Paneling Covering Doors/Windows/ \boxtimes Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)	antile bensulation				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			s _u e
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				•
28	Plumbing/Fixtures					N/A
						÷ 114°

Line #	Inspection Criteria	Yes	ndition No	Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes	
30	Technology Capable			
31	Occupancy Certificate Posted in Unit	\boxtimes		
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes	
34	What grade level or usage is unit?	3rd Gra	ade	
				Additional Comments/Observations
	igr			
111				
_	1			

<u>⊗-23-22</u> Date:

Manager Signature:

Unit Number: B 9119

Unit Location: Anona ES.

Inspe	ected By: John H. E	Boryc	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
		New	Good	Fair	Poor	inspection Continents
1	Pier and foundations (Show Location on Back)		\boxtimes			
2	Tie downs and Anchors (Show Location on Back)		\boxtimes			
3	Set Backs (Between Units and from property)		\boxtimes			
4	Steps and Ramps					Aluminum
5	Means of Egress		\boxtimes			
6	Structural Integrity		\boxtimes			
7	Roof Trusses		\boxtimes			
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Modified
9	Exterior Walls/Siding					T111
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering					Paneling
12	Doors/Windows/ Hardware		\boxtimes			
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line #	Inspection Criteria	New	Condi	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes		
16	Weatherproofing (List Deficiencies)		\boxtimes		
17	HVAC		\boxtimes		Bard
18	Electrical Receptacles		\boxtimes		
19	Distribution Panel (labeled Correctly)		\boxtimes		Westing House
20	Emergency Lighting		\boxtimes		
21	Interior Light Fixtures (tied to structure)		\boxtimes		
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes		
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes		
24	Heat Detector/Smoke Detector in Classroom		\boxtimes		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)				in attic
26	Intercom system		\boxtimes		
27	Fire Extinguisher (Tagged and Current)				
28	Plumbing/Fixtures				N/A

Line #	Inspection Criteria	Yes	ndition No		36 34 3 32 3 12 11			Inspection	Comments			
29	Is unit in 100-year flood plain?		\boxtimes							e.		
30	Technology Capable	\boxtimes							1			
31	Occupancy Certificate Posted in Unit	\boxtimes			8							
32	Local Agency Reports Posted			(9)								
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes									
34	What grade level or usage is unit?	4th Gra	ade									
						Additional Co	omments/Ol	bservations				
									=			
												_
												_
	2											_
			<i>3-</i> 23	`-77 .			0	100.		0/0	/re	_
spect	or Signature:		ate:				Man	ager Signature:		Date:	122	

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9209 Unit Location: Anona ES. Inspection Date: 8/23/22 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** Fair New Good Poor Pier and foundations \times (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes Means of Egress Structural Integrity \boxtimes 6 **Roof Trusses** X Roof Covering (Note type \times 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if 10 X any) Interior Walls and X Paneling Covering Doors/Windows/ \boxtimes 12 Hardware

Floors/Carpet/Tile Type

and Condition

13

 \boxtimes

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		8
34	What grade level or usage is unit?	Other		Music	
					Additional Comments/Observations

8-23-22 Date:

Manager Signature:

Unit Number: B 9847

Unit Location: Anona ES

Inspe	ected By: John H. I	3oryc	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
Eresti.		New	Good	Fair	Poor	inspection comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress		\boxtimes			
6	Structural Integrity		\boxtimes			
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber
9	Exterior Walls/Siding					Metal
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering					Vinyl covered drywall
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria Condition			Inspection Comments		
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition	Inspection Comments
#		Yes	No	
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted	\boxtimes		
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	4th Gra	ade	*
		il and a second		Additional Comments/Observations
	-			
~				

Manager Signature:

9/19/22

Unit Number: BR 0424 Unit Location: Anona ES Inspection Date: 8/23/22

Insp	ected By: John H. E	3oryc	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		
		New	Good	Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)		\boxtimes			
2	Tie downs and Anchors (Show Location on Back)		\boxtimes			
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress					
6	Structural Integrity					
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Rubber
9	Exterior Walls/Siding		\boxtimes			Metal
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering		\boxtimes			Vinyl covered drywall
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line	Inspection Criteria		Condi	ition	MARKE	Inspection Comments
#	The state of the s	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		*
34	What grade level or usage is unit?	4th Grade	
		Sale Sale Sale Sale Sale Sale Sale Sale	Additional Comments/Observations
		=	

7	1		* *

8-23-22

Manager Signature:

Unit Number: BR 1317

Unit Location: Anona ES

Inspe	ected By: John H. E	Boryc	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
		New	Good	Fair	Poor	inspection Confinents
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Concrete side walks
5	Means of Egress					
6	Structural Integrity		\boxtimes			
7	Roof Trusses		\boxtimes			
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Rubber
9	Exterior Walls/Siding		\boxtimes			Hardy board
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering					Vinyl covered drywall
12	Doors/Windows/ Hardware		\boxtimes			
13	Floors/Carpet/Tile Type and Condition					

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes		
16	Weatherproofing (List Deficiencies)				
17	HVAC				Bard
18	Electrical Receptacles		\boxtimes		
19	Distribution Panel (labeled Correctly)		\boxtimes		Square D panel and labeled
20	Emergency Lighting		\boxtimes		
21	Interior Light Fixtures (tied to structure)		\boxtimes		
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes		
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes		
24	Heat Detector/Smoke Detector in Classroom		\boxtimes		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)				in attic
26	Intercom system		\boxtimes		
27	Fire Extinguisher (Tagged and Current)				
28	Plumbing/Fixtures				This unit has a restroom

Line	Inspection Criteria	Co	ndition	Inspection Comments
#		Yes	No	
29	Is unit in 100-year flood plain?		\boxtimes	
30	Technology Capable	\boxtimes		
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted	\boxtimes		
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes	
34	What grade level or usage is unit?	2nd Gr	ade	
			96 SE 1646	Additional Comments/Observations
	This is what we call a pe	ermanen	t portable that I	has a foundation and concrete sidewalks
es				
_	1			

8-23-22 Date:

Manager Signature:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: BR 1318 Unit Location: Anona ES Inspection Date: 8/23/22

Inspected By: John H. Borycens License Number: BN 7352 Line **Inspection Criteria** Condition **Inspection Comments** # Poor Good Fair New Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes Steps and Ramps 4 Concrete side walks \boxtimes 5 Means of Egress Structural Integrity 6 M Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding X 9 Hardy board Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type 13 and Condition

Line	Inspection Criteria	- Contrait	Condition		144	Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel and labeled
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line	Inspection Criteria	Co	ndition	Inspection Comments
#		Yes	No	
29	Is unit in 100-year flood plain?			
30	Technology Capable	\boxtimes		
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes	
34	What grade level or usage is unit?	2nd G	rade	
				Additional Comments/Observations
	This is what we call a pe	ermanen	t portable that	has a foundation and concrete sidewalks
	1			

<u>8-23-22</u> Date:

Manager Signature:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: BR 1319

Unit Location: Anona ES

Inspe	ected By: John H. E	3oryc	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		
		New	Good	Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					,
2	Tie downs and Anchors (Show Location on Back)		\boxtimes			
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Concrete side walks
5	Means of Egress		\boxtimes			
6	Structural Integrity		\boxtimes			
7	Roof Trusses		\boxtimes			
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Rubber
9	Exterior Walls/Siding		\boxtimes			Hardy board
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering		\boxtimes			Vinyl covered drywall
12	Doors/Windows/ Hardware		\boxtimes			
13	Floors/Carpet/Tile Type and Condition					

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes		
16	Weatherproofing (List Deficiencies)		\boxtimes		
17	HVAC		\boxtimes		Bard
18	Electrical Receptacles		\boxtimes		
19	Distribution Panel (labeled Correctly)		\boxtimes		Square D panel and labeled
20	Emergency Lighting		\boxtimes		
21	Interior Light Fixtures (tied to structure)		\boxtimes		
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes		
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes		
24	Heat Detector/Smoke Detector in Classroom		\boxtimes		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes		in attic
26	Intercom system		\boxtimes		
27	Fire Extinguisher (Tagged and Current)				
28	Plumbing/Fixtures		\boxtimes		This unit has a restroom

Line #	Inspection Criteria		ndition No	Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes	
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes	
34	What grade level or usage is unit?	2nd Gr	ade	
				Additional Comments/Observations
	This is what we call a pe	ermanen	t portable that	has a foundation and concrete sidewalks
1				

8-23-22 Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 1320 Unit Location: Anona ES Inspection Date: 8/23/22 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations (Show Location on Back) Tie downs and Anchors X (Show Location on Back) Set Backs (Between Units X 3 and from property) \times 4 Steps and Ramps Concrete side walks \boxtimes 5 Means of Egress Structural Integrity 6 \boxtimes Roof Trusses \boxtimes Roof Covering (Note type X 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding 9 X Hardy board Exterior Lighting (note if \boxtimes 10 any) Interior Walls and 11 \boxtimes Vinyl covered drywall Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes		
16	Weatherproofing (List Deficiencies)		\boxtimes		
17	HVAC		\boxtimes		Bard
18	Electrical Receptacles		\boxtimes		
19	Distribution Panel (labeled Correctly)				Square D
20	Emergency Lighting		\boxtimes		
21	Interior Light Fixtures (tied to structure)				
22	Fire Alarm (Strobes, Horn, Pull Stations)				
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes		
24	Heat Detector/Smoke Detector in Classroom		\boxtimes		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes		in attic
26	Intercom system				
27	Fire Extinguisher (Tagged and Current)				
28	Plumbing/Fixtures .				This unit has a restroom

Line #	Inspection Criteria Is unit in 100-year flood plain?	Cor Yes	ndition No	Inspection Comments						
29			\boxtimes							
30	Technology Capable									
31	Occupancy Certificate Posted in Unit									
32	Local Agency Reports Posted									
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes							
34	What grade level or usage is unit?	2nd Gra	ade							
				Additional Comments/Observations						
			and the second s							
	This is what we call a permanent portable that has a foundation and concrete sidewalks									
			*							
			Y							

8-23-22 Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 1321

Unit Location: Anona ES

Inspection Date:

8/23/22

Inspected By: John H. Borycens						License Number: BN 7352
Line #	Inspection Criteria	Condition				Inspection Comments
		New	Good	Fair	Poor	inspection confinents
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Concrete side walks
5	Means of Egress					
6	Structural Integrity					
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber
9	Exterior Walls/Siding					Hardy board
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering					Vinyl covered drywall
12	Doors/Windows/ Hardware		\boxtimes			
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments						
29	Is unit in 100-year flood plain?								
30	Technology Capable								
31	Occupancy Certificate Posted in Unit								
32	Local Agency Reports Posted								
33	Does unit have any known Environmental factors? If yes, Explain.								
34	What grade level or usage is unit?	2nd Grade							
			Additional Comments/Observations						
	This is what we call a permanent portable that has a foundation and concrete sidewalks								
		Ψ							
	1								

<u>8-23-22</u> Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: **BR 1322** Unit Location: Anona ES Inspection Date: 8/23/22 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** New Good Fair **Poor** Pier and foundations 1 (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Concrete side walks \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type X Rubber Shingles, Veral, etc.) Exterior Walls/Siding X 9 Hardy board Exterior Lighting (note if X 10 any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes		
16	Weatherproofing (List Deficiencies)		\boxtimes		
17	HVAC		\boxtimes		Bard
18	Electrical Receptacles		\boxtimes		
19	Distribution Panel (labeled Correctly)		\boxtimes		Square D
20	Emergency Lighting		\boxtimes		
21	Interior Light Fixtures (tied to structure)		\boxtimes		
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes		
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes		
24	Heat Detector/Smoke Detector in Classroom				
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes		in attic
26	Intercom system		\boxtimes		
27	Fire Extinguisher (Tagged and Current)	\boxtimes			
28	Plumbing/Fixtures				This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments			
29	Is unit in 100-year flood plain?					
30	Technology Capable					
31	Occupancy Certificate Posted in Unit					
32	Local Agency Reports Posted					
33	Does unit have any known Environmental factors? If yes, Explain.					
34	What grade level or usage is unit?	2nd Grade				
			Additional Comments/Observations			
	This is what we call a pe	ermanent portable that has	a foundation and concrete sidewalks			
	1					

B-23-22 Date:

Manager Signature:

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: ER 8959

Unit Location: Anona ES.

Inspe	ected By: John H. E	Boryc	ens			License Number: BN 7352
Line #	Inspection Criteria	(Angalija)	Condi	tion		
		New	Good	Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)		\boxtimes			
4	Steps and Ramps		\boxtimes			Aluminum
5	Means of Egress		\boxtimes			
6	Structural Integrity		\boxtimes			
7	Roof Trusses		\boxtimes			
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Modified
9	Exterior Walls/Siding		\boxtimes			T 111
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering		\boxtimes			Paneling
12	Doors/Windows/ Hardware		\boxtimes			
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					This unit has a restroom

Line	Inspection Criteria	Coi	ndition		Inspection Comments
#	100 May 100 Ma	Yes	No		
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit	\boxtimes		-	
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		Mus	sic
					Additional Comments/Observations
	*				

<u>8-23-22</u> Date:

Manager Signature:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: LR 0645

Unit Location: Anona ES.

Insp	ected By: John H. I	3oryc	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		
		New	Good	Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)		\boxtimes			
4	Steps and Ramps		\boxtimes			Aluminum
5	Means of Egress		\boxtimes			
6	Structural Integrity		\boxtimes			
7	Roof Trusses		\boxtimes			
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified
9	Exterior Walls/Siding					Metal
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering					Vinyl covered drywall
12	Doors/Windows/ Hardware		\boxtimes			
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line	Inspection Criteria	illum.	Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition	Inspection Comments
		Yes No	
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	
			Additional Comments/Observations

8-23-22 Date:

Manager Signature:

9/19/22 Date:

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: LR 0657

Unit Location: Anona ES.

Inspe	ected By: John H. I	Boryc	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		
		New	Good	Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps		\boxtimes			Aluminum
5	Means of Egress		\boxtimes			
6	Structural Integrity		\boxtimes			
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Modified
9	Exterior Walls/Siding					Metal
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering		\boxtimes			Vinyl covered drywall
12	Doors/Windows/ Hardware		\boxtimes			*
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line #	Inspection Criteria		Cond			Inspection Comments
	Haraca and the second	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					This unit has a restroom

Line	Inspection Criteria	Co	ndition		Inspection Comments
#		Yes	No		
29	Is unit in 100-year flood plain?		\boxtimes		¥
30	Technology Capable				
31	Occupancy Certificate Posted in Unit	\boxtimes			
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		ОТ/РТ	
				Additional Comm	ents/Observations
\cap	/				

<u> 8 - 23 - ZZ</u> Date:

Manager Signature:

9/19/22 ate:

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: LR 0829 Unit Location: Anona ES Inspection Date: 8/23/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations 1 (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 Metal Exterior Lighting (note if 10 \boxtimes any) Interior Walls and \boxtimes 11 Vinyl covered drywall Covering Doors/Windows/ \boxtimes Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel and labeled
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes		3	
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No	Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes	
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes	
34	What grade level or usage is unit?	4th Gra	ade	
				Additional Comments/Observations
_	1			

Manager Signature:

9/19/22 Date:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: LR 0830

Unit Location: Anona ES

Inspe	ected By: John H. E	3oryc	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
		New	Good	Fair	Poor	inspection comments
1	Pier and foundations (Show Location on Back)		\boxtimes			
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps		\boxtimes			Aluminum
5	Means of Egress		\boxtimes			
6	Structural Integrity		\boxtimes			
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Rubber
9	Exterior Walls/Siding		\boxtimes			Metal
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering		\boxtimes			Vinyl covered drywall
12	Doors/Windows/ Hardware					4
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line	Inspection Criteria	Condition				Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			*
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	4th Grade	
			Additional Comments/Observations
	1		
	2		

Manager Signature: