Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B7909 Unit Location: Bauder ES. Inspection Date: 8/25/22 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** Good Fair New Poor Pier and foundations (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property) 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ 7 Roof Covering (Note type  $\boxtimes$ 8 Shingles Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/ 12  $\boxtimes$ Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A
						>

Line #	Inspection Criteria	4 1 1 1 1 1 1 1 1	ndition		Inspection Comments
		Yes	No		
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$		
34	What grade level or usage is unit?	Other		Art	
					Additional Comments/Observations

8-25-22 Date:

Manager Signature:

9/20/22 Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B8803 Unit Location: Bauder ES. Inspection Date: 8/25/22 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition **Inspection Comments** # New Good Fair Poor Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type X 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ Hardware Floors/Carpet/Tile Type  $\boxtimes$ and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition	Inspection Comments			
#		Yes No	[문화사이] [122] - 이 이 생물보이 이 기구로 이 그 경우는 이 그 경우 보이 이 기급하여 이 기계를 보이 되어 가장되었다. 이 그렇게 되는 이 기급을 보이 그 것도 되었다. 이 그 것도 하 [17] 이 기급 (14) 이 이 경영화의 이 기급을 보이 기급을 보이 기급을 보이 기급을 보이 기급을 보이 기급을 보이 되었다.			
29	Is unit in 100-year flood plain?					
30	Technology Capable					
31	Occupancy Certificate Posted in Unit					
32	Local Agency Reports Posted					
33	Does unit have any known Environmental factors? If yes, Explain.					
34	What grade level or usage is unit?	Other	Science			
		The state of the	Additional Comments/Observations			
	,i					
~	1					

8-25-22 Date:

Manager Signature:

9/20/22 te:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B9124 **Unit Location:** Inspection Date: 8/25/22 Bauder ES. Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations  $\times$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units 3  $\boxtimes$ and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity X 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding 9  $\bowtie$ T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and Paneling Covering Doors/Windows/  $\boxtimes$ Hardware Floors/Carpet/Tile Type  $\boxtimes$ 

13

and Condition

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					NA

Line #	Inspection Criteria	Conditio Yes No		Inspection Comments			
29	Is unit in 100-year flood plain?		348539				
30	Technology Capable						
31	Occupancy Certificate Posted in Unit						
32	Local Agency Reports Posted						
33	Does unit have any known Environmental factors? If yes, Explain.						
34	What grade level or usage is unit?	Other	Pre K				
		Additional Comments/Observations					
			) <b>*</b>				
			9				
1	1						

<u>8-25 - 2</u> Date:

Manager Signature:

9/20/22 Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Inspection Date: 8/25/22 Unit Location: Bauder ES. B9322 **Unit Number:** License Number: BN 7352 Inspected By: John H. Borycens Condition **Inspection Criteria** Line **Inspection Comments** # Fair Poor New Good Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Aluminum Steps and Ramps  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ 7 Roof Covering (Note type  $\boxtimes$ Modified 8 Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ T 111 9 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and Paneling 11 Covering Doors/Windows/ X 12 Hardware Floors/Carpet/Tile Type X 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting				X	Emergency light not working
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No	Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$	
30	Technology Capable	$\boxtimes$		
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted	$\boxtimes$		
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
	Work order for the eme	rgency lig	ght # 143158	
	-			
	1		Y	

Manager Signature:

9/20/22

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B9565 Unit Location: Bauder ES. Inspection Date: 8/25/22 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** Fair Poor New Good Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property) X 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity X 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if X 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition	Inspection Comments	
#		Yes	No		
29	Is unit in 100-year flood plain?		$\boxtimes$		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				-
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other			
				Additional Comments/Observations	
1	1				

<u>8-25-22</u> Date:

Manager Signature:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Inspection Date: 8/25/22 Unit Number: B9701 Unit Location: Bauder ES. License Number: Inspected By: John H. Borycens BN 7352 Inspection Criteria Condition Line **Inspection Comments** # Good Fair Poor New Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\times$ 2 (Show Location on Back) Set Backs (Between Units X 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity X 6 **Roof Trusses** X Roof Covering (Note type X Modified 8 Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and  $\times$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type 13 and Condition

Line	Inspection Criteria		Condi	tion	- 1000 a	Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Condition	Inspection Comments
#		Yes No	
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	
			Additional Comments/Observations
		2	
		1	
	,		

8-25-22 Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

1	Pier and foundations (Show Location on Back)			
2	Tie downs and Anchors (Show Location on Back)	$\boxtimes$		
3	Set Backs (Between Units and from property)	$\boxtimes$		
4	Steps and Ramps	$\boxtimes$		Aluminum
5	Means of Egress	$\boxtimes$		
6	Structural Integrity	$\boxtimes$		
7	Roof Trusses	$\boxtimes$		
8	Roof Covering (Note type Shingles, Veral, etc.)	$\boxtimes$		Modified
9	Exterior Walls/Siding	$\boxtimes$		T 111
10	Exterior Lighting (note if any)	$\boxtimes$		
11	Interior Walls and Covering	$\boxtimes$		Paneling
12	Doors/Windows/ Hardware			
13	Floors/Carpet/Tile Type and Condition	$\boxtimes$		

Line #	Inspection Criteria		Cond			Inspection Comments
#	THE PROPERTY OF THE PARTY OF	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC					Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Cond Yes 1	tion lo	Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$	
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$	
34	What grade level or usage is unit?	Other	·	
				Additional Comments/Observations
		W 1		
_	_			

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

**Unit Number:** B9815 Unit Location: Bauder ES. Inspection Date: 8/25/22 Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and X Paneling Covering Doors/Windows/  $\boxtimes$ Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	K-5
			Additional Comments/Observations
-			
1	$\sim$	Net T	

8-25-22 Date:

Manager Signature:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

**Unit Number:** BR9407 Unit Location: Bauder ES. Inspection Date: 8/25/22

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria	New	Condi	tion Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)		$\boxtimes$			
2	Tie downs and Anchors (Show Location on Back)		$\boxtimes$			
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress					
6	Structural Integrity					
7	Roof Trusses		$\boxtimes$			
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified
9	Exterior Walls/Siding					T 111
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering					Paneling
12	Doors/Windows/ Hardware		$\boxtimes$			
13	Floors/Carpet/Tile Type and Condition					

Line #	Inspection Criteria	New	Condi Good	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)				
16	Weatherproofing (List Deficiencies)		$\boxtimes$		
17	HVAC				Bard
18	Electrical Receptacles				
19	Distribution Panel (labeled Correctly)		$\boxtimes$		Square D panel
20	Emergency Lighting				
21	Interior Light Fixtures (tied to structure)				
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$		
23	Heat Detector/Smoke Detector in Storage Spaces				
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$		
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$		in attic
26	Intercom system				
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$			
28	Plumbing/Fixtures				This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		Pre K	
					Additional Comments/Observations
	(4)				
	,				
	1				

Manager Signature:

Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

**Unit Number: BR9709** Unit Location: Bauder ES. Inspection Date: 8/25/22 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition **Inspection Comments** # New Good Fair Poor Pier and foundations  $\times$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units X 3 and from property) X 4 Steps and Ramps Aluminum X Means of Egress Structural Integrity 6 X Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if 10 any) Interior Walls and  $\boxtimes$ 11 Paneling Covering Doors/Windows/  $\boxtimes$ Hardware Floors/Carpet/Tile Type 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)			Daniel III		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria  Is unit in 100-year flood plain?	Co Yes	ndition No		Inspection Comments
29					ON COLOR TRANSPORTED TO A MEDICAL COLOR OF THE COLOR OF T
30	Technology Capable	$\boxtimes$			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		Music	
					Additional Comments/Observations
			90000		
			-		

8-25-22 Date:

Manager Signature:

9/20/22

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: BRK 9133 Unit Location: Bauder ES. Inspection Date: 8/25/22

Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** New Good Fair Poor Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type 8  $\boxtimes$ Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if 10  $\boxtimes$ any) Interior Walls and  $\boxtimes$ Paneling Covering Doors/Windows/ X 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria		Condition		11.1	Inspection Comments
#	10777	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)					Westinghouse
20	Emergency Lighting				$\boxtimes$	Emergency light not working
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					This unit has a restroom

Line	Inspection Criteria	Co	ndition		Inspection Comments
#		Yes	No		
29	Is unit in 100-year flood plain?				
30	Technology Capable	$\boxtimes$			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		Pre K	
				Additi	onal Comments/Observations
			20-0-100-0-100		
	work order for the emer	gency lig	ht # 143142	2	
	<i>y</i>				
		-			
_					
11	1				

8-25-27 Date:

Manager Signature:

9/20/22 Date:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: ER8908 Unit Location: Bauder ES. Inspection Date: 8/25/22

Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 **Roof Trusses** Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if 10  $\boxtimes$ any) Interior Walls and Paneling Covering Doors/Windows/ 12  $\boxtimes$ Hardware Floors/Carpet/Tile Type 13 and Condition

Line #	Inspection Criteria	Condition New Good Fair Poor		Poor	Inspection Comments	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	Pre K
			Additional Comments/Observations
		4	
		. E.	
	1		

8-25-77 Date:

Manager Signature:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: ERK 9129 Unit Location: Bauder ES. Inspection Date: 8/25/22

BN 7352 Inspected By: John H. Borycens License Number: **Inspection Criteria** Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations  $\times$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses X Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if 10  $\boxtimes$ any) Interior Walls and 11 X Paneling Covering Doors/Windows/ X 12 Hardware Floors/Carpet/Tile Type 13  $\boxtimes$ and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Westinghouse
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom
						*

Line #	Inspection Criteria		dition		Inspection Comments			
		Yes	No					
29	Is unit in 100-year flood plain?		$\boxtimes$					
30	Technology Capable							
31	Occupancy Certificate Posted in Unit							
32	Local Agency Reports Posted							
33	Does unit have any known Environmental factors? If yes, Explain.							
34	What grade level or usage is unit?	Other		Pre K				
					Additional Comments/Observations			
			×					
					·			
1								

<u> 8-25-22</u> Date:

Manager Signature:

<u>9/2/22</u> Date:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: ERK 9130

Unit Location: Bauder ES.

Inspection Date: 8/25/22

Inspected By: John H. Borycens						License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
1 10 T 10 T		New	Good	Fair	Poor	inspection comments
1	Pier and foundations (Show Location on Back)		$\boxtimes$			
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress					
6	Structural Integrity					
7	Roof Trusses		$\boxtimes$			
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified
9	Exterior Walls/Siding		$\boxtimes$			T 111
10	Exterior Lighting (note if any)		$\boxtimes$			
11	Interior Walls and Covering		$\boxtimes$			Paneling
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Condition			Inspection Comments
#	g* a	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			-
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Westinghouse
20	Emergency Lighting		$\boxtimes$			Emergency light not working
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line	Inspection Criteria	Co	ndition	Inspection Comments					
#		Yes	No						
29	Is unit in 100-year flood plain?								
30	Technology Capable								
31	Occupancy Certificate Posted in Unit								
32	Local Agency Reports Posted								
33	Does unit have any known Environmental factors? If yes, Explain.								
34	NAME of social level and		***************************************	Pre K					
				Additional Comments/Observations					
			8						
	Work order for the eme	rgency li	ght #14314						
	,								
		2		2					
$\overline{}$									

Manager Signature:

9/20/22 Date: