Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BO 0567 Unit Location:

Unit Location: Bay Side HS..

Inspection Date: 9/20/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition **Inspection Comments** New Good Fair Poor Pier and foundations \times (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \times 4 Steps and Ramps Aluminum \times 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 X Metal Exterior Lighting (note if 10 \boxtimes any) Interior Walls and 11 X Plaster Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type 13 X and Condition

Line #	Inspection Criteria		Condi			Inspection Comments
*		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			GE panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	
			Additional Comments/Observations
		1	
			* *
7	1		

<u>9-20-22</u> Date:

Manager Signature:

Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BO 0568 Unit Location: Bay Side HS. Inspection Date: 9/20/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses 7 \boxtimes Roof Covering (Note type 8 \boxtimes Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 \boxtimes Aluminum Exterior Lighting (note if 10 \boxtimes any) Interior Walls and 11 X Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		\boxtimes			GE panel
20	Emergency Lighting				\boxtimes	Emergency light is not working
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No	Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes	
30	Technology Capable	\boxtimes		
31	Occupancy Certificate Posted in Unit	\boxtimes		
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes	
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
	Work order number for	the eme	rgency light #1	45951
^		V=		

<u>9-20-22</u> Date:

Manager Signature:

Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BO 0569 Unit Location: Bay Side HS. Inspection Date: 9/20/22

BN 7352 License Number: Inspected By: John H. Borycens Condition **Inspection Criteria** Line **Inspection Comments** # Poor New Good Fair Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors X (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \times 4 Aluminum Steps and Ramps \boxtimes 5 Means of Egress Structural Integrity X 6 Roof Trusses X Roof Covering (Note type X 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 Aluminum Exterior Lighting (note if X 10 any) Interior Walls and X 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type 13 X and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			GE panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Con Yes	dition No	Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes	
30	Technology Capable	\boxtimes		
31	Occupancy Certificate Posted in Unit	\boxtimes		
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes	
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
2				

9-20-22 Date:

Manager Signature:

Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 8408 Unit Location: Bay Side HS.. Inspection Date: 9/20/22

Inspected By: John H. Borycens License Number: BN 7352 Condition **Inspection Criteria** Line # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) X 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses X Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T111 Exterior Lighting (note if 10 X any) Interior Walls and X 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line #	Inspection Criteria		Cond			Inspection Comments
		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes		2.	GE panel
20	Emergency Lighting		\boxtimes			*
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	1	Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
\sim	1			

<u>9-20-22</u> Date:

Manager Signature:

10/11/22

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 9326 Unit Location: Bay Side HS. Inspection Date: 9/20/22

License Number: BN 7352 Inspected By: John H. Borycens Condition Inspection Criteria Line **Inspection Comments** # New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors X 2 (Show Location on Back) Set Backs (Between Units X 3 and from property) X 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity 6 \boxtimes Roof Trusses \times Roof Covering (Note type X 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 X T111 Exterior Lighting (note if 10 X any) Interior Walls and \times 11 Kemlite Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					7
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	
		ng Pakan Bwene ng palaman 110	Additional Comments/Observations
X		4	

Date:

Manager Signature:

10/11/22

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BRN 9306 Unit Location: Bay Side HS . **Inspection Date:** 9/20/22 License Number: Inspected By: John H. Borycens BN 7352 **Inspection Criteria** Condition Line **Inspection Comments** # Fair New Good Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity \times 6 Roof Trusses \boxtimes Roof Covering (Note type 8 \boxtimes Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T111 Exterior Lighting (note if 10 \boxtimes any) Interior Walls and 11 \times Kemlite Covering Doors/Windows/ X 12 Hardware

Floors/Carpet/Tile Type

and Condition

13

X

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	
			Additional Comments/Observations
		+	
	1		
_	1		

9-20-22 Date:

Manager Signature:

10/11/2Z