Unit Number: A 8830

Unit Location: Blanton ES.

| Inspe | ected By: John H. E | Boryce | ens | | | License Number: BN 7352 |
|-----------|--|--------|-------------|------|------|-------------------------|
| Line # | Inspection Criteria | | Condi | tion | | |
| | | New | Good | Fair | Poor | Inspection Comments |
| 1 | Pier and foundations (Show Location on Back) | | \boxtimes | | | |
| 2 | Tie downs and Anchors (Show Location on Back) | | | | | |
| 3 | Set Backs (Between Units and from property) | | | | | |
| 4 | Steps and Ramps | | | | | Aluminum |
| 5 | Means of Egress | | \boxtimes | | | |
| 6 | Structural Integrity | | \boxtimes | | | |
| 7 | Roof Trusses | | | | | |
| 8 | Roof Covering (Note type Shingles, Veral, etc.) | | \boxtimes | | | Modified |
| 9 | Exterior Walls/Siding | | \boxtimes | | | T111 |
| 10 | Exterior Lighting (note if any) | | \boxtimes | | | |
| 11 | Interior Walls and Covering | | | | | Paneling |
| 12 | Doors/Windows/ Hardware | | | | | |
| 13 | Floors/Carpet/Tile Type and Condition | | | | | |

| Line # | Inspection Criteria | New | Cond Good | Poor | Inspection Comments |
|-----------|---|------|--------------|------|--|
| 14 | Ceilings/Tiles/Grid/ | INCW | | | The second of th |
| 17 | Wire Hangers (12ga) | Ш | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | | | |
| 16 | Weatherproofing (List Deficiencies) | | | | |
| 17 | HVAC | | \boxtimes | | Bard |
| 18 | Electrical Receptacles | | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | Square D panel |
| 20 | Emergency Lighting | | \boxtimes | | |
| 21 | Interior Light Fixtures (tied to structure) | | \boxtimes | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | \boxtimes | | in attic |
| 26 | Intercom system | | \boxtimes | | |
| 27 | Fire Extinguisher (Tagged and Current) | | | | |
| 28 | Plumbing/Fixtures | | | | N/A |
| | | | | | |

| Line # | Inspection Criteria | | ndition No | | F 23; 17 | Inspection Comments | |
|-----------|--|-------------|---------------|---|----------|----------------------------------|--|
| 29 | Is unit in 100-year flood plain? | | \boxtimes | | | | |
| 30 | Technology Capable | \boxtimes | | | | | |
| 31 | Occupancy Certificate Posted in Unit | | | | | | |
| 32 | Local Agency Reports Posted | \boxtimes | | | | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | | | | | |
| 34 | What grade level or usage is unit? | Other | | A | Alpha Pr | Program | |
| | hame h | | | | | Additional Comments/Observations | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | 3 | | | | |
| | | | | | | | |
| | | | | | æ | | |
| | 1 | | | | | | |
| | | | _ | | | | |

 $\frac{9 - /3 - 7Z}{\text{Date:}}$

Manager Signature:

Pinellas County Schools

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: A 8831 Unit Location: Blanton ES. Inspection Date: 9/13/22 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes 1 (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum 5 Means of Egress Structural Integrity 6 Roof Trusses \boxtimes Roof Covering (Note type Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 T111 Exterior Lighting (note if 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ 12 Hardware Floors/Carpet/Tile Type 13 and Condition

| Line # | Inspection Criteria | Condition | | | | Inspection Comments |
|-----------|---|-------------|-------------|------|-------------|------------------------|
| # | | New | Good | Fair | Poor | |
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | \boxtimes | | | |
| 16 | Weatherproofing (List Deficiencies) | | \boxtimes | | | |
| 17 | HVAC | | \boxtimes | | | Bard |
| 18 | Electrical Receptacles | | \boxtimes | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | | Square D panel |
| 20 | Emergency Lighting | | | | \boxtimes | Repair emergency light |
| 21 | Interior Light Fixtures (tied to structure) | | \boxtimes | | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | \boxtimes | | | in attic |
| 26 | Intercom system | | \boxtimes | | | |
| 27 | Fire Extinguisher (Tagged and Current) | \boxtimes | | | | |
| 28 | Plumbing/Fixtures | | | | | N/A |
| | | | | | | |

| Line | Inspection Criteria | Co | ndition | Inspection Comments |
|-----------------|--|-------------|---------------|----------------------------------|
| # | | Yes | No | |
| 29 | Is unit in 100-year flood plain? | | \boxtimes | |
| 30 | Technology Capable | | | |
| 31 | Occupancy Certificate Posted in Unit | | | |
| 32 | Local Agency Reports Posted | \boxtimes | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | \boxtimes | |
| 34 | What grade level or usage is unit? | Other | | Alpha Program |
| | | | | Additional Comments/Observations |
| | | | | |
| | , | | | |
| | | | | |
| | #20 work order for the e | mergeno | cy light 1450 | 7 |
| | | | | |
| | - | | | |
| | | | | |
| $\overline{\ }$ | 1 | | | |

 $\frac{9-13-22}{\text{Date:}}$

Manager Signature:

10/11/22

Pinellas County Schools

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: A 8832 Unit Location: Blanton ES. Inspection Date: 9/13/22

Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** Good Fair New Poor Pier and foundations \times (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \times 3 and from property) X 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses X Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes Paneling Covering Doors/Windows/ 12 Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

| Line | Inspection Criteria | | Condition | | | Inspection Comments |
|------|---|-------------|-------------|------|------|---------------------|
| # | | New | Good | Fair | Poor | |
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | \boxtimes | | | |
| 16 | Weatherproofing (List Deficiencies) | | \boxtimes | | | |
| 17 | HVAC | | \boxtimes | | | Bard |
| 18 | Electrical Receptacles | | \boxtimes | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | | Square D panel |
| 20 | Emergency Lighting | | \boxtimes | | | |
| 21 | Interior Light Fixtures (tied to structure) | | \boxtimes | | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | - | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | \boxtimes | | | in attic |
| 26 | Intercom system | | \boxtimes | | | |
| 27 | Fire Extinguisher (Tagged and Current) | \boxtimes | | | | |
| 28 | Plumbing/Fixtures | | | | | N/A |
| | 12.26 | | | | | |

| Line | Inspection Criteria | Condition | Inspection Comments | | | | | | |
|------|--|-----------|----------------------------------|--|--|--|--|--|--|
| # | | Yes No | | | | | | | |
| 29 | Is unit in 100-year flood plain? | | | | | | | | |
| 30 | Technology Capable | | | | | | | | |
| 31 | Occupancy Certificate Posted in Unit | | | | | | | | |
| 32 | Local Agency Reports Posted | | | | | | | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | | | | | | | |
| 34 | What grade level or usage is unit? | Other | Alpha Program | | | | | | |
| | | | Additional Comments/Observations | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Manager Signature:

Unit Number: B 0903

Unit Location: Blanton ES.

| Omit i | Aullinel. D 0303 | | | 36 (3) | 5- | Onit Location. Bianton Es. Inspection Date: 9/13/22 |
|--------|--|-------|-------------|--------|------|---|
| Inspe | ected By: John H. I | 3oryc | ens | | | License Number: BN 7352 |
| Line | Inspection Criteria | | Condi | tion | | |
| # | | New | Good | Fair | Poor | Inspection Comments |
| 1 | Pier and foundations (Show Location on Back) | | | | | |
| 2 | Tie downs and Anchors (Show Location on Back) | | \boxtimes | | | |
| 3 | Set Backs (Between Units and from property) | | | | | |
| 4 | Steps and Ramps | | \boxtimes | | | concrete walkways |
| 5 | Means of Egress | | \boxtimes | | | |
| 6 | Structural Integrity | | | | | 8 |
| 7 | Roof Trusses | | \boxtimes | | | |
| 8 | Roof Covering (Note type Shingles, Veral, etc.) | | \boxtimes | | | Rubber |
| 9 | Exterior Walls/Siding | | \boxtimes | | | hardie board |
| 10 | Exterior Lighting (note if any) | | | | | |
| 11 | Interior Walls and Covering | | \boxtimes | | | vinyl covered drywall |
| 12 | Doors/Windows/ Hardware | | \boxtimes | | | |
| 13 | Floors/Carpet/Tile Type and Condition | | | | | |

| Line | Inspection Criteria | | Condition | | | Inspection Comments |
|------|---|-------------|-------------|------|------|---------------------|
| # | | New | Good | Fair | Poor | |
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | | | | |
| 16 | Weatherproofing (List Deficiencies) | | \boxtimes | | | |
| 17 | HVAC | | \boxtimes | | | Bard |
| 18 | Electrical Receptacles | | | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | | Square D panel |
| 20 | Emergency Lighting | | \boxtimes | | | |
| 21 | Interior Light Fixtures (tied to structure) | | \boxtimes | | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | \boxtimes | | | in attic |
| 26 | Intercom system | | \boxtimes | | | |
| 27 | Fire Extinguisher (Tagged and Current) | \boxtimes | | | | |
| 28 | Plumbing/Fixtures | | | | | N/A |
| | | | | | | |

| Line # | Inspection Criteria | Yes | ndition No | | Inspection Comments |
|-----------|--|-------------|---------------|-----------------------|----------------------------------|
| 29 | Is unit in 100-year flood plain? | | \boxtimes | | |
| 30 | Technology Capable | | | | |
| 31 | Occupancy Certificate Posted in Unit | | | | |
| 32 | Local Agency Reports Posted | \boxtimes | | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | \boxtimes | | |
| 34 | What grade level or usage is unit? | Other | | K-5 | |
| | | | 2 may | l _a ethgas | Additional Comments/Observations |
| | | | | | |
| | | | | | |
| | i a | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 7 | | | | | |

9-13-22 Date:

Manager Signature:

10/11/22 Date:

Unit Number: B 0904

Unit Location: Blanton ES.

| Inspe | ected By: John H. E | Boryc | ens | | | License Number: BN 7352 |
|-----------|--|-------|-------------|------|------|-------------------------|
| Line # | Inspection Criteria | | Condition | | | Inspection Comments |
| | | New | Good | Fair | Poor | Inspection Comments |
| 1 | Pier and foundations (Show Location on Back) | | | | | |
| 2 | Tie downs and Anchors (Show Location on Back) | | | | | |
| 3 | Set Backs (Between Units and from property) | | | | | |
| 4 | Steps and Ramps | | | | | concrete walkways |
| 5 | Means of Egress | | | | | |
| 6 | Structural Integrity | | | | | |
| 7 | Roof Trusses | | | | | |
| 8 | Roof Covering (Note type Shingles, Veral, etc.) | | | | | Rubber |
| 9 | Exterior Walls/Siding | | | | | hardie board |
| 10 | Exterior Lighting (note if any) | | | | | |
| 11 | Interior Walls and Covering | | \boxtimes | | | vinyl covered drywall |
| 12 | Doors/Windows/ Hardware | | | | | |
| 13 | Floors/Carpet/Tile Type and Condition | | | | | |

| Line | Inspection Criteria | 1000 | Cond | ition | | Inspection Comments |
|------|---|-------------|-------------|-------|------|---------------------|
| # | | New | Good | Fair | Poor | |
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | | | | |
| 16 | Weatherproofing (List Deficiencies) | | \boxtimes | | | |
| 17 | HVAC | | | | | Bard |
| 18 | Electrical Receptacles | | \boxtimes | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | | Square D panel |
| 20 | Emergency Lighting | | \boxtimes | | | |
| 21 | Interior Light Fixtures (tied to structure) | | \boxtimes | | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | \boxtimes | | | in attic |
| 26 | Intercom system | | \boxtimes | | | |
| 27 | Fire Extinguisher (Tagged and Current) | \boxtimes | | | | |
| 28 | Plumbing/Fixtures | | | | | N/A |
| | | | | | | |

| Line # | Inspection Criteria | Condition | Inspection Comments | | | | | |
|-----------|--|-----------|----------------------------------|--|--|--|--|--|
| # | | Yes No | | | | | | |
| 29 | Is unit in 100-year flood plain? | | | | | | | |
| 30 | Technology Capable | | | | | | | |
| 31 | Occupancy Certificate Posted in Unit | | | | | | | |
| 32 | Local Agency Reports Posted | | | | | | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | | | | | | |
| 34 | What grade level or usage is unit? | Other | K-5 | | | | | |
| | | | Additional Comments/Observations | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | 2 | * | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

9-/3-27 Date:

Manager Signature:

Date:

Pinellas County Schools

Relocatable Classroom Inspection Certificate

(Yearly Inspection Report) Inspection Date: 9/13/22 Unit Number: B 0905 Unit Location: Blanton ES. License Number: Inspected By: John H. Borycens BN 7352 Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back)

| 2 | Tie downs and Anchors (Show Location on Back) | | | | |
|----|--|-------------|---|---|-----------------------|
| 3 | Set Backs (Between Units and from property) | \boxtimes | | | |
| 4 | Steps and Ramps | \boxtimes | | | concrete walkways |
| 5 | Means of Egress | \boxtimes | | | |
| 6 | Structural Integrity | \boxtimes | | | |
| 7 | Roof Trusses | \boxtimes | | | |
| 8 | Roof Covering (Note type Shingles, Veral, etc.) | \boxtimes | | | Rubber |
| 9 | Exterior Walls/Siding | \boxtimes | | | hardie board |
| 10 | Exterior Lighting (note if any) | \boxtimes | | | |
| 11 | Interior Walls and Covering | \boxtimes | | | vinyl covered drywall |
| 12 | Doors/Windows/ Hardware | \boxtimes | | | |
| 13 | Floors/Carpet/Tile Type | | П | П | |

| Line | Inspection Criteria | | Cond | ition | | Inspection Comments |
|------|---|-----|-------------|-------|------|---------------------|
| # | | New | Good | Fair | Poor | |
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | | | | |
| 16 | Weatherproofing (List Deficiencies) | | | | | |
| 17 | HVAC | | \boxtimes | | | Bard |
| 18 | Electrical Receptacles | | | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | | Square D panel |
| 20 | Emergency Lighting | | \boxtimes | | | |
| 21 | Interior Light Fixtures (tied to structure) | | | | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | \boxtimes | | | in attic |
| 26 | Intercom system | | \boxtimes | | | |
| 27 | Fire Extinguisher (Tagged and Current) | | | | | |
| 28 | Plumbing/Fixtures | | | | | N/A |
| | | | | | | |

| Line # | Inspection Criteria | Yes | ndition No | | Inspection Comments |
|-----------|--|-------------|---------------|-----|----------------------------------|
| 29 | Is unit in 100-year flood plain? | | | | |
| 30 | Technology Capable | | | | |
| 31 | Occupancy Certificate Posted in Unit | | | | |
| 32 | Local Agency Reports Posted | \boxtimes | | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | | | |
| 34 | 380 4 1 3 1 | | | | |
| | | | | | Additional Comments/Observations |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | 7=1 | |
| | | | | | |
| <u></u> | / | | | | |

<u>9-/3-ZZ</u> Date:

Manager Signature:

10/11/22 Date:

Unit Number: B 0906

Unit Location: Blanton ES.

| Office | Number: B 0906 | | | | Sec. | Unit Location: Blanton E5. Inspection Date: 9/13/22 |
|--------|--|-------|-------------|------|------|---|
| Inspe | ected By: John H. I | 3oryc | ens | | | License Number: BN 7352 |
| Line | Inspection Criteria | | Condi | tion | | |
| # | | New | Good | Fair | Poor | Inspection Comments |
| 1 | Pier and foundations (Show Location on Back) | | \boxtimes | | | |
| 2 | Tie downs and Anchors (Show Location on Back) | | \boxtimes | | | |
| 3 | Set Backs (Between Units and from property) | | \boxtimes | | | |
| 4 | Steps and Ramps | | \boxtimes | | | concrete walkways |
| 5 | Means of Egress | | \boxtimes | | | |
| 6 | Structural Integrity | | \boxtimes | | | |
| 7 | Roof Trusses | | \boxtimes | | | |
| 8 | Roof Covering (Note type Shingles, Veral, etc.) | | \boxtimes | | | Rubber |
| 9 | Exterior Walls/Siding | | | , | | hardie board |
| 10 | Exterior Lighting (note if any) | | \boxtimes | | | |
| 11 | Interior Walls and Covering | | \boxtimes | | | vinyl covered drywall |
| 12 | Doors/Windows/ Hardware | | \boxtimes | | | |
| 13 | Floors/Carpet/Tile Type and Condition | | | | | |

| Line # | Inspection Criteria | New | Cond | Poor | Inspection Comments |
|-----------|---|-----|-------------|------|---------------------|
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | | | |
| 16 | Weatherproofing (List Deficiencies) | | | | |
| 17 | HVAC | | \boxtimes | | Bard |
| 18 | Electrical Receptacles | | \boxtimes | | |
| 19 | Distribution Panel (labeled Correctly) | | | | Square D panel |
| 20 | Emergency Lighting | | | | |
| 21 | Interior Light Fixtures (tied to structure) | | \boxtimes | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | | | in attic |
| 26 | Intercom system | | \boxtimes | | |
| 27 | Fire Extinguisher (Tagged and Current) | | | | |
| 28 | Plumbing/Fixtures | | | | N/A |
| | | | | | |

| Line | Inspection Criteria | | ndition | | Inspection Comments | | | | | |
|------|--|-------|-------------|--|----------------------------------|--|--|--|--|--|
| # | | Yes | No | | | | | | | |
| 29 | Is unit in 100-year flood plain? | | | | | | | | | |
| 30 | Technology Capable | | | | | | | | | |
| 31 | Occupancy Certificate Posted in Unit | | | | | | | | | |
| 32 | Local Agency Reports Posted | | | | | | | | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | \boxtimes | | | | | | | |
| 34 | What grade level or usage is unit? | Other | | | | | | | | |
| | | | | | Additional Comments/Observations | | | | | |
| | | | | | | | | | | |
| | | ŧ | | | | | | | | |
| | | · | | | | | | | | |
| | * | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

<u>9-/3-22</u> Date:

Manager Signature:

Jo/11/52

Unit Number: B 0907

Unit Location: Blanton ES.

| Inspe | ected By: John H. E | Borve | ens | | | License Number: BN 7352 | | |
|-----------|--|-------|-------------|------|------|-------------------------|--|--|
| Line # | Inspection Criteria | | Condi | tion | | Inspection Comments | | |
| | | New | Good | Fair | Poor | | | |
| 1 | Pier and foundations (Show Location on Back) | | | | | | | |
| 2 | Tie downs and Anchors (Show Location on Back) | | | | | | | |
| 3 | Set Backs (Between Units and from property) | | | | | | | |
| 4 | Steps and Ramps | | \boxtimes | | | concrete walkways | | |
| 5 | Means of Egress | | \boxtimes | | | | | |
| 6 | Structural Integrity | | \boxtimes | | | | | |
| 7 | Roof Trusses | | \boxtimes | | | 7 | | |
| 8 | Roof Covering (Note type Shingles, Veral, etc.) | | | | | Rubber | | |
| 9 | Exterior Walls/Siding | | | | | hardie board | | |
| 10 | Exterior Lighting (note if any) | | | | | | | |
| 11 | Interior Walls and Covering | | | | | vinyl covered drywall | | |
| 12 | Doors/Windows/ Hardware | | | | | | | |
| 13 | Floors/Carpet/Tile Type and Condition | | | | | | | |

| Line | Inspection Criteria | | Cond | ition | | Inspection Comments |
|------|---|-------------|-------------|-------|------|---------------------|
| # | | New | Good | Fair | Poor | |
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | \boxtimes | | | |
| 16 | Weatherproofing (List Deficiencies) | | \boxtimes | | | |
| 17 | HVAC | | \boxtimes | | | Bard |
| 18 | Electrical Receptacles | | \boxtimes | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | | Square D panel |
| 20 | Emergency Lighting | | | | | |
| 21 | Interior Light Fixtures (tied to structure) | | \boxtimes | | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | \boxtimes | | | in attic |
| 26 | Intercom system | | \boxtimes | | | |
| 27 | Fire Extinguisher (Tagged and Current) | \boxtimes | | | | |
| 28 | Plumbing/Fixtures | | | | | N/A |
| | | | | | | |

| Line | Inspection Criteria | Co | ndition | | Inspection Comments | | | | | |
|------|--|-------|-------------|--|----------------------------------|--|--|--|--|--|
| # | | Yes | No | | | | | | | |
| 29 | Is unit in 100-year flood plain? | | \boxtimes | | | | | | | |
| 30 | Technology Capable | | | | | | | | | |
| 31 | Occupancy Certificate Posted in Unit | | | | | | | | | |
| 32 | Local Agency Reports Posted | | | | | | | | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | | | | | | | | |
| 34 | What grade level or usage is unit? | Other | | K-5 | K-5 | | | | | |
| | | | | | Additional Comments/Observations | | | | | |
| | | | | Section of the sectio | | | | | | |
| | | | | | 8 | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | * | | | | | | |
| | | | | | | | | | | |
| 370 | 1 | | | | | | | | | |

9-/3-22 Date:

Manager Signature:

70/11/22 Date:

Unit Number: B 0908

Unit Location: Blanton ES.

Inspection Date:

9/13/22

| Inspe | ected By: John H. I | Boryce | ens | | | License Number: BN 7352 |
|-----------|--|--------|-------------|------|--|-------------------------|
| Line # | Inspection Criteria | | Condi | tion | PROTECTION OF THE PROTECTION O | Inspection Comments |
| 11.00 | 1000 | New | Good | Fair | Poor | inspection Confinents |
| 1 | Pier and foundations (Show Location on Back) | | \boxtimes | | | |
| 2 | Tie downs and Anchors (Show Location on Back) | | \boxtimes | | | |
| 3 | Set Backs (Between Units and from property) | | | | | |
| 4 | Steps and Ramps | | \boxtimes | | | concrete walkways |
| 5 | Means of Egress | | \boxtimes | | | |
| 6 | Structural Integrity | | \boxtimes | | | |
| 7 | Roof Trusses | | \boxtimes | | | |
| 8 | Roof Covering (Note type Shingles, Veral, etc.) | | \boxtimes | | | Rubber |
| 9 | Exterior Walls/Siding | | | | | hardie board |
| 10 | Exterior Lighting (note if any) | | \boxtimes | | | |
| 11 | Interior Walls and Covering | | | | | vinyl covered drywall |
| 12 | Doors/Windows/ Hardware | | \boxtimes | | | |
| 13 | Floors/Carpet/Tile Type and Condition | | | | | |

| Line | Inspection Criteria | | Cond | ition | | Inspection Comments |
|------|--|-------------|-------------|-------|------|---------------------|
| # | 17 TO MINE TO 18 T | New | Good | Fair | Poor | |
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | \boxtimes | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | \boxtimes | | | |
| 16 | Weatherproofing (List Deficiencies) | | \boxtimes | | | |
| 17 | HVAC | | \boxtimes | | | Bard |
| 18 | Electrical Receptacles | | \boxtimes | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | | Square D panel |
| 20 | Emergency Lighting | | \boxtimes | | | |
| 21 | Interior Light Fixtures (tied to structure) | | \boxtimes | | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | \boxtimes | | | in attic |
| 26 | Intercom system | | \boxtimes | | | |
| 27 | Fire Extinguisher (Tagged and Current) | \boxtimes | | | | |
| 28 | Plumbing/Fixtures | | | | | N/A |
| | | | | | | |

| Line # | Inspection Criteria | Condition Yes No | | Inspection Comments |
|-----------|--|---------------------|-----|----------------------------------|
| 29 | Is unit in 100-year flood plain? | | | |
| 30 | Technology Capable | | | |
| 31 | Occupancy Certificate Posted in Unit | | | |
| 32 | Local Agency Reports Posted | | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | | |
| 34 | What grade level or usage is unit? | Other | K-5 | |
| | | | | Additional Comments/Observations |
| | | | | |
| | | | | 1 |
| | | | | |
| | ,= | | | |
| | | 91 | | |
| | | | | |
| | | | | |
| | | | | |
| 1 | 1 | | | |

<u>9-/3-22</u> Date:

Manager Signature:

10/11/22 Date:

Pinellas County Schools

Relocatable Classroom Inspection Certificate

| 1 | Pier and foundations (Show Location on Back) | \boxtimes | | |
|----|--|-------------|---|-----------------------|
| 2 | Tie downs and Anchors (Show Location on Back) | | | |
| 3 | Set Backs (Between Units and from property) | | | |
| 4 | Steps and Ramps | | | concrete walkways |
| 5 | Means of Egress | \boxtimes | | |
| 6 | Structural Integrity | \boxtimes | | |
| 7 | Roof Trusses | | | |
| 8 | Roof Covering (Note type Shingles, Veral, etc.) | | | Rubber |
| 9 | Exterior Walls/Siding | \boxtimes | | hardie board |
| 10 | Exterior Lighting (note if any) | | | |
| 11 | Interior Walls and Covering | \boxtimes | | vinyl covered drywall |
| 12 | Doors/Windows/ Hardware | | | |
| 13 | Floors/Carpet/Tile Type | X | П | |

| Line # | Inspection Criteria | | Cond | | | Inspection Comments |
|-----------|--|-------------|-------------|------|------|---------------------|
| # | A PERSONAL PROPERTY OF THE PERSON NAMED AND ADDRESS OF THE PER | New | Good | Fair | Poor | |
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | | | | |
| 16 | Weatherproofing (List Deficiencies) | | \boxtimes | | | |
| 17 | HVAC | | \boxtimes | | | Bard |
| 18 | Electrical Receptacles | | \boxtimes | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | | Square D panel |
| 20 | Emergency Lighting | | | | | |
| 21 | Interior Light Fixtures (tied to structure) | | | | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | \boxtimes | | | in attic |
| 26 | Intercom system | | \boxtimes | | | |
| 27 | Fire Extinguisher (Tagged and Current) | \boxtimes | | | | |
| 28 | Plumbing/Fixtures | | | | | N/A |
| | | | | | | |

| Line # | Inspection Criteria | Condition Yes No | Inspection Comments | |
|-----------|--|---------------------|----------------------------------|---|
| 29 | Is unit in 100-year flood plain? | | | |
| 30 | Technology Capable | | | |
| 31 | Occupancy Certificate Posted in Unit | | | * |
| 32 | Local Agency Reports Posted | | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | | |
| 34 | What grade level or usage is unit? | Other | K-5 | |
| | | | Additional Comments/Observations | |
| | 5 | | | |
| | ε | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | 3 | |
| 7 | | | | |

9-13-22 Date:

Manager Signature:

19/18/22 Date:

Unit Number: B 0910

Unit Location: Blanton ES.

| Inspe | ected By: John H. E | Boryc | ens | | | License Number: BN 7352 |
|-----------|--|-------|-------------|------|------|-------------------------|
| Line # | Inspection Criteria | | Condi | tion | | Inspection Comments |
| | | New | Good | Fair | Poor | |
| 1 | Pier and foundations (Show Location on Back) | | | | | |
| 2 | Tie downs and Anchors (Show Location on Back) | | \boxtimes | | | |
| 3 | Set Backs (Between Units and from property) | | \boxtimes | | | |
| 4 | Steps and Ramps | | | | | concrete walkways |
| 5 | Means of Egress | | | | | |
| 6 | Structural Integrity | | | | | |
| 7 | Roof Trusses | | \boxtimes | | | |
| 8 | Roof Covering (Note type Shingles, Veral, etc.) | | \boxtimes | | | Rubber |
| 9 | Exterior Walls/Siding | | \boxtimes | | | hardie board |
| 10 | Exterior Lighting (note if any) | | \boxtimes | | | |
| 11 | Interior Walls and Covering | | | | | vinyl covered drywall |
| 12 | Doors/Windows/ Hardware | | \boxtimes | | | |
| 13 | Floors/Carpet/Tile Type and Condition | | \boxtimes | | | |

| Line | Inspection Criteria | | Cond | ition | T (C. 4.15) | Inspection Comments |
|------|---|-------------|-------------|-------|-------------|---------------------|
| # | | New | Good | Fair | Poor | |
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | \boxtimes | | | |
| 16 | Weatherproofing (List Deficiencies) | | \boxtimes | | | |
| 17 | HVAC | | \boxtimes | | | Bard |
| 18 | Electrical Receptacles | | | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | | Square D panel |
| 20 | Emergency Lighting | | \boxtimes | | | |
| 21 | Interior Light Fixtures (tied to structure) | | \boxtimes | | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | \boxtimes | | | in attic |
| 26 | Intercom system | | \boxtimes | | | |
| 27 | Fire Extinguisher (Tagged and Current) | \boxtimes | | | | |
| 28 | Plumbing/Fixtures | | | | | N/A |
| | | | | | | |

| Line # | Inspection Criteria | Condition Yes No | Inspection Comments |
|-----------|--|---------------------|----------------------------------|
| 29 | Is unit in 100-year flood plain? | | |
| 30 | Technology Capable | | |
| 31 | Occupancy Certificate Posted in Unit | | |
| 32 | Local Agency Reports Posted | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | |
| 34 | What grade level or usage is unit? | Other | K-5 |
| | | | Additional Comments/Observations |
| | | | |
| | | | |
| | | | |
| | 1 | | |
| | | | |
| | | | |
| | | | |
| 0 | AN | | |

9-/3-22 Date:

Manager Signature:

Date:

Unit Number: B 0911

Unit Location: Blanton ES.

| Inspected By: John H. Borycens | | | | | | License Number: BN 7352 |
|--------------------------------|--|-----|-------|------|------|-------------------------|
| Line # | Inspection Criteria | | Condi | tion | | |
| | | New | Good | Fair | Poor | Inspection Comments |
| 1 | Pier and foundations (Show Location on Back) | | | | | |
| 2 | Tie downs and Anchors (Show Location on Back) | | | | | |
| 3 | Set Backs (Between Units and from property) | | | | | |
| 4 | Steps and Ramps | | | | | concrete walkways |
| 5 | Means of Egress | | | | | |
| 6 | Structural Integrity | | | | | |
| 7 | Roof Trusses | | | | | |
| 8 | Roof Covering (Note type Shingles, Veral, etc.) | | | | | Rubber |
| 9 | Exterior Walls/Siding | | | | | hardie board |
| 10 | Exterior Lighting (note if any) | | | | | |
| 11 | Interior Walls and Covering | | | | | vinyl covered drywall |
| 12 | Doors/Windows/ Hardware | | | | | |
| 13 | Floors/Carpet/Tile Type and Condition | | | | | |

| Line | Inspection Criteria | | Cond | ition | | Inspection Comments |
|------|---|-------------|-------------|-------|------|---------------------|
| # | | New | Good | Fair | Poor | |
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | | | | |
| 16 | Weatherproofing (List Deficiencies) | | | | | |
| 17 | HVAC | | \boxtimes | | | Bard |
| 18 | Electrical Receptacles | | \boxtimes | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | | Square D panel |
| 20 | Emergency Lighting | | \boxtimes | | | |
| 21 | Interior Light Fixtures (tied to structure) | | \boxtimes | | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | | | | in attic |
| 26 | Intercom system | | \boxtimes | | | |
| 27 | Fire Extinguisher (Tagged and Current) | \boxtimes | | | | |
| 28 | Plumbing/Fixtures | | | | | N/A |
| | | | | | | |

| Line # | Inspection Criteria | Yes | ndition No | Inspection Comments | |
|-----------|--|-------|----------------|----------------------------------|---------------------------------------|
| 29 | Is unit in 100-year flood plain? | res | NO | | |
| 30 | Technology Capable | | | | |
| 31 | Occupancy Certificate Posted in Unit | | | | |
| 32 | Local Agency Reports Posted | | | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | | | |
| 34 | What grade level or usage is unit? | Other | | K-5 | |
| | | | | Additional Comments/Observations | |
| | | | | | |
| | | | | | |
| 70 | | | 1 | | |
| | | | | | |
| | | | | | 1 |
| | | | and the second | | |
| | | | | | · · · · · · · · · · · · · · · · · · · |
| | | | | | |

9-/3-22 Date:

Manager Signature:

Date:

Pinellas County Schools

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B 0912

Unit Location: Blanton ES.

Inspection Date: 9/13/22

Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps concrete walkways \boxtimes 5 Means of Egress Structural Integrity 6 Roof Trusses X Roof Covering (Note type 8 \boxtimes Rubber Shingles, Veral, etc.) Exterior Walls/Siding 9 hardie board Exterior Lighting (note if 10 any) Interior Walls and 11 vinyl covered drywall Covering Doors/Windows/ 12 Hardware Floors/Carpet/Tile Type 13 and Condition

| Line | Inspection Criteria | ā ta ta | Cond | ition | | Inspection Comments |
|------|---|-------------|-------------|-------|------|---------------------|
| # | | New | Good | Fair | Poor | |
| 14 | Ceilings/Tiles/Grid/ Wire Hangers (12ga) | | \boxtimes | | | |
| 15 | Visual Aids (Chalk/Marker Boards and Tack Boards) | | \boxtimes | | | |
| 16 | Weatherproofing (List Deficiencies) | | \boxtimes | | | |
| 17 | HVAC | | \boxtimes | | | Bard |
| 18 | Electrical Receptacles | | \boxtimes | | | |
| 19 | Distribution Panel (labeled Correctly) | | \boxtimes | | | Square D panel |
| 20 | Emergency Lighting | | \boxtimes | | | |
| 21 | Interior Light Fixtures (tied to structure) | | \boxtimes | | | |
| 22 | Fire Alarm (Strobes, Horn, Pull Stations) | | \boxtimes | | | |
| 23 | Heat Detector/Smoke Detector in Storage Spaces | | \boxtimes | | | |
| 24 | Heat Detector/Smoke Detector in Classroom | | \boxtimes | | | |
| 25 | Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only) | | \boxtimes | | | in attic |
| 26 | Intercom system | | \boxtimes | | | |
| 27 | Fire Extinguisher (Tagged and Current) | \boxtimes | | | | |
| 28 | Plumbing/Fixtures | | | | | N/A |
| | | | | | | |

| Line | Inspection Criteria | Condition | Inspection Comments | | | | | |
|------|--|-----------|----------------------------------|--|--|--|--|--|
| # | | Yes No | | | | | | |
| 29 | Is unit in 100-year flood plain? | | | | | | | |
| 30 | Technology Capable | | | | | | | |
| 31 | Occupancy Certificate Posted in Unit | | | | | | | |
| 32 | Local Agency Reports Posted | | | | | | | |
| 33 | Does unit have any known Environmental factors? If yes, Explain. | | | | | | | |
| 34 | What grade level or usage is unit? | Other | K-5 | | | | | |
| | | | Additional Comments/Observations | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | 1 | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | 1 | | | | | | | |

9-13-22 Date:

Manager Signature:

10/11/22