Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

**Unit Number:** B9001 Unit Location: Brooker Creek ES. Inspection Date: 9/15/22 License Number: BN 7352 Inspected By: John H. Borycens Condition **Inspection Criteria** Line **Inspection Comments** # Good Fair Poor New Pier and foundations  $\times$ 1 (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity 6  $\bowtie$ Roof Trusses 7  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 X T 111 Exterior Lighting (note if 10 Xany) Interior Walls and 11  $\boxtimes$ Paneling Covering

Doors/Windows/

and Condition

Floors/Carpet/Tile Type

Hardware

 $\boxtimes$ 

 $\boxtimes$ 

12

13

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					я
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$		×		
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition		Inspection Comments
#		Yes	No		
29	Is unit in 100-year flood plain?				
30	Technology Capable	$\boxtimes$			
31	Occupancy Certificate Posted in Unit	$\boxtimes$			
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
7					

<u>9-15-22</u> Date:

Manager Signature:

9/22/22

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B8614 Unit Location: Brooker Creek ES. Inspection Date: 9/15/22

License Number: BN 7352 Inspected By: John H. Borycens **Inspection Criteria** Condition Line **Inspection Comments** # Good Fair Poor New Pier and foundations  $\boxtimes$ 1 (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity X 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if X 10 any) Interior Walls and X 11 Paneling Covering Doors/Windows/ X 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria		Condition			Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures		$\boxtimes$			This unit has a sink only

Line #	Inspection Criteria	Condition Yes No	Inspection Comments					
29	Is unit in 100-year flood plain?							
30	Technology Capable							
31	Occupancy Certificate Posted in Unit							
32	Local Agency Reports Posted							
33	Does unit have any known Environmental factors? If yes, Explain.							
34	What grade level or usage is unit?	Other	K-5 science lab					
			Additional Comments/Observations					
		-						
			÷					

9-15-22 Date:

Manager Signature:

9/22/22

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B9112 Unit Location: Brooker Creek ES. Inspection Date: 9/15/22

BN 7352 Inspected By: John H. Borycens License Number: Inspection Criteria Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations X(Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses 7  $\boxtimes$ Roof Covering (Note type  $\times$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\times$ 9 T 111 Exterior Lighting (note if  $\times$ 10 any) Interior Walls and 11 XPaneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			The second secon
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			× ×
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments					
29	Is unit in 100-year flood plain?		$\boxtimes$							
30	Technology Capable									
31	Occupancy Certificate Posted in Unit	$\boxtimes$								
32	Local Agency Reports Posted	$\boxtimes$								
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$							
34	What grade level or usage is unit?	Other	Other		K-5					
					Additional Comments/Observations					

9-/5-2Z Date:

Manager Signature:

9/22/22 Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B9323 Unit Location: Brooker Creek ES. Inspection Date: 9/15/22

Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units X 3 and from property) X 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses 7 M Roof Covering (Note type 8  $\boxtimes$ Modified Shingles, Veral, etc.) Exterior Walls/Siding 9  $\boxtimes$ T 111 Exterior Lighting (note if 10  $\boxtimes$ any) Interior Walls and 11  $\boxtimes$ Paneling Covering Doors/Windows/ 12  $\boxtimes$ Hardware Floors/Carpet/Tile Type 13  $\boxtimes$ and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting				X	Emergency light is not working
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	K-5
			Additional Comments/Observations
	#20 work order for the e	mergency light #14535	0
		*	
_			

9-15-22 Date:

Manager Signature:

10/11/22 Data:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: E8919 Unit Location: Brooker Creek ES. Inspection Date: 9/15/22

License Number: Inspected By: John H. Borycens BN 7352 **Inspection Criteria** Condition Line # **Inspection Comments** Fair New Good Poor Pier and foundations  $\boxtimes$ 1 (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and 11 X Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	K-5
			Additional Comments/Observations
. 1			
1			

9-15-22 Date:

Manager Signature:

9/22/22 Date: