# **Pinellas County Schools**

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9016 Unit Location: Campbell Park Es. Inspection Date: 9/13/22 Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations  $\times$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property) X 4 Steps and Ramps Concrete  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses X Roof Covering (Note type X Rubber Shingles, Veral, etc.) Exterior Walls/Siding X 9 Hardie board Exterior Lighting (note if 10 X any) Interior Walls and  $\boxtimes$ 11 vinyl covered drywall Covering Doors/Windows/  $\boxtimes$ Hardware Floors/Carpet/Tile Type 13 X and Condition

Line	Inspection Criteria	\$#A	Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$		2.4	
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria		ndition		Inspection Comments
		Yes	No		
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		K-5	
in a					Additional Comments/Observations
			1		
	1				

9-13-72 Date:

Manager Signature:

9/21/22

## **Pinellas County Schools**

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B 9017

Unit Location: Campbell Park Es.

Inspection Date: 9/13/22

BN 7352 License Number: Inspected By: John H. Borycens Condition Line **Inspection Criteria Inspection Comments** # New Good Fair Poor Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units X 3 and from property) X Concrete 4 Steps and Ramps  $\times$ 5 Means of Egress Structural Integrity X 6 Roof Trusses X Roof Covering (Note type X 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding X 9 Hardie board Exterior Lighting (note if X 10 any) X Interior Walls and vinyl covered drywall Covering Doors/Windows/ X Hardware Floors/Carpet/Tile Type 13 and Condition

Line			ition		Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					NA
						*

Line #	Inspection Criteria	Condition Yes No		Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	K-5	
				Additional Comments/Observations
		4		
	\ /			

 $\frac{9-/3-2z}{\text{Date:}}$ 

Manager Signature:

9/21/22

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9018

Unit Location: Campbell Park Es.

Inspection Date: 9/13/22

Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion	126.3	
		New	Good	Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps		$\boxtimes$			Concrete
5	Means of Egress					
6	Structural Integrity		$\boxtimes$			
7	Roof Trusses		$\boxtimes$			
8	Roof Covering (Note type Shingles, Veral, etc.)		$\boxtimes$			Rubber
9	Exterior Walls/Siding		$\boxtimes$			Hardie board
10	Exterior Lighting (note if any)		$\boxtimes$			
11	Interior Walls and Covering		$\boxtimes$			vinyl covered drywall
12	Doors/Windows/ Hardware		$\boxtimes$			
13	Floors/Carpet/Tile Type and Condition		$\boxtimes$			

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition		Inspection Comments		
#		Yes	No				
29	Is unit in 100-year flood plain?						
30	Technology Capable	$\boxtimes$					
31	Occupancy Certificate Posted in Unit						
32	Local Agency Reports Posted	$\boxtimes$					
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$				
34	What grade level or usage is unit?	Other		K-5			
				Ado	litional Comments/Observations		
			9	280			
				E			
	1						

9 -/3 - 2z Date:

Manager Signature:

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9019

Unit Location: Campbell Park Es.

Inspection Date: 9/13/22

Inspe	ected By: John H. E	Boryce	ens		Kuri Alia	License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		
		New	Good	Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps		$\boxtimes$			Concrete
5	Means of Egress					
6	Structural Integrity					
7	Roof Trusses		$\boxtimes$			
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber
9	Exterior Walls/Siding		$\boxtimes$			Hardie board
10	Exterior Lighting (note if any)		$\boxtimes$			
11	Interior Walls and Covering					vinyl covered drywall
12	Doors/Windows/ Hardware		$\boxtimes$			
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					NA

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
	s				
		3			
				8	
1					9
7	,				

9-13-27 Date:

Manager Signature:

9/21/22 Date:

## **Pinellas County Schools**

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9020 Unit Location: Campbell Park Es. Inspection Date: 9/13/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units 3  $\boxtimes$ and from property)  $\times$ 4 Steps and Ramps Concrete  $\boxtimes$ 5 Means of Egress Structural Integrity 6  $\boxtimes$ Roof Trusses  $\boxtimes$ Roof Covering (Note type X Rubber Shingles, Veral, etc.) Exterior Walls/Siding 9 X Hardie board Exterior Lighting (note if 10  $\boxtimes$ any) Interior Walls and  $\boxtimes$ vinyl covered drywall Covering Doors/Windows/ X Hardware Floors/Carpet/Tile Type X 13 and Condition

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC					Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					NA

Line	Inspection Criteria	Col	ndition		Inspection Comments				
#		Yes	No						
29	Is unit in 100-year flood plain?		$\boxtimes$						
30	Technology Capable								
31	Occupancy Certificate Posted in Unit								
32	Local Agency Reports Posted	$\boxtimes$							
33	Does unit have any known Environmental factors? If yes, Explain.								
34	What grade level or usage is unit?  Other  K-5								
		e service Participation			Additional Comments/Observations				
4									

<u>9-/3-22</u> Date:

Manager Signature:

9/21/22

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9021

Unit Location: Campbell Park Es.

Inspection Date: 9/13/22

Insp	ected By: John H. I	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		
	The state of the s	New	Good	Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)		$\boxtimes$			
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps		$\boxtimes$			Concrete
5	Means of Egress		$\boxtimes$			
6	Structural Integrity		$\boxtimes$			
7	Roof Trusses		$\boxtimes$			
8	Roof Covering (Note type Shingles, Veral, etc.)					Rubber
9	Exterior Walls/Siding					Hardie board
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering		$\boxtimes$			vinyl covered drywall
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Condition			Inspection Comments
#		Yes	No	2002	
29	Is unit in 100-year flood plain?		$\boxtimes$		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$		
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
			особ, в саницарии и		

9-13-22 Date:

Manager Signature:

<u>9/21/22</u> Date: