Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: LGR2003 Unit Location: Clearwater H.S.. Inspection Date: 4/27/23 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity X Roof Trusses X Roof Covering (Note type \boxtimes Metal Shingles, Veral, etc.) Exterior Walls/Siding X 9 Metal Exterior Lighting (note if X 10 any) Interior Walls and \boxtimes 11 Kemlite Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					N/A
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		\boxtimes			This is a group restroom

Line	Inspection Criteria	Cor	ndition		Inspection Comments
#		Yes	No		
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable		\boxtimes		
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		Lease	ed group restroom
					Additional Comments/Observations
$\overline{}$					

<u>4-27-28</u> Date:

Manager Signature:

__*\$\\\^2/23* Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

(Yearly Inspection Report) Unit Number: LGR 2002 Unit Location: Clearwater HS. Inspection Date: 4/27/23 Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum 5 Means of Egress Structural Integrity \boxtimes 6 **Roof Trusses** \boxtimes Roof Covering (Note type X 8 Metal Shingles, Veral, etc.) Exterior Walls/Siding \times 9 Metal Exterior Lighting (note if \times 10 any) Interior Walls and X Kem lite Covering Doors/Windows/ \boxtimes Hardware Floors/Carpet/Tile Type X 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					N/A
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit is a group restroom

Line #	Inspection Criteria		ndition		Inspection Comments
Ħ		Yes	No		
29	Is unit in 100-year flood plain?				
30	Technology Capable		\boxtimes		
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		••••	eased Group restroom
					Additional Comments/Observations

<u>4-27-23</u> Date:

Manager Signature:

5/2/23

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8722 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 Condition **Inspection Criteria** Line **Inspection Comments** # New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 **Roof Trusses** \boxtimes 7 Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \times 9 T 111 Exterior Lighting (note if 10 \times any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No		Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	9-12	
				Additional Comments/Observations
				*
1				

9 -22-22 Date:

Manager Signature:

10/11/22 Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8811 Unit Location: Clearwater HS. Inspection Date: 9/22/22 Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes 1 (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units 3 \boxtimes and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses 7 Roof Covering (Note type 8 \boxtimes Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 \boxtimes T 111 Exterior Lighting (note if 10 \boxtimes any) Interior Walls and 11 \boxtimes Paneling Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations
					×
1	1				

9-22-22 Date:

Manager Signature:

<u>19/11/22</u> Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8812

Unit Location: Clearwater HS.

Inspection Date: 9/22/22

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	e Inspection Criteria Condition					Inspection Comments
		New	Good	Fair	Poor	
1	Pier and foundations (Show Location on Back)		\boxtimes			
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps		\boxtimes			Aluminum
5	Means of Egress		\boxtimes			
6	Structural Integrity		\boxtimes			
7	Roof Trusses		\boxtimes			
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Modified
9	Exterior Walls/Siding		\boxtimes			T 111
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering		\boxtimes			Paneling
12	Doors/Windows/ Hardware					3
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line	Inspection Criteria	Condition				Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	9-12
			Additional Comments/Observations
	,		
		8	
	100		
1	1		

<u>9-22-22</u> Date:

Manager Signature:

12/11/22 Pate:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8821 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 Line **Inspection Criteria** Condition # **Inspection Comments** Good Fair Poor New Pier and foundations \boxtimes 1 (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes 7 Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if 10 \boxtimes any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection	Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	9-12	
			Additional Comments/Observations	

<u>9-21-22</u> Date:

Manager Signature:

19/11/22

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8823 Unit Location: Clearwater HS. Inspection Date: 9/22/22

License Number: BN 7352 Inspected By: John H. Borycens Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units X 3 and from property) X Aluminum 4 Steps and Ramps \times 5 Means of Egress Structural Integrity \times 6 Roof Trusses X Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if \times 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line	Inspection Criteria	Condition				Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			,
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments				
29	Is unit in 100-year flood plain?						
30	Technology Capable						
31	Occupancy Certificate Posted in Unit						
32	Local Agency Reports Posted						
33	Does unit have any known Environmental factors? If yes, Explain.						
34	What grade level or usage is unit?	Other	9-12				
			Additional Comments/Observations				
	5						
2	1						

7-22-22 Date:

Manager Signature:

79/11/82 Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8913 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** Fair New Good Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses 7 \boxtimes Roof Covering (Note type 8 \boxtimes Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and 11 \boxtimes Paneling Covering Doors/Windows/ 12 \times Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			9
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	9-12
			Additional Comments/Observations
		-	
			**
1			

<u>9-22-72</u> Date:

Manager Signature:

Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8916 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes 7 Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 \boxtimes T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	9-12
			Additional Comments/Observations
			*
			X X
1	1		

9-22-22 Date:

Manager Signature:

19/11/22

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8922 Unit Location: Clearwater HS. Inspection Date: 9/22/22

License Number: Inspected By: John H. Borycens BN 7352 Inspection Criteria Condition Line # **Inspection Comments** Good Fair New Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 **Roof Trusses** \boxtimes Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ X 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					*
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Con Yes	dition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit	\boxtimes			
32	Local Agency Reports Posted				<
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		9-12	
				F960	Additional Comments/Observations
	8				
7	1				

<u>9-22-22</u> Date:

Manager Signature:

oate:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8933 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** Good Fair Poor New Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type 8 \boxtimes Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 \boxtimes T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria	Condition				Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes	-		
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)					
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	9-12
			Additional Comments/Observations
		-	
^	/		

9-2z-zz Date:

Manager Signature:

ate:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8946 Unit Location: Clearwater HS. Inspection Date: 9/22/22

License Number: BN 7352 Inspected By: John H. Borycens Inspection Criteria Condition Line **Inspection Comments** # Poor Fair New Good Pier and foundations \boxtimes 1 (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses X 7 Roof Covering (Note type X 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if X 10 any) Interior Walls and X 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria	Condition				Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No			Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		9-12	
	Additional Comments/Observations				
			¥.		
					*
					*
	1				

9-22-27 Date:

Manager Signature:

Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 8956 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Line Condition # **Inspection Comments** New Good Fair Poor Pier and foundations \times (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes 7 Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if 10 \boxtimes any) Interior Walls and X 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No		Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			. ~
34	What grade level or usage is unit?	Other	9-12	
			Additional Comments/Obs	servations
				*
			,	
		9-22-2	3	10/11/22

Date:

Manager Signature:

19/11/22 Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9004 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 Line **Inspection Criteria** Condition # **Inspection Comments** Good Fair Poor New Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 **Roof Trusses** X 7 Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condit Yes N			Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other	•	9-12	
				Addition	nal Comments/Observations
		22			
7	/				

<u>9-22-22</u> Date:

Manager Signature:

10/11/22

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9025 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: **BN 7352** Inspection Criteria Condition Line # **Inspection Comments** Good Fair New Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors 2 \boxtimes (Show Location on Back) Set Backs (Between Units \times 3 and from property) X 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity 6 X Roof Trusses 7 X Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if \times 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes		Ò	
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No)n	Inspection Comments
29	Is unit in 100-year flood plain?]	
30	Technology Capable]	
31	Occupancy Certificate Posted in Unit]	
32	Local Agency Reports Posted]	
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	9-12	
				Additional Comments/Observations
-			***	

9-22-22-Date:

Manager Signature:

19/11/82 Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9102 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** Good Fair New Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes 7 Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria	P REST	Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			*
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	9-12
			Additional Comments/Observations
7	1		

9-22-22 Date:

Manager Signature:

10/11/2Z

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9115 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: **BN 7352 Inspection Criteria** Condition Line # **Inspection Comments** Good Fair Poor New Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity \times 6 Roof Trusses \boxtimes 7 Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and 11 \boxtimes Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line	Inspection Criteria		Condi	ition	***	Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)					
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations
					×
	4				
7					

9-22-22 Date:

Manager Signature:

0/11/22 Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9136 Unit Location: Clearwater HS. Inspection Date: 9/22/22

License Number: Inspected By: John H. Borycens BN 7352 Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity X6 **Roof Trusses** \boxtimes 7 Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \times 9 T 111 Exterior Lighting (note if 10 \boxtimes any) Interior Walls and 11 XPaneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	dition No		Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations

<u>9-22-22</u> Date:

Manager Signature:

19/11/12 Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9139 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 Condition Line **Inspection Criteria** # **Inspection Comments** New Good Fair Poor Pier and foundations (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) 4 Steps and Ramps Aluminum 5 \boxtimes Means of Egress Structural Integrity 6 \boxtimes Roof Trusses \boxtimes 7 Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			C
16	Weatherproofing (List Deficiencies)					
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit	\boxtimes			
32	Local Agency Reports Posted	\boxtimes			
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		9-12	
				Ado	litional Comments/Observations
					· · · · · · · · · · · · · · · · · · ·
^					

 $\frac{9-22-22}{\text{Date:}}$

Manager Signature:

)ate:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9205 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # Fair Poor New Good Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Aluminum Steps and Ramps \boxtimes 5 Means of Egress Structural Integrity X 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and X 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			×
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No		Inspection Comments	
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other	9-12		
			Additional	Comments/Observations	
	~				
		5			
					,
					501 1001

9-22-22 Date:

Manager Signature:

<u> 19/11/22</u> Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9207 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 **Inspection Criteria** Condition Line # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes 1 (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line #	Inspection Criteria		Condi			Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No		Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	9-12	
				Additional Comments/Observations
			-	
1				

9-22-22 Date:

Manager Signature:

<u>/9/11/22</u> Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9310 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 Line **Inspection Criteria** Condition # **Inspection Comments** Good Fair Poor New Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type 8 \boxtimes Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 \boxtimes T 111 Exterior Lighting (note if 10 \boxtimes any) Interior Walls and X11 Paneling Covering Doors/Windows/ 12 \times Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Cond	ition	Nation of	Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted	\boxtimes).
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations
			(i		
7	1				

Date:

Manager Signature:

19/11/20

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9324 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 Line **Inspection Criteria** Condition # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Aluminum Steps and Ramps \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes 7 Roof Covering (Note type \times 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if 10 \boxtimes any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	. National transmission with programmer and progra
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	9-12
			Additional Comments/Observations
	į.		
_			

9-22-22-Date:

Manager Signature:

/3/11/22 Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9325 Unit Location: Clearwater HS. Inspection Date: 9/22/22 Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** New Good Fair **Poor** Pier and foundations \boxtimes 1 (Show Location on Back) Tie downs and Anchors \boxtimes 2 (Show Location on Back) Set Backs (Between Units 3 \boxtimes and from property) \boxtimes 4 Steps and Ramps Aluminum 5 \boxtimes Means of Egress Structural Integrity \boxtimes 6 Roof Trusses 7 Roof Covering (Note type 8 \boxtimes Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 \boxtimes T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and 11 \boxtimes Paneling Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line #	Inspection Criteria	New	Condi	Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)				
15	Visual Aids (Chalk/Marker Boards and Tack Boards)				
16	Weatherproofing (List Deficiencies)				
17	HVAC		\boxtimes		Bard
18	Electrical Receptacles		\boxtimes		,
19	Distribution Panel (labeled Correctly)		\boxtimes		Square D
20	Emergency Lighting		\boxtimes		
21	Interior Light Fixtures (tied to structure)		\boxtimes		
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes		
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes		
24	Heat Detector/Smoke Detector in Classroom		\boxtimes		=
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)				in attic
26	Intercom system		\boxtimes		
27	Fire Extinguisher (Tagged and Current)				
28	Plumbing/Fixtures				N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	9-12
***			Additional Comments/Observations
			p I
	1		

<u>9-2z-2z</u> Date:

Manager Signature:

19/11/22 Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BRN 9307 Unit Location: Clearwater HS. Inspection Date: 9/22/22

BN 7352 License Number: Inspected By: John H. Borycens **Inspection Criteria** Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors X (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) X 4 Steps and Ramps Aluminum \times 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses X Roof Covering (Note type \boxtimes 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	HER HAMINING THE TOTAL TO THE TOTAL OF THE PARTY OF THE TOTAL STATES OF THE TRANSPORT OF THE TRANSPORT OF THE T THE TRANSPORT OF THE TRANSPORT OF THE TOTAL STATES OF THE TRANSPORT OF THE TRANSPORT OF THE TRANSPORT OF THE T
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No	Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes	
30	Technology Capable			
31	Occupancy Certificate Posted in Unit	\boxtimes		
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes	
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
<u></u>				

9-22-22 Date:

Manager Signature:

10/W/22

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BRN 9328 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria	New	Condit Good	tion Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)		\boxtimes			
3	Set Backs (Between Units and from property)		\boxtimes			
4	Steps and Ramps		\boxtimes			Aluminum
5	Means of Egress		\boxtimes			
6	Structural Integrity		\boxtimes			
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified
9	Exterior Walls/Siding					T 111
10	Exterior Lighting (note if any)		\boxtimes			
11,	Interior Walls and Covering		\boxtimes			Paneling
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria	788	Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			T T
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	
			Additional Comments/Observations
-			
		7	
1	1		

<u>9-22-22</u> Date:

Manager Signature:

10/u/22

Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BRN 9404 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria	New	Condi	tion Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)		\boxtimes			
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress					
6	Structural Integrity					
7	Roof Trusses		\boxtimes			
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Modified
9	Exterior Walls/Siding		\boxtimes			T 111
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering		\boxtimes			Paneling
12	Doors/Windows/ Hardware		\boxtimes			
13	Floors/Carpet/Tile Type and Condition		\boxtimes			

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		X			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	
			Additional Comments/Observations
	2		
7	1		

9-22-22 Date:

Manager Signature:

Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: C 8904 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \times 2 (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) X 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity X 6 Roof Trusses X Roof Covering (Note type X8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and X Paneling Covering Doors/Windows/ \boxtimes 12 Hardware Floors/Carpet/Tile Type 13 X and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria		dition No		Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes		
34	What grade level or usage is unit?	Other	•	9-12	
			an in		Additional Comments/Observations
4					
1					

9-22-22 Date:

Manager Signature:

10/11/22

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B 8721 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspe	ected By: John H. E	Boryc	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
		New	Good	Fair	Poor	mispection Comments
1	Pier and foundations (Show Location on Back)		\boxtimes			
2	Tie downs and Anchors (Show Location on Back)		\boxtimes			
3	Set Backs (Between Units and from property)		\boxtimes			
4	Steps and Ramps		\boxtimes			Aluminum
5	Means of Egress		\boxtimes			
6	Structural Integrity					
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified
9	Exterior Walls/Siding					T 111
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering		\boxtimes			Paneling
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		Á			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?		\boxtimes		
30	Technology Capable	\boxtimes			
31	Occupancy Certificate Posted in Unit	\boxtimes			
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		9-12	
					Additional Comments/Observations
					*
7					

<u>9-22-22</u> Date:

Manager Signature:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B 8948 Unit Location: Clearwater HS. Inspection Date: 9/22/22

Inspected By: John H. Borycens						License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		
		New	Good	Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)		\boxtimes			
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress					
6	Structural Integrity		\boxtimes			
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified
9	Exterior Walls/Siding		\boxtimes			T 111
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering					Paneling
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No	Inspection Comments		
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other	9-12		
			Additional Comments/Observations		
	-				

9-22-22 Date:

Manager Signature:

Date: