Pinellas County Schools
Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 7107

Unit Location: Cross Bayou ES.

Inspection Date: 8/26/22

	New Good Fair Pier and foundations (Show Location on Back) Tile downs and Anchors (Show Location on Back) Set Backs (Between Units and from property) Steps and Ramps Means of Egress					Offic Location. Gross Bayou Lo. Inspection Date. Grzorzz
Insp	ected By: John H. I	3oryc	ens			License Number: BN 7352
Line	Inspection Criteria		Condi	tion		
#	- a di da manazio di Lamo i Stangar. La di dalla di Sebagai di Silvania	New	Good	Fair	Poor	Inspection Comments
1						
2			\boxtimes			
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress					
6	Structural Integrity					
7	Roof Trusses					
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified
9	Exterior Walls/Siding					T 111
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering					Paneling
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Cutler Hammer panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			×
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Condition Yes No		Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted		4.7	
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	K-5	
				Additional Comments/Observations
		4		
A			, je	
	u.			
	1	×		

8-26-22 Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: B 9134 Unit Location: Cross Bayou ES. Inspection Date: 8/26/22

Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** Good Fair Poor New Pier and foundations \boxtimes (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type \boxtimes Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and X Paneling Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type \boxtimes 13 and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC					Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting				\boxtimes	Emergency light not working
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					N/A

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments						
29	Is unit in 100-year flood plain?										
30	Technology Capable	\boxtimes									
31	Occupancy Certificate Posted in Unit										
32	Local Agency Reports Posted	\boxtimes									
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes								
34	What grade level or usage is unit?	Other		K-5							
					Additional Comments/Observations						
	# 20 Work order for the	emerge	ncy light #	143240							
_	/										

<u>8-76-27</u> Date:

Manager Signature:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: B 9414

Unit Location: Cross Bayou ES.

Inspection Date: 8/26/22

Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes 1 (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units \boxtimes 3 and from property) \boxtimes 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \times 6 Roof Trusses 7 X Roof Covering (Note type 8 \boxtimes Modified Shingles, Veral, etc.) Exterior Walls/Siding \boxtimes 9 T 111 Exterior Lighting (note if 10 X any) Interior Walls and \boxtimes 11 Paneling Covering Doors/Windows/ 12 \boxtimes Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line	Inspection Criteria	tana Luna III	Cond	ition	5700000	Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC -		\boxtimes			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		\boxtimes			Square D panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Cor	ndition		Inspection Comments						
#		Yes	No								
29	Is unit in 100-year flood plain?		\boxtimes								
30	Technology Capable										
31	Occupancy Certificate Posted in Unit										
32	Local Agency Reports Posted										
33	Does unit have any known Environmental factors? If yes, Explain.										
34	What grade level or usage is unit?	Other	or K-5								
					Additional Comments/Observations						
		1									
				¥							
	×										
1	1										

<u>8-26-22</u> Date:

Manager Signature:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: E 8717 Unit Location: Cross Bayou ES. Inspection Date: 8/26/22 Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** Good Fair New Poor Pier and foundations \boxtimes 1 (Show Location on Back) Tie downs and Anchors \boxtimes (Show Location on Back) Set Backs (Between Units X and from property) X 4 Steps and Ramps Aluminum \boxtimes Means of Egress Structural Integrity \boxtimes 6 Roof Trusses \boxtimes Roof Covering (Note type 8 \boxtimes Modified Shingles, Veral, etc.) Exterior Walls/Siding 9 \boxtimes T 111 Exterior Lighting (note if \boxtimes 10 any) Interior Walls and X 11 Paneling Covering Doors/Windows/ \boxtimes Hardware Floors/Carpet/Tile Type 13 \boxtimes

and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		\boxtimes			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			×
19	Distribution Panel (labeled Correctly)		\boxtimes			GE
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					N/A

Line	Inspection Criteria	Co	ndition		Inspection Comments		
#		Yes	No				
29	Is unit in 100-year flood plain?						
30	Technology Capable						
31	Occupancy Certificate Posted in Unit						
32	Local Agency Reports Posted	\boxtimes					
33	Does unit have any known Environmental factors? If yes, Explain.	-					
34	What grade level or usage is unit?	Other		K-5			
					Additional Comments/Observations		
		1,					
-					•		
			1:				
0							

 $\frac{\mathcal{B}-26-22}{\text{Date:}}$

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: ERK 9033

Unit Location: Cross Bayou ES.

Inspection Date: 8/26/22

Insp	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi			Inspection Comments
		New	Good	Fair	Poor	
1	Pier and foundations (Show Location on Back)					
2	Tie downs and Anchors (Show Location on Back)					
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress					
6	Structural Integrity		\boxtimes			
7	Roof Trusses		\boxtimes			
8	Roof Covering (Note type Shingles, Veral, etc.)		\boxtimes			Metal
9	Exterior Walls/Siding		\boxtimes			Metal
10	Exterior Lighting (note if any)		\boxtimes			
11	Interior Walls and Covering					Paneling
12	Doors/Windows/ Hardware		\boxtimes			
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Cond	ition	1997	Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		\boxtimes			
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles		\boxtimes			
19	Distribution Panel (labeled Correctly)		\boxtimes			Cutler Hammer panel
20	Emergency Lighting		\boxtimes			
21	Interior Light Fixtures (tied to structure)		\boxtimes			
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			·
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		\boxtimes			in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures					This unit has a restroom

Line	Inspection Criteria	Condition	Inspection Comments	Inspection Comments	
#		Yes No			
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other	К		
			Additional Comments/Observations		
800					

8-76-22 Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: LR 0429 Unit Location: Cross Bayou ES. Inspection Date: 8/26/22

Inspected By: John H. Borycens License Number: BN 7352 Line **Inspection Criteria** Condition # **Inspection Comments** New Good Fair Poor Pier and foundations \boxtimes 1 (Show Location on Back) Tie downs and Anchors 2 (Show Location on Back) Set Backs (Between Units 3 M and from property) 4 Steps and Ramps Aluminum \boxtimes 5 Means of Egress Structural Integrity \boxtimes 6 Roof Trusses 7 Roof Covering (Note type \boxtimes 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding 9 \boxtimes Metal Exterior Lighting (note if 10 any) Interior Walls and 11 Vinyl covered drywall Covering Doors/Windows/ \boxtimes Hardware Floors/Carpet/Tile Type 13 \boxtimes and Condition

Line	Inspection Criteria	Condition				Inspection Comments
#	A STATE OF S	New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		\boxtimes			
17	HVAC		\boxtimes			Bard
18	Electrical Receptacles			4		
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		\boxtimes			
23	Heat Detector/Smoke Detector in Storage Spaces		\boxtimes			
24	Heat Detector/Smoke Detector in Classroom		\boxtimes			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system		\boxtimes			
27	Fire Extinguisher (Tagged and Current)	\boxtimes				
28	Plumbing/Fixtures		\boxtimes			This unit has a restroom

Line #	Inspection Criteria Is unit in 100-year flood plain?	Condition Yes No			Inspection Comments						
29			\boxtimes								
30	Technology Capable	\boxtimes									
31	Occupancy Certificate Posted in Unit	\boxtimes									
32	Local Agency Reports Posted										
33	Does unit have any known Environmental factors? If yes, Explain.		\boxtimes								
34	What grade level or usage is unit?	Other	,	K-5							
	Additional Comments/Observations										
		15									
\bigcap	1										

8-26-22 Date:

Manager Signature: