Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: ER 9014

Unit Location: Curlew Creek ES

Inspection Date: 9/15/22

Oniti	Number: ER 9014					Offit Location. Curiew Creek ES Inspection Date. 9/19/22
Inspe	ected By: John H. E	3oryce	ens			License Number: BN 7352
Line #	Inspection Criteria		Condi	tion		Inspection Comments
#		New	Good	Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)		$\boxtimes$			
2	Tie downs and Anchors (Show Location on Back)		$\boxtimes$			
3	Set Backs (Between Units and from property)		$\boxtimes$			
4	Steps and Ramps		$\boxtimes$			Aluminum
5	Means of Egress					
6	Structural Integrity					
7	Roof Trusses		$\boxtimes$			
8	Roof Covering (Note type Shingles, Veral, etc.)					Modified
9	Exterior Walls/Siding					T 111
10	Exterior Lighting (note if any)					
11	Interior Walls and Covering		$\boxtimes$			Paneling
12	Doors/Windows/ Hardware		$\boxtimes$			
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom

Line #	Inspection Criteria	Co Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable		- 🔲		
31	Occupancy Certificate Posted in Unit	$\boxtimes$			
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$		8
34	What grade level or usage is unit?	Other		ОТ/РТ	
				Additional Con	nments/Observations
					×
^					

9-/5-22 Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 0575 Unit Location: Curlew Creek ES Inspection Date: 9/15/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # Good Fair Poor New Pier and foundations (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units 3  $\boxtimes$ and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity X 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding X9 Metal Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and 11 X Vinyl covered drywall Covering Doors/Windows/ 12  $\boxtimes$ Hardware Floors/Carpet/Tile Type 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No		Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	K-5	
			Additional C	omments/Observations
		=		
	4			
			TX	
7				

9-15-22 Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 0584 Unit Location: Curlew Creek ES Inspection Date: 9/15/22

BN 7352 License Number: Inspected By: John H. Borycens Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations  $\boxtimes$ 1 (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses 7  $\times$ Roof Covering (Note type  $\boxtimes$ 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 Metal Exterior Lighting (note if 10  $\times$ any) Interior Walls and  $\boxtimes$ 11 Vinyl covered drywall Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type 13  $\boxtimes$ and Condition

Line #	Inspection Criteria		Cond			Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom

Line #	Inspection Criteria	Condition	Inspection Comments
#		Yes No	
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	K-5
			Additional Comments/Observations
			•
	,		
			*
		3	
7	/		

<u>9-15-22</u> Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 9504 Unit Location: Curlew Creek ES Inspection Date: 9/15/22

License Number: BN 7352 Inspected By: John H. Borycens Line Inspection Criteria Condition **Inspection Comments** # New Good Fair Poor Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property) X 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity 6  $\boxtimes$ Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and 11 Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line #	Inspection Criteria	New	Condi Good		Poor	Inspection Comments
	Ceilings/Tiles/Grid/	New		Fair	POOR	
14	Wire Hangers (12ga)	Ш			Ш	
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No		Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			*
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	K-5	
				Additional Comments/Observations
				×
1	$\cap$			

9-15-22 Date:

Manager Signature:

9/22/22 ate:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: LR 0516 Unit Location: Curlew Creek ES Inspection Date: 9/15/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations  $\boxtimes$ 1 (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum 5  $\boxtimes$ Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses 7 X Roof Covering (Note type  $\boxtimes$ 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding 9 Metal Exterior Lighting (note if 10  $\boxtimes$ any) Interior Walls and X 11 Vinyl covered drywall Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria		Condi	ition	Mail	Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	K-5
			Additional Comments/Observations
^			

9-15-22 Date:

Manager Signature:

Date:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: LR 0672 Unit Location: Curlew Creek ES Inspection Date: 9/15/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # Fair New Good Poor Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity X 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding 9 X Metal Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and  $\boxtimes$ 11 Vinyl covered drywall Covering Doors/Windows/ 12  $\boxtimes$ Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	K-5
			Additional Comments/Observations
			Na de la companya de
		7-19-	
	_		±
1	//		

9-/5-27 Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 0764 Unit Location: Curlew Creek (Chi Chi) Inspection Date: 9/15/22

Inspected By: John H. Borycens License Number: BN 7352 Line **Inspection Criteria** Condition # **Inspection Comments** New Good Fair Poor Pier and foundations X (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity 6 X Roof Trusses 7  $\boxtimes$ Roof Covering (Note type  $\times$ 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding X 9 Metal Exterior Lighting (note if 10  $\boxtimes$ any) Interior Walls and 11  $\boxtimes$ Vinyl covered drywall Covering Doors/Windows/ 12  $\times$ Hardware Floors/Carpet/Tile Type 13 X and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting				X	emergency light is not working
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments			
29	Is unit in 100-year flood plain?					
30	Technology Capable					
31	Occupancy Certificate Posted in Unit					
32	Local Agency Reports Posted					
33	Does unit have any known Environmental factors? If yes, Explain.					
34	What grade level or usage is unit?	Other				
			Additional Comments/Observations			
	#20 work order for the emergency light #145348					
1						

 $\frac{9-15-22}{\text{Date:}}$ 

Manager Signature:

19/11/22 Date:

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: BR 0765 Unit Location: Curlew Creek (Chi Chi) Inspection Date: 9/15/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line **Inspection Comments** # New Good Fair Poor Pier and foundations  $\times$ 1 (Show Location on Back) Tie downs and Anchors  $\boxtimes$ 2 (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding  $\times$ 9 Metal Exterior Lighting (note if 10  $\times$ any) Interior Walls and  $\boxtimes$ 11 Vinyl covered drywall Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good		Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No	Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$	
30	Technology Capable	$\boxtimes$		
31	Occupancy Certificate Posted in Unit	$\boxtimes$		
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$	
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
1	1			

<u>9-15-22</u> Date:

Manager Signature:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 0766 Unit Location: Curlew Creek (Chi Chi) Inspection Date: 9/15/22

Inspected By: John H. Borycens License Number: BN 7352 Inspection Criteria Condition Line # **Inspection Comments** Fair New Good Poor Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors 2  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Rubber Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 Metal Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and 11  $\boxtimes$ Vinyl covered drywall Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria		Cond	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No	Inspection Comments
29	Is unit in 100-year flood plain?		$\boxtimes$	
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other		
				Additional Comments/Observations
7	1			

9-15-22 Date:

Manager Signature:

9/27/2Z ate:

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: BR 0767 Unit Location: Curlew Creek (Chi Chi) Inspection Date: 9/15/22

Inspe	ected By: John H. E	Boryce	ens			License Number: BN 7352
Line #	Inspection Criteria	New	Condit Good	tion Fair	Poor	Inspection Comments
1	Pier and foundations (Show Location on Back)		$\boxtimes$			
2	Tie downs and Anchors (Show Location on Back)		$\boxtimes$			
3	Set Backs (Between Units and from property)					
4	Steps and Ramps					Aluminum
5	Means of Egress		$\boxtimes$			
6	Structural Integrity		$\boxtimes$			
7	Roof Trusses		$\boxtimes$			
8	Roof Covering (Note type Shingles, Veral, etc.)		$\boxtimes$			Rubber
9	Exterior Walls/Siding		$\boxtimes$			Metal
10	Exterior Lighting (note if any)		$\boxtimes$			
11	Interior Walls and Covering		$\boxtimes$			Vinyl covered drywall
12	Doors/Windows/ Hardware					
13	Floors/Carpet/Tile Type and Condition					

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					•
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	Inspection Comments
29	Is unit in 100-year flood plain?		
30	Technology Capable		
31	Occupancy Certificate Posted in Unit		
32	Local Agency Reports Posted		
33	Does unit have any known Environmental factors? If yes, Explain.		
34	What grade level or usage is unit?	Other	
			Additional Comments/Observations
		9.	
			·
	/	¥	

9-15-2Z Date:

Manager Signature:

<u>9/22/22</u> Date: