## **Pinellas County Schools**

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: ER 9015 Unit Location: Dunedin ES. Inspection Date: 10/13/22 Inspected By: John H. Borycens License Number: BN 7352 Line **Inspection Criteria** Condition # **Inspection Comments** New Good Fair Poor Pier and foundations  $\times$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum 5  $\boxtimes$ Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ Modified Shingles, Veral, etc.) Exterior Walls/Siding X 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and 11 X Paneling Covering Doors/Windows/ 12 X Hardware Floors/Carpet/Tile Type  $\boxtimes$ and Condition

Line	Inspection Criteria		Condi	ition		Inspection Comments
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Westing House panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)	$\boxtimes$				
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom

Line #	Inspection Criteria	Yes	ndition No		Inspection Comments
29	Is unit in 100-year flood plain?				
30	Technology Capable	$\boxtimes$			
31	Occupancy Certificate Posted in Unit	$\boxtimes$			
32	Local Agency Reports Posted	$\boxtimes$			
33	Does unit have any known Environmental factors? If yes, Explain.		$\boxtimes$		
34	What grade level or usage is unit?	Other		K-5	
		1 - 10 m (1994)			Additional Comments/Observations
	.=				
	,				
7	1			7	

Inspector Signature:

<u>10 -13-22</u> Date:

Manager Signature:

10/24/22 ate:

## **Pinellas County Schools**

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

**Unit Number: ER 9017** Unit Location: Dunedin ES. Inspection Date: 10/13/22 Inspected By: John H. Borycens License Number: BN 7352 Line Inspection Criteria Condition # **Inspection Comments** Fair Poor New Good Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ 3 and from property)  $\boxtimes$ Steps and Ramps 4 Aluminum  $\boxtimes$ 5 Means of Egress Structural Integrity  $\boxtimes$ 6 **Roof Trusses**  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ 8 Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and  $\boxtimes$ Paneling Covering Doors/Windows/  $\boxtimes$ 12 Hardware Floors/Carpet/Tile Type 13  $\boxtimes$ and Condition

Line #	Inspection Criteria	Condition  New Good Fair Poor			Poor	Inspection Comments
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)		$\boxtimes$			
15	Visual Aids (Chalk/Marker Boards and Tack Boards)	<u></u>	$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)		$\boxtimes$			Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures		$\boxtimes$			This unit has a restroom

Line #	Inspection Criteria	Condition Yes No	) - Programme of the control of the	Inspection Comments
29	Is unit in 100-year flood plain?			
30	Technology Capable			
31	Occupancy Certificate Posted in Unit			
32	Local Agency Reports Posted			
33	Does unit have any known Environmental factors? If yes, Explain.			
34	What grade level or usage is unit?	Other	K-5	
				Additional Comments/Observations
			44	
				9
1				

Inspector Signature:

<u>// /3 - /2 / Date:</u>

Manager Signature:

19/24/22

## **Pinellas County Schools**

Relocatable Classroom Inspection Certificate
(Yearly Inspection Report)

Unit Number: ER 9210 Unit Location: Dunedin ES. Inspection Date: 10/13/22

Inspected By: John H. Borycens License Number: BN 7352 Line **Inspection Criteria** Condition **Inspection Comments** # Fair Poor New Good Pier and foundations  $\boxtimes$ (Show Location on Back) Tie downs and Anchors  $\boxtimes$ (Show Location on Back) Set Backs (Between Units  $\boxtimes$ and from property)  $\boxtimes$ 4 Steps and Ramps Aluminum X 5 Means of Egress Structural Integrity  $\boxtimes$ 6 Roof Trusses  $\boxtimes$ Roof Covering (Note type  $\boxtimes$ Modified Shingles, Veral, etc.) Exterior Walls/Siding  $\boxtimes$ 9 T 111 Exterior Lighting (note if  $\boxtimes$ 10 any) Interior Walls and X Paneling Covering Doors/Windows/  $\boxtimes$ Hardware Floors/Carpet/Tile Type  $\boxtimes$ 13 and Condition

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)		$\boxtimes$			
16	Weatherproofing (List Deficiencies)		$\boxtimes$			
17	HVAC		$\boxtimes$			Bard
18	Electrical Receptacles		$\boxtimes$			
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting		$\boxtimes$			
21	Interior Light Fixtures (tied to structure)		$\boxtimes$			
22	Fire Alarm (Strobes, Horn, Pull Stations)		$\boxtimes$			
23	Heat Detector/Smoke Detector in Storage Spaces		$\boxtimes$			
24	Heat Detector/Smoke Detector in Classroom		$\boxtimes$			
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system		$\boxtimes$			
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line #	Inspection Criteria	Z Title lazer	ndition		Inspection Comments
		Yes	No		
29	Is unit in 100-year flood plain?				
30	Technology Capable				
31	Occupancy Certificate Posted in Unit				
32	Local Agency Reports Posted				
33	Does unit have any known Environmental factors? If yes, Explain.				
34	What grade level or usage is unit?	Other		K-5	
					Additional Comments/Observations
amand C					
7					

Inspector Signature:

10 - 13 - 22 Date:

Manager Signature:

70/24/22 Date: