Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: BR 0764 Unit Location: Curlew Creek (Chi Chi) Inspection Date: 9/15/22

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					emergency light is not working
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line	Inspection Criteria	Condition			Inspection Comments					
#		Yes	No							
29	Is unit in 100-year flood plain?									
30	Technology Capable									
31	Occupancy Certificate Posted in Unit									
32	Local Agency Reports Posted									
33	Does unit have any known Environmental factors? If yes, Explain.									
34	What grade level or usage is unit?	Other								
						Additional Comments/Observations				
	#20 work order for the emergency light #145348									
nspect	pector Signature: Date: Manager Signature: Date:									

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: BR 0765 Unit Location: Curlew Creek (Chi Chi) Inspection Date: 9/15/22

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line	Inspection Criteria	Condition		Inspection Comments			
#		Yes	No				
29	Is unit in 100-year flood plain?						
30	Technology Capable						
31	Occupancy Certificate Posted in Unit						
32	Local Agency Reports Posted						
33	Does unit have any known Environmental factors? If yes, Explain.						
34	What grade level or usage is unit?	Other					
					Additional Comments/Observations		
nspector Signature:			ate:		Manager Signature: Date:		

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: BR 0766 Unit Location: Curlew Creek (Chi Chi) Inspection Date: 9/15/22

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)					in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line	Inspection Criteria	Condition		Inspection Comments			
#		Yes	No				
29	Is unit in 100-year flood plain?						
30	Technology Capable						
31	Occupancy Certificate Posted in Unit						
32	Local Agency Reports Posted						
33	Does unit have any known Environmental factors? If yes, Explain.						
34	What grade level or usage is unit?	Other					
					Additional Comments/Observations		
nspector Signature:			ate:		Manager Signature: Date:		

Relocatable Classroom Inspection Certificate (Yearly Inspection Report)

Unit Number: BR 0767 Unit Location: Curlew Creek (Chi Chi) Inspection Date: 9/15/22

Line	Inspection Criteria	Condition			Inspection Comments	
#		New	Good	Fair	Poor	
14	Ceilings/Tiles/Grid/ Wire Hangers (12ga)					
15	Visual Aids (Chalk/Marker Boards and Tack Boards)					
16	Weatherproofing (List Deficiencies)					
17	HVAC					Bard
18	Electrical Receptacles					
19	Distribution Panel (labeled Correctly)					Square D panel
20	Emergency Lighting					
21	Interior Light Fixtures (tied to structure)					
22	Fire Alarm (Strobes, Horn, Pull Stations)					
23	Heat Detector/Smoke Detector in Storage Spaces					
24	Heat Detector/Smoke Detector in Classroom					
25	Heat Detector/Smoke Detector in Unsupervised Spaces (For VB Only)		$\boxtimes$			in attic
26	Intercom system					
27	Fire Extinguisher (Tagged and Current)					
28	Plumbing/Fixtures					This unit has a restroom

Line	Inspection Criteria	Condition		Inspection Comments			
#		Yes	No				
29	Is unit in 100-year flood plain?						
30	Technology Capable						
31	Occupancy Certificate Posted in Unit						
32	Local Agency Reports Posted						
33	Does unit have any known Environmental factors? If yes, Explain.						
34	What grade level or usage is unit?	Other					
					Additional Comments/Observations		
nspector Signature:			ate:		Manager Signature: Date:		